DEKRA

DEKRA Automotive Solutions


Appraisal Report

Vehicle details

VIN	VR3USHNS0 RJ713488	Registration date	25/06/2024	Exterior Color	Inconnu
Brand	PEUGEOT	Licence Plate	TF-MR 999	Odometer	55 207 km
Model	2008 PureTech 130 EAT8 GT				

Inspection Details

Arrival Date	18/08/2026	Inspection ID	7121382	Inspection date	21/08/2026
Assign Date	18/08/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys AKB Zörbig



Generic equipment

Removable element

Toolkit	✓
Rear parcel shelf	✓
Floor mat B	✓
Floor mat F	✓
Spare wheel kit	✗


Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Key	✓
Remote key	✓
Service	✓

Tyres

Goodyear 215/60/17 H All seasons 5.0 mm

Goodyear 215/60/17 H All seasons 5.0 mm





Goodyear 215/60/17 H All seasons 6.0 mm

Goodyear 215/60/17 H All seasons 6.0 mm

Exception / Damage

1



Part	Engine soundproofing	Repair Time	0.10	Part Cost	74.82€
Position	-	Repair Cost	14.00€	Gross Cost	88.82€
Damages	Defective	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	- 13.32
Repair mode	Replace	Flat Rate	-	**Net Cost**	**75.50€**

2



Part	Spare wheel kit	Repair Time	-	Part Cost	51.79€
Position	-	Repair Cost	-	Gross Cost	51.79€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**51.79€**

3



Part	Bonnet	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Repaired	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

4

Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

5

Part	Bonnet	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

6

Part	Windscreen	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

7

Part	Bumper	Repair Time	-	Part Cost	-
Position	Back	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

8

Part	Caisse de chargement complète	Repair Time	-	Part Cost	-
		Repair Cost	-	Gross Cost	-
Position	-	Paint Time	-	Depreciation %	15.00%
Damages	Scratched	Paint cost	-	Depreciation	-
Severity	-	Flat Rate	-	**Net Cost**	**-**
Repair mode	For info				

Summary Inspection

Gross Price	140.61€	Depreciation	-13.32€	Net Price	127.29€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	0.10	14.00€	15.00 %	-2.10€	11.90€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	126.61€	8.86 %	-11.22€	115.39€
Flat Rate	-51.79€	-	-	-51.79€