TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48496793
Order No. / Reference: 27253144
Inspection date: 4 Nov 2026

Manufacturer: Opel	Model: Corsa 1.2 Direct Injection Turbo Start/Stop Elegance
VIN: VXKUPHNEKN4169526	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Corsa 1.2 Direct Injection Turbo Start/Stop Elegance	
Vehicle Identification number	VXKUPHNEKN4169526
Mileage (Read)	75,742 km
First registration	21 Apr 2022
Number of holders	1
Fuel type	Petrol
Engine displacement / Cylinder	1,199 ccm / 3
Power	74 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Car hatchback
Colour / colour code	Jade Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Blue

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	13,400 km
Last service on / at	12/2025 at 69,151 km		
Key is / should be	1 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ656020
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / ABU 00286		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,620 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/45 R17 88V	All-season tyres on Light alloy	Continental	5mm / 5mm
2)	205/45 R17 88V	All-season tyres on Light alloy	Continental	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag: Front airbags, driver and front passenger
- Airbag: Side airbag for driver and front passenger side
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- On-board computer
- Tachometer
- Electronic Stability Program Plus (ESP Plus)
- Electric windows front and rear
- Pedestrian protection
- Intelligent speed control and limiter
- Back window, heater
- Child safety lock in the rear doors, manual
- LED daytime running lights
- Steering wheel: Leather steering wheel, flattened at the bottom
- Center armrest with storage compartment in front
- OpelConnect iVm. Multimedia Navi Pro
- Pollen filter
- Radio: Multimedia radio with 7" touchscreen color display
- Seat belts: Three-point seat belts in all seats
- Seats: Comfort passenger seat
- Seats: Rear seat backrest split 60:40, foldable
- Start/Stop System
- Traction Control (TC) Plus
- Traffic sign recognition
- Pre-wiring for child seat mounting system "ISOFIX"
- Central locking with remote control
- Adaptive brake light
- Airbag: Front and rear head airbags
- Anti-lock braking system (ABS)
- Exterior mirror housings in black
- Hill Start Assist
- third brake light
- Electronic brake force distribution (EBD)
- Driver information display 7", color
- Front collision warning system with automatic emergency braking and pedestrian detection
- Transmission: 6-speed manual transmission
- rear window wiper
- Headrests (5)
- LED headlights
- Steering column, height and reach adjustable
- Makeup mirror
- Fatigue detection
- Otto particulate filter
- Upholstery: Fabric/premium leatherette combination
- Power steering
- Visibility equipment
- Seats: Comfort driver's seat
- Lane Keeping Assist
- 12V power outlet in the center console, front
- Ambient lighting
- Pre-installation for ISOFIX child seat mounting system
- Heat-insulating glazing, tinted

Extra equipment

- 2 folding ignition keys with remote control
- Automatic climate control (recirculation mode, manual - automatic air distribution - sun position sensor - activated carbon filter - rear footwell heating)
- Park & Go Plus (180-degree panoramic reversing camera - Park Pilot, front and rear parking aid with audiovisual warning - blind spot warning and side protection - electrically folding exterior mirrors)
- Heated seats for driver and front passenger (multi-stage adjustable)
- Heated leather steering wheel
- Paint finish: Solid special color Jade White
- Package: Style (solid paint finish) (roof in contrasting black - Solar Protect heat-insulating glazing, heavily tinted, in the rear)
- Electric parking brake
- Wheels: 7 J x 17 alloy wheels in 5-twin-spoke design in bi-color black (205/45 R 17 - low rolling resistance tires)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Floor mats - Broken / torn - Replace
2	Door - front right side	Door handle - outside - Scratch(es) - Smart repair
3	Equipment	Tirefit filler - Expired - Replace
4	Trim / covers	Door trim - rear right side - Scratch(es) - Loss in value
5	Trim / covers	Door trim - rear left side - Scratch(es) - Loss in value
6	Side panel - rear left side	Side panel - dent(s) - Smooth repair work

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Side panel - Abrasion - No deduction
2	Boot lid / rear door	Boot lid - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Vehicle key

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 14 Sept 2023	1.692,09 €

Repainting

No.	Repainting
1	Mudguard - right side

Paint coat thickness measurement

Mudguard - right side	200 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents




Figure 16: Documents



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Damage 1: Trim / covers: Floor mats - Broken / torn - Replace



Damage 1: Trim / covers: Floor mats - Broken / torn - Replace



Damage 2: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 2: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 2: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 3: Equipment: Tirefit filler - Expired - Replace



Damage 4: Trim / covers: Door trim - rear right side - Scratch(es) - Loss in value



Damage 4: Trim / covers: Door trim - rear right side - Scratch(es) - Loss in value



Damage 4: Trim / covers: Door trim - rear right side - Scratch(es) - Loss in value



Damage 5: Trim / covers: Door trim - rear left side - Scratch(es) - Loss in value




Damage 5: Trim / covers: Door trim - rear left side - Scratch(es) - Loss in value




Damage 6: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 6: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 6: Side panel - rear left side: Side panel - dent(s) - Smooth repair work




Damage 6: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Wear and tear 1: Side panel - rear right side: Side panel - Abrasion - No deduction



Wear and tear 1: Side panel - rear right side: Side panel - Abrasion - No deduction




Wear and tear 2: Boot lid / rear door: Boot lid - dent(s) - No deduction



Wear and tear 2: Boot lid / rear door: Boot lid - dent(s) - No deduction



Wear and tear 2: Boot lid / rear door: Boot lid - dent(s) - No deduction



Missing part 1: Equipment: Vehicle key - Missing - Replace



Repainting 1: Mudguard - right side



Repainting 1: Mudguard - right side