MACADAM








Mercedes Citan (Segm. B1): 2DLK038

Vinnumber:	**W1VTAACZ8PU335724**	Versionname:	**Citan 108 Base L1 1.5CDi 75pk/cv**
First Registrationdate:	**17/04/2023**	Fiscalpower:	
Expertise Mileage:	**64206**	Power Kw:	**55**
Bodytype:		Type of rims (mounted)	**Steel**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**ass A plus 675 d**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Light Commercial Vehicle**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**No Tow bar**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/60/16/96 H**			
	Fr.L.	**Vredestein: 5 mm**	Fr.R.	**Vredestein: 5 mm**
	Re.L.	**Michelin: 5 mm**	Re.R.	**Michelin: 5 mm**


Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**205/60 R 16 96 H**
Tyre size FR	**205/60 R 16 96 H**
Tyre size RL	**205/60 R 16 96 H**
Tyre size RR	**205/60 R 16 96 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**2480**
Tyre make FR	**2480**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Windscreen, Stone chip(s), Windscreen repair






Bumper R, Scratch(es), Acceptable




Outer door handle FR, Scratch(es), Acceptable





Mirror side repeater R, Scratch(es), Replace





Bodywork, Not original part, Check





Onderhoudshistorie van: W1VTAACZ8PU335724

ALPHABET

Kenteken	2DLK038
Merk Model	Mercedes Citan 108 Base L1 1.5CDi 75pk/cv
Brandstofsoort	Diesel
Datum deel1	4/17/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
9/1/26	63,470	brandstof hoofdfilter	Vervangen
9/1/26	63,470	luchtfilter	Vervangen
9/1/26	63,470	oliezeef	Vervangen
9/1/26	63,470	onderhoud 12 maand	Uitvoeren
9/1/26	63,470	ruitenwisserrubber vooraan	Vervangen
9/1/26	63,470	ruitenwisservloeistof	Vervangen
9/1/26	63,470	stoffilter (motor compartiment)	Vervangen
8/26/26	63,282	mercedes assyst b	Uitvoeren
8/26/26	63,282	ruitenwisserrubber vooraan	Vervangen
10/20/25	31,209	accu	Vervangen
10/20/25	31,209	klein materiaal	
4/3/25	9,500	klein materiaal	
4/3/25	9,500	mercedes assyst a	Uitvoeren
4/3/25	9,500	remvloeistof	Vervangen
4/3/25	9,500	ruitenwisserrubber vooraan	Vervangen