TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig


Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48460063
Order No. / Reference: 27179472
Inspection date: 3 Nov 2026

Manufacturer: Audi	Model: A6 Avant 40 TDI S tronic
VIN: WAUZZZF29RN035868	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A6 Avant 40 TDI S tronic	
Vehicle Identification number	WAUZZZF29RN035868
Mileage (Read)	136,984 km
First registration	26 Apr 2024
Number of holders	1
Next periodical technical inspection	04/2027
(Report not on hand)	
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,968 ccm / 4
Power	150 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Firmamentblau-metallic (X5B)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	13,100 km
Last service on / at	06/2026 at 122,728 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HA932834
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0588 / BSZ 02677		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,330 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R18 102Y	Summer tyres on Light alloy	Pirelli	3mm / 3mm
2)	225/55 R18 102Y	Summer tyres on Light alloy	Pirelli	3mm / 3mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- AdBlue tank (12 liters)
- Airbag: Front side airbags and head airbag system
- Audi connect navigation & infotainment
- Audi drive select
- Audi pre sense front
- Electrically adjustable and heated exterior mirrors
- Control buttons, matte black
- third brake light
- Decorative inlays, fine lacquer, graphite grey
- Parking aid plus with surround view
- Door sills with aluminum inlay front and rear
- key fob
- Cruise control system with speed limiter
- Heated rear window
- Interior lighting
- ISOFIX child seat attachment and Top Tether for the outer rear seats
- Headrests (4)
- LED headlights
- Manual steering wheel adjustment
- MMI navigation with MMI touch response
- Progressive steering
- Wheel: Tire pressure monitoring system
- Radio: MMI Radio plus with MMI touch response
- Rail system with fixing set
- Seats: Standard front seats
- Sun visor on driver and passenger side
- Start-stop system
- Glazing: Windscreen in heat-insulating glazing
- Glazing: Rear window, rear door and side windows in clear glass
- Thermal insulation glazing on the sides and rear
- Airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Audi connect emergency call & service m.connect remote & control
- Audi virtual cockpit plus
- Exterior mirror housings in body color
- Vehicle tool kit
- Fabric headliner
- Diesel particulate filter (DPF) with nitrogen oxide catalyst and AdBlue tank
- Electronic Stability Control (ESC)
- Luggage compartment lid, electrically opening and closing
- Transmission: S tronic 7-speed
- rear window wiper
- Interior mirror dimming
- 2-zone automatic climate control
- Comfort center armrest in front
- Paint finish: Solid
- Steering wheel: Leather steering wheel with multifunction controls
- Non-smoking version
- Wheel: Alloy wheels, 10-spoke design
- Wheel: Tire repair kit
- Radio accessories: 8 speakers (passive) front and rear
- Fabric seat covers with effect
- Seats: Split-folding rear seat backrest Avant
- Lane Departure Warning
- First aid kit including warning triangle and high-visibility vests
- Camera-based traffic sign recognition
- Electronic immobilizer
- Central locking with remote control

Extra equipment

- Electrically adjustable, heated and folding exterior mirrors, automatically dimming on both sides (including curb view function for the passenger-side exterior mirror with integrated LED turn signal, including heated windshield washer nozzles, aspherical mirror glass. The curb view function tilts the passenger-side exterior mirror downwards when reverse gear is engaged, providing the driver with a better view of the curb.)
- Retrofitting a towbar
- Assistance Package Tour (Adaptive Driving Assistant, Adaptive Speed Assistant provides support within system limits for acceleration, braking, and maintaining speed and distance with Lane Keeping Assist - Efficiency Assistant - Turning Assistant, monitors the oncoming lane using data from the radar sensor and front camera as soon as the turn signal is activated - Evasive Steering Assist, helps the driver steer the vehicle around an obstacle in a critical situation - Emergency Assist)
- Wheel: Light alloy wheels 10-twin-spoke segment design, graphite grey (8 J x 18 with tires 225/55 R 18)
- Radio accessories: Bang & Olufsen Premium Sound System with 3D sound (sound reproduction via 16 speakers including 3D sound speakers, center speaker and subwoofer, 15-channel amplifier with a total output of 705 watts; spatial sound reproduction thanks to the 3D sound feature for the front seats. This is created by additional speakers in the A-pillars, the midrange speakers and Fraunhofer Symphoria technology. The 3D sound can be played back with all sources.)
- Phone: Preparation for smartphone interface
- High beam assist (within the system's limits, it automatically detects oncoming headlights, taillights of other road users, and built-up areas. Depending on the traffic situation, the high beam is automatically switched on or off.)
- Paint finish: Metallic
- Steering wheel: Double-spoke leather steering wheel with multifunction controls, paddle shifters, and steering wheel heating (steering wheel design with aluminum look. The leather on the steering wheel and gear selector knob is color-matched to the selected color of the instrument panel top. The steering wheel's height and reach are manually adjustable; with 12 multifunction buttons for convenient operation of the infotainment system. Paddle shifters allow manual gear changes. The steering wheel rim is also heated.)
- Business Package (Assistance Package Tour (adaptive speed assist, efficiency assist, turn assist, evasive steering assist, emergency assist) - 4-zone automatic climate control - heated front seats - Audi phone box - automatically dimming interior mirror - automatically dimming exterior mirrors - adaptive windscreen wipers with integrated washer nozzles - high-beam assist)
- Seats: 4-way lumbar support (electrically adjustable, horizontally and vertically)
- Front seat heating (heats seat and backrest center panels; with leather upholstery, sport seats and sport seats plus also seat side bolsters - individually adjustable in multiple stages for driver and front passenger side via the climate control unit)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
2	Rear bumper	Spoiler - Scratch(es) - Loss in value
3	Headlight	Headlight - left side (beschlagen, reinigen, Mehrkosten möglich) - Soiled - Perform diagnosis
4	Headlight	Headlight - right side (beschlagen, reinigen, Mehrkosten möglich) - Soiled - Perform diagnosis
5	Roof	Roof - dent(s) - Smooth repair work
6	Side panel - rear left side	Side panel - Dent / paintcoat damage - Smart repair
7	Rear bumper	Rear bumper - Scratched - Paint
8	Front bumper	Front bumper - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	Body	Body - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 21 Jun 2024	2.480,04 €

Repainting

No.	Repainting
1	Door - front left side, Professionally carried out

Paint coat thickness measurement

Door - front left side	179 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)




Figure 3: Diagonal rear (left)




Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents



Figure 13: Documents




Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Damage 1: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 1: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value




Damage 2: Rear bumper: Spoiler - Scratch(es) - Loss in value




Damage 2: Rear bumper: Spoiler - Scratch(es) - Loss in value




Damage 2: Rear bumper: Spoiler - Scratch(es) - Loss in value




Damage 3: Headlight: Headlight - left side (beschlagen, reinigen, Mehrkosten möglich) - Soiled - Perform diagnosis




Damage 3: Headlight: Headlight - left side (beschlagen, reinigen, Mehrkosten möglich) - Soiled - Perform diagnosis




Damage 3: Headlight: Headlight - left side (beschlagen, reinigen, Mehrkosten möglich) - Soiled - Perform diagnosis




Damage 4: Headlight: Headlight - right side (beschlagen, reinigen, Mehrkosten möglich) - Soiled - Perform diagnosis



Damage 4: Headlight: Headlight - right side (beschlagen, reinigen, Mehrkosten möglich) - Soiled - Perform diagnosis




Damage 5: Roof: Roof - dent(s) - Smooth repair work




Damage 5: Roof: Roof - dent(s) - Smooth repair work




Damage 5: Roof: Roof - dent(s) - Smooth repair work




Damage 5: Roof: Roof - dent(s) - Smooth repair work



Damage 5: Roof: Roof - dent(s) - Smooth repair work




Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair




Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 7: Rear bumper: Rear bumper - Scratched - Paint




Damage 7: Rear bumper: Rear bumper - Scratched - Paint



Damage 7: Rear bumper: Rear bumper - Scratched - Paint



Damage 7: Rear bumper: Rear bumper - Scratched - Paint



Damage 7: Rear bumper: Rear bumper - Scratched - Paint



Damage 8: Front bumper: Front bumper - Scratched - Paint




Damage 8: Front bumper: Front bumper - Scratched - Paint



Damage 8: Front bumper: Front bumper - Scratched - Paint



Damage 8: Front bumper: Front bumper - Scratched - Paint



Damage 8: Front bumper: Front bumper - Scratched - Paint



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Repainting 1: Door - front left side



Repainting 1: Door - front left side