Audi

VIN: WAUZZZGY0PA114112

Estimated repair cost

1,725.00 EUR
TOTAL



Description

Registration number 2FEA545	**Registration date** -	**Odometer** -
Color -	**Year** -	**Upholstery** -
Number of doors -	**Number of seats** -	**Generation** -

Statement details

Inspection loc
PARC LIZY

Control


Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction	net cost
001	Registration certficate2 / -	Missing	Replace	0.00 EUR
	Bodywork time: - / Paint time: - / Part Price: - / Bodywork cost: - / Paint cost: - / MaterialCost: - / Lumpsum: -			
002	Registration certficate / -	Missing	Replace	250.00 EUR

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

		Bodywork time -	Paint time -	Part Price -	Lumpsum **250.00 EUR**
		Bodywork cost -	Paint cost -	MaterialCost -	
003	Spare Key / -		Missing	Replace	350.00 EUR
		Bodywork time -	Paint time -	Part Price -	Lumpsum **350.00 EUR**
		Bodywork cost -	Paint cost -	MaterialCost -	
004	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 16 " / Surface : Painted		Scratched	Repair	165.00 EUR
		Bodywork time -	Paint time -	Part Price -	Lumpsum **165.00 EUR**
		Bodywork cost -	Paint cost -	MaterialCost -	
005	Bumper towing hook cover plate / Front Right		Scratched	Painting	25.50 EUR
		Bodywork time -	Paint time **0.30 h**	Part Price -	Lumpsum -
		Bodywork cost -	Paint cost **25.50 EUR**	MaterialCost -	
006	Bumper / Front		Dent	Repair	194.00 EUR
		Bodywork time **1.00 h**	Paint time **1.40 h**	Part Price -	Lumpsum -
		Bodywork cost **75.00 EUR**	Paint cost **119.00 EUR**	MaterialCost -	
007	Rim / Front Left Material : Aluminium alloy / Rim/Tyre diameter : 16 "		Scratched	Acceptable	-
		Bodywork time -	Paint time -	Part Price -	Lumpsum -
		Bodywork cost -	Paint cost -	MaterialCost -	
008	Interior complete / -		Stained	Cleaning	75.00 EUR

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
1.00 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
75.00 EUR	-	-	

009	Door / Back Left	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

010	Wing / Back Left	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

011	Bumper / Back	Dent	Repair	185.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
1.00 h	1.30 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
75.00 EUR	110.50 EUR	-	

012	Wing / Back Right	Dent	Repair	320.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
2.00 h	2.00 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
150.00 EUR	170.00 EUR	-	

013	Door / Back Right	Dent	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

014	Door sill / Back Right	Scratched	Acceptable	-

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

015	Rear-view mirror / Right	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

016	Wing / Front Right	Paint etching	Polishing	37.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	-	-	

017	Roof post A/B/C / Right	Paint etching	Polishing	37.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	-	-	

018	Door sill / Back Left	Scratched	Painting	85.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	**1.00 h**	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	**85.00 EUR**	-	

Loose Items

- [x] Tyre repair kit complete
- [x] Compressor tyre repair kit
- [x] Document holder
- [ ] Registration certificate owner
- [x] Rear parcel shelf
- [ ] Registration certificate
- [ ] Spare Key

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	UNIROYAL	205/55/16 100 H All-season	7 mm
Front Right	UNIROYAL	205/55/16 100 H All-season	7 mm
Back Left	UNIROYAL	205/55/16 100 H All-season	7 mm
Back Right	UNIROYAL	205/55/16 100 H All-season	7 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right



Odometer



Navigation


Spare Tyre



Vin

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Bumper towing hook cover plate / Front Right / Scratched



Bumper towing hook cover plate / Front Right / Scratched



Bumper / Front / Dent



Bumper / Front / Dent



Bumper / Front / Dent



Bumper / Front / Dent



Bumper / Front / Dent



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Interior complete / - / Stained



Interior complete / - / Stained

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained



Door / Back Left / Scratched



Wing / Back Left / Scratched



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Wing / Back Right / Dent



Wing / Back Right / Dent



Wing / Back Right / Dent


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Door / Back Right / Dent



Door sill / Back Right / Scratched



Rear-view mirror / Right / Scratched



Wing / Front Right / Paint etching



Wing / Front Right / Paint etching



Roof post A/B/C / Right / Paint etching



Roof post A/B/C / Right / Paint etching



Door sill / Back Left / Scratched



Door sill / Back Left / Scratched



Door sill / Back Left / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.