TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48469574
Order No. / Reference: 27154322-1
Inspection date: 23 Oct 2026

Manufacturer: Ford	Model: Puma 1.0 EcoBoost Hybrid Aut. TITANIUM
VIN: WF02XXERK2PL28635	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Puma 1.0 EcoBoost Hybrid Aut. TITANIUM	
Vehicle Identification number	WF02XXERK2PL28635
Mileage (Read)	126,709 km
First registration	5 Oct 2023
Number of holders	1
Next periodical technical inspection	10/2026
(Report not on hand)	
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	999 ccm / 3
Power	92 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Multipurpose vehicle
Colour / colour code	Agate Black Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	42 %
Last service on / at	08/2025 at 123,366 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT916964
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BSO 00103		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,760 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 94H	Winter tyres on Light alloy	Nokian	7mm / 7mm
2)	215/55 R17 94H	Winter tyres on Light alloy	Nokian	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 94V	Summer tyres on Steel	Continental	4mm / 4mm
2)	215/55 R17 98W	Summer tyres on Steel	Goodyear	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Ambient lighting in the front, including front door storage compartment, footwell and cup holder lighting with LED technology
- Passenger airbag deactivation
- Tires: 7 J x 17 design wheels (4) in 5x2-spoke design, black-silver with 215/55 R 17 tires
- Hill start assist
- third brake light
- Tachometer
- Driver information system with on-board computer
- Lane keeping assist including lane keeping assist
- Electric front and rear windows with one-touch down function including all windows closed function
- High Beam Assist
- Ford EcoCoach shows the efficiency of current driving behavior.
- Ford MegaBox
- FordPass Connect including eCall, Live Traffic Information
- Luggage compartment lighting
- Transmission: 7-speed automatic dual-clutch transmission
- Rear window wiper/washer system
- Intelligent Protection System (IPS) - Front airbags for driver and front passenger - Front and rear head/shoulder airbags - Side airbags for driver and front passenger - Seat belt tensioners and force limiters for front and outer rear seats - Seat belt warning system for front and second-row seats
- LED fog lights including static cornering lights
- Steering column, adjustable in height and reach
- Front center console with integrated armrest - 2 cup holders - 12-volt socket
- Ford navigation system including Ford SYNC 3 with AppLink and 8" touchscreen - Digital radio reception DAB/DAB+ (Digital Audio Broadcasting) - 6 speakers - Android Auto and Apple CarPlay - Bluetooth hands-free system and audio streaming - Steering wheel controls - Radio player - USB port - Voice control for audio and telephone - Road map for Europe - Ford navigation system includes advanced voice control and voice output, detailed visualization (3D display), One Box Search
- Headlights with LED daytime running lights and LED low beam headlights
- Electromechanical, speed-dependent power steering (EPAS - Electric Power Assisted Steering)
- Seats: Driver's seat height-adjustable with lumbar support
- Seats: Rear seat backrest, foldable, 60:40 split
- Seats: Front sports seats with integrated headrests
- Carpet floor mats, front, velour
- Traffic sign recognition system
- Immobiliser
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Electrically adjustable, heated and folding exterior mirrors - painted in body color - with integrated turn signals and ambient lighting
- Tires: Tire repair kit - maximum speed 80 km/h when used
- Brake Assist (EBA)
- Fabric headliner
- Electronic Stability Program (ESP) with Traction Control System (TCS)
- Wrong-way driver warning function: Traffic signs, e.g. no-overtaking zones or speed limits, are detected via the front camera and displayed on the on-board computer.
- Ford Easy Fuel - Ford Easy Fuel convenience refueling system (Eliminates the need for a separate internal fuel filler cap and prevents misfueling by detecting the size difference between petrol and diesel nozzles. The filler neck only opens when the correct fuel is used.)
- Cruise control
- Grab handles for driver and passenger side
- Heated rear window
- Intelligent speed limiter with speed limit display
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- air conditioning, manual
- Rear headrests (3) height adjustable
- Front headrests are height-adjustable
- LED taillights
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- MyKey key system: individually programmable second key
- Fatigue warning
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Otto particulate filter
- Rear parking pilot system
- Upholstery: Cloth
- Post-Collision Assist
- Pre-Collision Assist including Forward Alert (FA) with pedestrian and bicycle detection
- Tire Pressure Monitoring System (TPMS)
- Headlight assistant with day/night sensor
- Selective driving mode switch - settings "Normal", "Eco", "Sport", "Slippery" and "unpaved roads" - Depending on the selected mode, various factors such as the steering, the resistance of the accelerator pedal and the iACC basic settings are affected.
- Start-stop system
- Variable radiator air intake
- Lashing eyes in the luggage compartment
- Central locking with remote control

Extra equipment

- Paint finish: Agate Black Metallic
- Package: Driver Assistance Package II (Automatic) - Active Parking Assist with parallel and perpendicular parking function - Evasive Steering Assist - Distance display and warning - Intelligent adaptive cruise control with traffic sign recognition system - Traffic Jam Assist with Stop&Go function - Front parking pilot system - Pre-Collision Assist including forward collision warning system with pedestrian and cyclist detection - Rearview camera with "Split View" technology - Blind Spot Assist including Cross Traffic Alert with emergency braking function when reversing out of parking spaces and trailer detection.

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Body	C-pillar - right side - Dent / paintcoat damage - Smart repair
2	Boot lid / rear door	Boot lid - Scratch(es) - Smart repair
3	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
4	Rear bumper	Rear bumper - Scratch(es) - Smart repair
5	Door - rear left side	Door (teilweise) - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	Door - front left side	Door edge - Scratch(es) - Cover / polish

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side right, Provided by user / customer, from 13 Dec 2024	9.173,55 €

Paint coat thickness measurement

Mudguard - right side	252 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Damage 1: Body: C-pillar - right side - Dent / paintcoat damage - Smart repair




Damage 1: Body: C-pillar - right side - Dent / paintcoat damage - Smart repair




Damage 2: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 5: Door - rear left side: Door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 5: Door - rear left side: Door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 5: Door - rear left side: Door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 5: Door - rear left side: Door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 5: Door - rear left side: Door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 5: Door - rear left side: Door (teilweise) - Dent / paintcoat damage - Repair and paint



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 4: Door - front left side: Door edge - Scratch(es) - Cover / polish



Wear and tear 4: Door - front left side: Door edge - Scratch(es) - Cover / polish



Mudguard - right side: 252 µm



Mudguard - right side: 252 µm