TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48459458
Order No. / Reference: 27112788
Inspection date: 3 Nov 2026

Manufacturer: Mercedes-Benz	Model: B 220 d 8G-DCT Progressive Line Advanced Plus
VIN: W1K4F1EB5PJ511729	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz B 220 d 8G-DCT Progressive Line Advanced Plus	
Vehicle Identification number	W1K4F1EB5PJ511729
Mileage (Read)	47,104 km
First registration	6 Apr 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	04/2028
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	140 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	POLARWEISS - UNILACK
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	283 Tag(e)
Last service on / at	07/2026 at 45,000 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS707688
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	2222 / AHH 00041		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,120 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91W	Summer tyres on Light alloy	Goodyear	3mm / 3mm
2)	205/55 R17 91W	Summer tyres on Light alloy	Goodyear	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 95V	Winter tyres on Light alloy	Fulda	5mm / 5mm
2)	205/55 R17 95V	Winter tyres on Light alloy	Fulda	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in center console with roller blind
- Airbag for driver and front passenger
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Foldable armrest in the center console for driver and front passenger
- Outdoor temperature display
- Diesel particulate filter
- EASY-PACK tailgate
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Speed Limit Assistant
- Rear lights with taillights and brake lights using LED light guide technology
- Interior headliner fabric crystal grey
- Mechanical child safety lock
- Rear headrests (3)
- Paint finish: Solid
- LED High Performance headlights including Adaptive High Beam Assist
- Steering column mechanically adjustable in height and length
- Package: Parking package with reversing camera
- Package: Mirror package
- Upholstery: ARTICO leatherette/Bertrix fabric
- Tire pressure monitoring system
- Wheels: 43.2 cm (17") alloy wheels, 4-spoke design, 5-twin-spoke design
- Seats: Comfort seats
- Heated seats for driver and front passenger
- Bumpers in body color
- TIREFIT with tire inflation compressor
- Electronic immobilizer
- Decorative elements Star Pattern
- ADAPTIVE BRAKE with hill start assist, HOLD function, pre-filling and drying braking in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbag
- Traction control (ASR)
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Brake assist, active
- Third brake light in LED technology
- Door sills with "Mercedes-Benz" lettering
- Chassis: Comfort chassis with lowered suspension
- Velour floor mats
- Transmission: 8G-DCT automatic
- Rear window wiper with intermittent function
- Heated rear window with timer
- ISOFIX child seat attachment with top tether in the rear
- THERMATIC automatic climate control
- Front headrests are height-adjustable
- Cargo area cover
- Steering wheel: Multifunction sports steering wheel in leather
- Steering: Direct steering
- Navigation: MBUX Navigation Premium
- Package: Seating comfort
- Package: USB Package Plus
- Radio accessories: Central Media Display
- Remote Services Plus
- Seat belts B-Class
- Seats: 4-way lumbar support for driver and front passenger
- Seats: Rear seat backrests foldable in a 40/20/40 ratio
- Lane Keeping Assist, active
- Cruise control
- Pre-installation for digital key handover
- Central locking

Extra equipment

- Paint finish: Solid polar white
- Package: Advanced Plus (KEYLESS-GO Comfort Package (incl. HANDS-FREE ACCESS and KEYLESS-GO) - Ambient lighting - Fully digital instrument display - Wireless charging system for mobile devices in the front - Fingerprint scanner)
- Package: Cargo area (12V socket in the luggage compartment - reversible mat - nets on the left and right sides - storage compartment under the left net - tension strap on the right side - net on the trunk floor)
- Wheels: Run-flat tires (instead of TIREFIT tire sealant)
- Wheels: Winter complete wheels M+S 4-way 43.2 cm (17") (43.2 cm (17") light alloy wheels 5-twin-spoke design aerodynamically optimized, vanadium silver painted with 205/55 R17 on 6.5J x 17 ET44)
- MULTIBEAM LED (18 individually controllable high-performance LEDs per MULTIBEAM LED module; low beam and high beam in LED projection technology; Adaptive Highbeam Assist Plus; Active cornering light when high beam is activated; Country road light, city light and motorway light with road illumination optimized for the driving situation; Cornering light with roundabout and intersection function in conjunction with hard drive navigation; Adaptive full-LED taillights with automatic adjustment of light intensity to the surroundings)
- Wheels: Complete summer wheel sets fitted at the factory
- Seats: Driver's seat electrically adjustable with memory function
- Seats: Front right seat electrically adjustable with memory
- Separation net

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Bonnet	Bonnet - dent(s) - Smooth repair work
2	Door - rear left side	Door - Scratch(es) - Smart repair
3	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
4	Side panel - rear right side	Sill - Scratch(es) - Smart repair
5	Rear bumper	Rear bumper - Scratch(es) - Paint
6	Front bumper	Front bumper (Steinschläge) - dent(s) - Repair and paint
7	Boot lid / rear door	Boot lid (Steinschlag) - Corrosion - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Tirefit complete

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Roof, Front, Rear, Provided by user / customer, from 12 Jul 2024	9.172,25 €

Repainting

No.	Repainting
1	Bonnet, Professionally carried out

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Damage 1: Bonnet: Bonnet - dent(s) - Smooth repair work




Damage 1: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 2: Door - rear left side: Door - Scratch(es) - Smart repair



Damage 2: Door - rear left side: Door - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 4: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 4: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 4: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 6: Front bumper: Front bumper (Steinschläge) - dent(s) - Repair and paint




Damage 6: Front bumper: Front bumper (Steinschläge) - dent(s) - Repair and paint



Damage 6: Front bumper: Front bumper (Steinschläge) - dent(s) - Repair and paint



Damage 6: Front bumper: Front bumper (Steinschläge) - dent(s) - Repair and paint




Damage 6: Front bumper: Front bumper (Steinschläge) - dent(s) - Repair and paint



Damage 6: Front bumper: Front bumper (Steinschläge) - dent(s) - Repair and paint



Damage 6: Front bumper: Front bumper (Steinschläge) - dent(s) - Repair and paint



Damage 7: Boot lid / rear door: Boot lid (Steinschlag) - Corrosion - Repair and paint



Damage 7: Boot lid / rear door: Boot lid (Steinschlag) - Corrosion - Repair and paint



Damage 7: Boot lid / rear door: Boot lid (Steinschlag) - Corrosion - Repair and paint



Damage 7: Boot lid / rear door: Boot lid (Steinschlag) - Corrosion - Repair and paint



Damage 7: Boot lid / rear door: Boot lid (Steinschlag) - Corrosion - Repair and paint



Previous damage 1: Roof, Front, Rear



Previous damage 1: Roof, Front, Rear



Previous damage 1: Roof, Front, Rear



Previous damage 1: Roof, Front, Rear



Previous damage 1: Roof, Front, Rear



Previous damage 1: Roof, Front, Rear

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen



Repainting 1: Bonnet



Repainting 1: Bonnet