DEKRA

DEKRA Automotive Solutions


# Condition Report

## Vehicle details

| | | | | | |
|---|---|---|---|---|---|
| VIN | WAUZZZGY6 TA044478 | Mileage | 23 077 km | Engine (Fuel) Type | Hybrid petrol |
| Licence Plate | 2HTS133 | Registration date | 05/11/2025 | Engine size | 1498 |
| Brand | AUDI | Fuel level | - | Transmission | Automatic |
| Model | A3Lim-8YS-2020 | Car type | PC | Gears | - |
| Body Type | SUV CrossOver | Number of seats | - | Condition of the car | Unknown |
| Doors | 5 | Exterior Color | Gris | | |

## Inspection Details

| | | | | | |
|---|---|---|---|---|---|
| Inspection date | 29/10/2026 | Inspection loc. | AVIS Own Risk - Parc AVIS | Fleet owner | AVIS Own Risk Belgique |




## Other technical information

| | |
|---|---|
| Emergency compressor kit | ✔ |
| Refill emergency kit | ✔ |

## Tyres

Bridgestone 225/45/17 V Summer 4.0 mm

Bridgestone 225/45/17 V Summer 4.0 mm





Bridgestone 225/45/17 V Summer 5.0 mm

Bridgestone 225/45/17 V Summer 5.0 mm

## Damages


**1**



| | |
|---|---|
| Part | Wheel nut trim |
| Position | Front right |
| Damages | Missing |
| Severity | - |
| Repair mode | Replace |
| Net cost (Excluding VAT) | 10.28€ |

x5

**2**



| | |
|---|---|
| Part | Wheel nut trim |
| Position | Back right |
| Damages | Missing |
| Severity | - |
| Repair mode | Replace |
| Net cost (Excluding VAT) | 10.28€ |

x5

**3**



| | |
|---|---|
| Part | Wheel nut trim |
| Position | Back left |
| Damages | Missing |
| Severity | - |
| Repair mode | Replace |
| Net cost (Excluding VAT) | 10.28€ |

x5

**4**



| | |
|---|---|
| Part | Wheel nut trim |
| Position | Front left |
| Damages | Missing |
| Severity | - |
| Repair mode | Replace |
| Net cost (Excluding VAT) | 10.28€ |

x5

DEKRA

DEKRA Automotive Solutions

# Condition Report

**5**



| | |
|---|---|
| Part | Roof |
| Position | Centre |
| Damages | Dented |
| Severity | - |
| Repair mode | Repair |
| Net cost (Excluding VAT) | 517.00€ |
| gros impacts | |

**6**



| | |
|---|---|
| Part | Door |
| Position | Back left |
| Damages | Dented |
| Severity | - |
| Repair mode | Smart Repair |
| Net cost (Excluding VAT) | 49.00€ |

**7**



| | |
|---|---|
| Part | Bonnet |
| Position | - |
| Damages | Dented |
| Severity | - |
| Repair mode | Repair |
| Net cost (Excluding VAT) | 428.13€ |
| gros impacts | |

## Summary Inspection

| | |
|---|---|
| Net Price (Exclusing VAT) | 1,035.25€ |