TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48412535
Order No. / Reference: 27162595
Inspection date: 21 Oct 2026

Manufacturer: Volkswagen	Model: Crafter 35 TDI Autm. 4MOTION
VIN: WV1ZZZSYXN9050546	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Crafter 35 TDI Autm. 4MOTION	
Vehicle Identification number	WV1ZZZSYXN9050546
Mileage (Read)	135,673 km
First registration	3 Aug 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	130 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Van
Colour / colour code	Candy White (B9A)
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Anthracite-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	10,300 km
Last service on / at	04/2026 at 119,517 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ227735
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CCB 23364		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 113R	Summer tyres on Steel rim with wheel cover	Continental	7mm / 7mm
2)	235/65 R16 113R	Summer tyres on Steel rim with wheel cover	Continental	7mm / 7mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Driver's side
- Convex exterior mirrors (left and right), with integrated LED turn signal and wide-angle range
- Floor coverings: Rubber floor covering in the driver's cab
- Three-point automatic seat belts (with belt height adjustment and belt tensioners for driver and front passenger)
- Total weight: Vehicle registration with a permissible total weight of 3.5 t
- Rear wing door without window cutout
- High roof, painted exterior in car color
- Headrests (2)
- Paint finish: Solid
- Headlight range control
- Multifunction display "Plus"
- Package: Fuel consumption optimization package without stone chip protection
- Upholstery: Seat covers in fabric, design "Austin"
- Wheels/Tires: 235/65 R 16 C 115/113 R, optimized for low rolling resistance
- Wheels: Tire Mobility Set (12-volt compressor and tire sealant)
- Crosswind assist
- Seat belt monitoring system (warning buzzer and light when front seat belts are not fastened)
- Power outlet: 12V socket and 4 cup holders in the dashboard
- Daytime running light
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control and interior operation
- Accessories: On-board tools
- 4MOTION all-wheel drive (permanent)
- Exterior mirrors, adjustable from the outside
- Hill Start Assist
- third brake light
- Electronic Stability Program and ABS
- Chassis: Suspension and damping, standard
- Electric windows, front
- Transmission: 8-speed automatic
- Weight class front axle (reinforced front axle)
- Rear doors/tailgate: Hinges for rear doors
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Steering wheel adjustable in height and reach
- Marker lights, side
- Without the efficiency package
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- Wheel cover center
- Wheels: Steel wheels 6.5 J x 16, in silver (load capacity 1,200 kg)
- Sliding door, on the right in the passenger/cargo area
- Keys for locking system: 2 remote control flip keys
- electromechanical power steering
- Seats 1st row: Seat on the right
- Start-stop system (with brake energy recuperation)
- Power outlets: 2 12V sockets in the driver's cab (in the dashboard)
- Partition walls: Partition wall
- Lashing eyes for securing cargo
- Heat-insulating glazing (front and rear side windows and rear window in heat-insulating glass (if fitted))
- Registration as a truck (with an N1 registration (up to and including 3.5 t permissible total weight))

Extra equipment

- Storage compartments: Glove compartment with lockable, illuminated flap
- Exterior mirrors, electrically adjustable, heated and folding
- Three-point automatic seat belts (with front belt height adjustment and electric belt tensioner for the driver)
- High beam assistant "Light Assist"
- Floor mats: All-weather mats in the driver's cab (made of rubber)
- Fog lights including cornering lights
- ParkPilot in the front and rear area with active side protection
- "Discover Media" radio navigation system including "Streaming & Internet" with 4 speakers (voice control - 2 USB ports (Type C) in the dashboard - illuminated glove compartment with lockable flap - "Discover Media" radio navigation system with 20.3 cm (8 inch) touchscreen including "Streaming and Internet" - 4 speakers: 2 tweeters, 2 woofers - Wired & Wireless App-Connect - mobile phone interface)
- Hinges for rear doors with an increased opening angle (270°)
- Seats 1st row: Double passenger seat on the right, with storage compartment, in the 1st row (including headrest, height adjustable)
- Seats 1st row: "ergoComfort" suspension seat on the left, in the 1st row
- Power outlets: 12 volt socket(s) (2 12V sockets in the passenger/cargo area (one on the C-pillar, one on the D-pillar))
- Storage package 2: Roof gallery with two 1-DIN slots and reading light
- Floor coverings, wooden floor (wooden floor in the cargo area with loading edge protection, rear)
- Suspension/damping, reinforced and stabilization, reinforced
- Interior lighting: Front step lighting
- Air conditioning with manual control in the driver's cab
- Package: Driver Assistance 2: Front Assist, ACC, Lane Assist (Drowsiness Detection - Multifunction Steering Wheel (3 Spokes) - Front Assist with City Emergency Braking (for ACC up to 160 km/h) - Lane Assist - ACC up to 160 km/h, including speed limiter - Multifunction Display "Plus")
- Radio accessories: Digital radio reception DAB+
- Smoker's version (12V socket with cigarette lighter, ashtray and 4 cup holders in the dashboard)
- Wheels, tires: All-season tires
- Rear View reversing camera
- Windscreen wiper intermittent control with rain sensor, automatic headlight control (daytime running lights with automatic headlight control, "Leaving home" function and manual "Coming home" function - windscreen wiper intermittent control with light and rain sensor)
- Seat heating, left and right, separately adjustable, in the 1st row of seats
- Partition walls: Partition wall with cladding

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Sill - Dent / paintcoat damage - Smart repair
2	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
3	Seat - front	Seat cover - left side - Porous / cracked - Replace
4	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
5	Vehicle glazing	Windscreen - Stone chips - Replace
6	Sliding door, right	Sliding door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Navigation




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.



Damage 1: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 1: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 1: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work




Damage 2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work




Damage 2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 3: Seat - front: Seat cover - left side - Porous / cracked - Replace



Damage 3: Seat - front: Seat cover - left side - Porous / cracked - Replace



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 5: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 6: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint




Damage 6: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 6: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 6: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 6: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 6: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 6: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint