TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48516170
Order No. / Reference: 27251535
Inspection date: 3 Nov 2026

Manufacturer: Volkswagen	Model: ID.3 PRO S 150 KW 5-Sitzer
VIN: WVWZZZE1ZPP055357	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen ID.3 PRO S 150 KW 5-Sitzer	
Vehicle Identification number	WVWZZZE1ZPP055357
Mileage (Read)	78,173 km
First registration	28 Aug 2023
Number of holders	1
Next periodical technical inspection	08/2026
(Report not on hand)	
Fuel type	Electric
Power	70 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Saloon car
Colour / colour code	Scala Silver Metallic / Dach Schwarz
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	326 Tag(e)
Last service on / at	10/2025 at 53,968 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV326159
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0603 / CKW 00067		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,300 kg	**Empty weight**	
Dimensions	4261 x 1809 x 1546		

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R19 93T	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	215/50 R19 93T	Summer tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R19 93T	Winter tyres on Light alloy	Bridgestone	6mm / 6mm
2)	215/50 R19 93T	Winter tyres on Light alloy	Bridgestone	3mm / 3mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Turning brake function and evasive steering support
- Airbags: Front and rear head airbags, front side airbags, center airbag
- App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto
- third brake light
- CCS charging socket
- Black surround for the infotainment display and central controls
- Driving profile selection
- Transmission: Direct drive, 1-speed
- rear window wiper
- "Climatronic" air conditioning system
- Mode 3 Type 2 charging cable, 16 A
- LED taillights
- Steering wheel: Multifunction steering wheel in leather
- Front center console with 2 cup holders
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Upholstery in microfleece “ArtVelours”
- Radio accessories: 2 USB-C ports at the front
- Tire pressure monitoring system (passive)
- Keyless start system without safe locking
- electromechanical power steering
- Seats: 3 rear seats, rear seat backrest asymmetrically split and foldable
- Seats: Front seats are height-adjustable
- First aid kit, warning triangle and high-visibility vest
- Warning tone and light for unfastened seat belts front and rear
- Central locking with remote control
- Airbag for driver and front passenger
- 30-color ambient lighting
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors
- Vehicle tool kit
- Car2X
- e-Sound
- Parking assistance
- Electronic Stability Program (ESP)
- Speed limiter
- Rear window heated
- ISOFIX mounting points
- Headrests (5) front and rear
- Charging: 11 kW AC charging capacity
- LED headlights with automatic headlight control
- Illuminated makeup mirrors in the sun visors
- Fatigue detection
- Emergency call service
- Online update capability from ID.Software 2.1 onwards.
- Radio: "Ready 2 Discover"
- Radio accessories: 4 + 1 speakers
- Wheels: 4 "Andoya" alloy wheels 7.5 J x 19 in black, polished finish
- Seat belts: Three-point automatic seat belts at the front with belt tensioners
- Seats: Armrests, front seats
- Lane keeping assistant “Lane Assist”
- Traffic sign recognition
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear

Extra equipment

- Two-tone paintwork with black roof, Scale Silver Metallic
- Package: Infotainment package (Navigation system "Discover Pro" (touchscreen, internet access for music listening, information, telephone calls, access to the mobile online services of We Connect Plus, DAB+) - Telephone interface "Comfort" with inductive charging function (hands-free system))
- Textile floor mats front and rear
- Heat pump for range optimization
- Charging cable: Mains charging cable for household socket
- Package: Comfort Package (Pro S) (2 USB-C ports in the front, 2 USB-C charging ports on the rear center console - Electrically adjustable, folding and heated exterior mirrors - Automatically dimming interior mirror - Center console with illuminated storage compartment with roller blind, 2 cup holders - Rain sensor - Automatically heated front windshield washer nozzles - Ambient lighting with logo projection - Heated front seats)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Side panel - Stone chips - Smart repair
2	Misc.	Main inspection - Due - Perform
3	Measurement	Undercarriage - Malposition - Measure
4	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
5	Wheel / tyres	Tyres - complete set (Einseitig abgefahren) - Worn - Replace

Wear and tear

No.	Component group	Description
1	2nd wheel set	2 tyres (3mm) - Does not meet the leasing specifications - No deduction
2	2nd wheel set	1 alloy rim - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - front left side	177 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Damage 1: Side panel - rear right side: Side panel - Stone chips - Smart repair



Damage 1: Side panel - rear right side: Side panel - Stone chips - Smart repair



Damage 3: Measurement: Undercarriage - Malposition - Measure




Damage 3: Measurement: Undercarriage - Malposition - Measure



Damage 3: Measurement: Undercarriage - Malposition - Measure



Damage 3: Measurement: Undercarriage - Malposition - Measure




Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 5: Wheel / tyres: Tyres - complete set (Einseitig abgefahren) - Worn - Replace




Damage 5: Wheel / tyres: Tyres - complete set (Einseitig abgefahren) - Worn - Replace



Damage 5: Wheel / tyres: Tyres - complete set (Einseitig abgefahren) - Worn - Replace




Damage 5: Wheel / tyres: Tyres - complete set (Einseitig abgefahren) - Worn - Replace



Wear and tear 2: 2nd wheel set: 1 alloy rim - Scratch(es) - No deduction



Wear and tear 2: 2nd wheel set: 1 alloy rim - Scratch(es) - No deduction



Wear and tear 2: 2nd wheel set: 1 alloy rim - Scratch(es) - No deduction



Repainting 1: Door - front left side



Repainting 1: Door - front left side