TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48566726
Order No. / Reference: 27283740
Inspection date: 6 Nov 2026

Manufacturer: Mercedes-Benz	Model: Vito 110 CDI Lang VA BASE
VIN: W1V44760313866864	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz Vito 110 CDI Lang VA BASE	
Vehicle Identification number	W1V44760313866864
Mileage (Read)	84,316 km
First registration	7 Jun 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,750 ccm / 4
Power	75 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	brillantsilber metallic
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	657 Tag(e)
Last service on / at	08/2026 at 81,886 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GB979940
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / ARU 00295		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Winter tyres on Steel rim with wheel cover	Michelin	8mm / 8mm
2)	205/65 R16 107T	Winter tyres on Steel rim with wheel cover	Pirelli	9mm / 9mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Summer tyres on Steel	Continental	7mm / 7mm
2)	205/65 R16 107T	Summer tyres on Steel	Continental	8mm / 8mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- AdBlue tank (24 liters)
- Attention Assistant
- Hill start assist
- Brake lights, adaptive
- Diesel particulate filter
- Electronic Stability Program (ADAPTIVE ESP) with integrated anti-lock braking system (ABS) (traction control (ASR) - electronic brake force distribution (EBD) - brake assist (BAS))
- Transmission: 6-speed manual
- Lockable glove box
- Interior trim of cargo area, side
- Headrests (2), front
- Headlight range control
- Mercedes-Benz emergency call system (communication module (LTE) for digital services breakdown management)
- Wheels: Steel rims 6.5 J x 16
- Key: 3-button remote control
- electromechanical power steering
- 12V socket
- First aid kit
- Pre-installation for Remote Services Plus
- Maintenance interval indicator >>ASSYST<
- Heat-insulating glass all around
- Airbag for driver and front passenger
- Outdoor temperature display
- third brake light
- Ceiling interior light (in driver and passenger area)
- ECO start/stop function
- Electric window regulator driver/passenger (with anti-pinch protection, quick lowering and raising)
- Parking brake
- Speed limit 210 km/h
- Seatbelt warning device for driver and front passenger seat
- Tailgate with an opening angle of approximately 90°
- Instrument cluster (speedometer with trip odometer - quartz-controlled digital clock - fuel gauge - electronic tachometer)
- Package: BlueEFFICIENCY (Efficiency Package)
- Upholstery: Caluma fabric, black
- Sliding door on the right, cargo/passenger compartment
- Crosswind Assist
- Front stabilizer
- continuous partition wall
- Lashing eyes in the cargo area
- Warning triangle
- Immobiliser
- Central locking with radio remote control

Extra equipment

- Upgrading/downgrading (upgrading to 3.05 t GVW)
- Battery: fleece battery 12 V / 92 Ah
- Deletion: Cruise control
- Tempmatic controlled air conditioning
- Large fuel tank, approx. 70 liters
- LED light strip in the cargo area
- Package: Smoker's package
- Rain sensor
- Tires: 205/65 R 16
- Tire pressure monitoring (on front and rear axles (wireless))
- Seat: Lumbar support driver's seat
- Seat heating on driver's side
- Electrically adjustable and heated exterior mirrors, left and right
- Driving light assistant (automatically switching on driving lights)
- Paint finish: Metallic
- Steering wheel adjustable for tilt and height
- Radio: Audio 30 (DAB Digital Radio - 7" LCD touchscreen - Apple CarPlay and Android Auto - Bluetooth 3.0, hands-free system - 2-way front speakers)
- High-resolution reversing camera with guide lines
- Cabinet installation
- Seats: Comfort driver's seat
- Auxiliary heater, electric

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Mudguard - right side	Mudguard - right side - dent(s) - Smart repair
2	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Roof	Roof - dent(s) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Boot lid / rear door	Boot lid - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 30 Apr 2025	1.474,46 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation




Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.




Damage 1: Mudguard - right side: Mudguard - right side - dent(s) - Smart repair



Damage 1: Mudguard - right side: Mudguard - right side - dent(s) - Smart repair



Damage 2: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 2: Vehicle glazing: Windscreen - Broken / torn - Replace