TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48541920
Order No. / Reference: 27260932
Inspection date: 5 Nov 2026

Manufacturer: Mercedes-Benz	Model: 311 CDI Sprinter Kompakt HA Kasten
VIN: W1V9076311P215628	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz 311 CDI Sprinter Kompakt HA Kasten	
Vehicle Identification number	W1V9076311P215628
Mileage (Read)	100,575 km
First registration	16 Mar 2020
Number of holders	1
Next periodical technical inspection	04/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	2,143 ccm / 4
Power	84 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Iridiumsilber metallic
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	524 Tag(e)
Key is / should be	2 / 2	**FZG documents**	ZB#1 (S) was available (copy), ZB#2 (B) was not available.
		Letter No.	FS118709
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	2222 / ARJ 02566		
Emission standard	EUROVI	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Winter tyres on Steel	Fulda	5mm / 5mm
2)	235/65 R16 115R	Winter tyres on Steel	Fulda	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Summer tyres on Steel	Continental	7mm / 7mm
2)	235/65 R16 115R	Summer tyres on Steel	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	235/65 R16 115R	All-season tyres on Steel	Continental	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment above windshield
- Rear towing eye
- Driver's side airbag
- Electrically adjustable and heated exterior mirrors, left and right
- third brake light
- Diesel particulate filter and SCR
- Driving light assistant
- Transmission: 6-speed manual
- Instrument panel and combination instrument with various storage options
- Communication module (LTE) for digital services
- Paint finish: Solid color paint
- Headlight range control
- Upholstery: Cloth
- Radio: Pre-installation for digital radio DAB
- Sliding door on the right side
- Power steering
- Seats: Driver's seat armrest
- Seats: Driver's seat adjustable
- continuous partition wall
- Lashing eyes
- ASSYST maintenance interval indicator
- Central locking with radio remote control
- Storage compartment under cockpit
- ADAPTIVE ESP (latest generation) with load- and speed-dependent driving dynamics control
- Outdoor temperature display
- Battery: fleece battery 1x 12 V / 70 Ah
- Brake lights, adaptive
- Tachometer
- Electric window regulator for driver and passenger door
- Seatbelt warning device for driver's seat
- KEYLESS start
- Child safety locks on doors in the passenger compartment
- Headrests (2), front
- Steering wheel adjustable for tilt and height
- Mercedes-Benz emergency call system
- Radio: Radio preparation
- Wheels: Steel rims 6.5 J x 16
- Crosswind Assist
- Seats: Passenger seat armrest
- Seats: Adjustable passenger seat
- Daytime running light
- Doors: Rear doors, double-wing doors opening 180 degrees, available in two height versions
- Immobiliser

Extra equipment

- Entrance rear door
- Tempmatic controlled air conditioning
- Cable duct at rear portal
- Steering wheel: Multifunction steering wheel
- Navigation (linguatronic voice control, Wi-Fi hotspot, multimedia connection unit for connecting portable devices via an additional USB-C interface, center fill speaker for improved sound and voice output, improved hands-free function, dual-phone operation, digital operating instructions)
- Package: Parking package with reversing camera
- Package: SMOKER
- Radio: Digital Radio DAB
- Spare wheel carrier with jack (under frame end)
- Key: Multi-button radio remote control
- Seats: Comfort driver's seat
- Seat heating on driver's side
- Hot water auxiliary heater (5 kW)
- Battery: fleece battery 12 V / 92 Ah
- Paint finish: Metallic
- Cable duct on side wall
- MBUX multimedia system with 7-inch touchscreen (High-resolution 7-inch touchscreen (960 x 540 pixels), AM/FM radio with dual tuner, Bluetooth connectivity with audio streaming and hands-free function, smartphone integration via Android Auto or Apple CarPlay, multimedia connection unit for connecting portable devices via a USB-C interface, 4 x 25 W output power, sound adjustment, separate volume control for audio and telephone, 2-way front speakers)
- Spare wheel
- Wheels: Hydraulic jack
- Keys: 2 additional master keys
- Seats: Lumbar support for driver's seat
- Start-stop function
- Heat-insulating glass

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 1 (registration document) was available, but the vehicle registration certificate Part 2 (title) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Rear door - left side (Schleifspuren) - Unprofessionally repaired - Cover / polish
2	Wheel / tyres	Spare wheel - wheel rim (Sta) - Corrosion - Replace
3	Side panel - rear right side	Side panel - Unprofessionally repaired - Smart repair
4	Bonnet	Bonnet - dent(s) - Smooth repair work

Wear and tear

No.	Component group	Description
1	Interior	Cargo area floor - Scratch(es) - No deduction
2	Rear bumper	Rear bumper (unpainted) - Scratch(es) - No deduction
3	Interior	Cargo space partition (Bott Regalsystem) - Differs from the original configuration - No deduction
4	Misc.	Inspection / maintenance - No evidence - No deduction
5	Braking system	Brake fluid - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side right, Provided by user / customer	

Repainting

No.	Repainting
1	Boot lid / rear door, Side panel - rear right side, Door - front right side

Paint coat thickness measurement

Boot lid / rear door	240.61 µm	Side panel - rear right side	222 µm
Door - rear right side	317 µm	Door - front right side	178 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Für den montierten Radsatz wurde kein Nachweis erbracht.

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Instrument cluster



Figure 7: Instrument panel

Figure 8: Interior 360° view (Online Link)



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Damage 1: Boot lid / rear door: Rear door - left side (Schleifspuren) - Unprofessionally repaired - Cover / polish



Damage 1: Boot lid / rear door: Rear door - left side (Schleifspuren) - Unprofessionally repaired - Cover / polish



Damage 1: Boot lid / rear door: Rear door - left side (Schleifspuren) - Unprofessionally repaired - Cover / polish



Damage 2: Wheel / tyres: Spare wheel - wheel rim (Sta) - Corrosion - Replace



Damage 2: Wheel / tyres: Spare wheel - wheel rim (Sta) - Corrosion - Replace



Damage 3: Side panel - rear right side: Side panel - Unprofessionally repaired - Smart repair



Damage 3: Side panel - rear right side: Side panel - Unprofessionally repaired - Smart repair



Damage 3: Side panel - rear right side: Side panel - Unprofessionally repaired - Smart repair



Damage 3: Side panel - rear right side: Side panel - Unprofessionally repaired - Smart repair



Damage 4: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 4: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 4: Bonnet: Bonnet - dent(s) - Smooth repair work



Wear and tear 1: Interior: Cargo area floor - Scratch(es) - No deduction



Wear and tear 2: Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction




Wear and tear 2: Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - front right side