TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48535959
Order No. / Reference: 27206227
Inspection date: 29 Oct 2026

Manufacturer: Opel	Model: Vivaro 2.0 D Cargo L EHZ Autm. Elegance Kasten
VIN: VXEVFEHZ7N7041488	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Vivaro 2.0 D Cargo L EHZ Autm. Elegance Kasten	
Vehicle Identification number	VXEVFEHZ7N7041488
Mileage (Read)	73,883 km
First registration	30 Sept 2022
Number of holders	1
Next periodical technical inspection (Report not on hand)	11/2026
Fuel type	Diesel
Engine displacement / Cylinder	1,997 ccm / 4
Power	130 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Jade weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Re-import	no
readiness to drive	Not roadworthy / moveable

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	30,600 km
Last service on / at	01/2026 at 62,387 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GN176201
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	3003 / AXZ 01227		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,100 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 106T	Summer tyres on Steel rim with wheel cover	Michelin	6mm / 6mm
2)	215/65 R16 106T	Summer tyres on Steel rim with wheel cover	Michelin	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 106R	Winter tyres on Light alloy	Pirelli	7mm / 7mm
2)	215/65 R16 109T	Winter tyres on Light alloy	Pirelli	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments (storage compartment in the center console, front - storage shelf above the windshield, open - storage compartment in the front doors, suitable for 1.5-liter beverage bottles - glove compartment, open - storage compartment on dashboard, passenger side, closed)
- Exterior mirror housings in black
- Hill Start Assist
- On-board computer
- Diesel particulate filter, maintenance-free
- Three-point seat belts on all seats (belt force limiter, front - double belt tensioners, front - warning tone and light for unfastened seat belts, front)
- Speed controller and limiter
- Grab handle in the first row of seats, passenger side
- Air conditioning, front with particle and odor filter (recirculation mode, manual)
- Fatigue detection level 1 coffee break
- Package: Driver Assistance Package 1 (High Beam Assist - Driver Alert System with Camera Monitoring - Lane Keeping Assist - Traffic Sign Recognition with Intelligent Speed Control - Solar Reflect Windscreen)
- Radio accessories: Digital radio reception DAB+ (Digital Audio Broadcasting) (Offers a wider selection of radio programs. Digitally broadcast radio stations and traffic information can be received.)
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- Wheels: Steel wheels 7 J x 16 with wheel hub cover (tires 215/65 R 16 C 106T)
- Side impact protection
- Speed-sensitive power steering
- Seats: Comfort driver's seat and double passenger seat (comfort driver's seat adjustable in 6 ways, with armrest and lumbar support - double passenger seat with storage under the seat - height-adjustable headrests, front)
- Daytime running light
- Traction control with engine and brake intervention (TC Plus)
- Electronic immobilizer
- Central locking with remote control
- Ignition key (2), foldable
- ABS including brake assist and adaptive brake light
- Driver and passenger side airbags (front airbag, passenger airbag, deactivatable)
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Exterior mirrors, electrically folding, heated and adjustable
- Battery discharge protection
- Floor covering: Cargo area floor, painted
- third brake light
- Tachometer
- Electric parking brake
- Electronic Stability Program (ESP Plus)
- Electric front windows (with one-touch function)
- Transmission: 8-speed automatic
- Glove compartment closed at the top (cooled and illuminated)
- Steering column, adjustable for reach and height
- Fog light
- Park pilot, front and rear parking aid (with acoustic warning signal when parking forwards and backwards - blind spot warning - electrically folding exterior mirrors - fog lights)
- Radio: Multimedia radio with 7" color touchscreen display (Automatic music recognition for audio devices with USB connection, Bluetooth audio streaming, DAB+ digital radio reception, hands-free calling via Bluetooth interface, phonebook and call list display, up to 10 mobile phones can be paired, display of pictures/films/videos via USB interface, smartphone integration, voice control, 1 USB interface, dual tuner, graphic equalizer, 4 speakers (8 in double cab Edition or Elegance))
- Side protection strips (in black)
- Visibility equipment (rain sensor - automatic dipped headlights)
- Sun visors, driver and passenger
- 12-volt power outlet in the center console
- 12V power outlet in the cargo area and in the lower glove compartment (2nd row of seats, left side of cargo area)
- Doors: Sliding door, passenger side
- Lashing eyes (8) in the cargo area
- Heat-insulating glazing, tinted
- Payload increased by +300 kg

Extra equipment

- Additional cost for fixtures
- Steering wheel: Multifunction leather steering wheel
- Package: Design package (front and rear bumpers in body color - door handles in body color - exterior mirror housings in black - exterior mirrors, electrically adjustable, heated and folding - side protection strip in body color - fog lights - LED daytime running lights)
- Retrofitted seat heating
- Sortimo installations
- Partition wall: closed with window (FlexCargo function)
- Doors: Rear wing doors, glazed with a 180° opening angle (and heated rear window wipers)
- Design Package
- Multimedia Navigation Pro
- 180° panoramic reversing camera (displays the area behind the vehicle up to 180 degrees, including steering guidelines, when reverse gear is engaged, on the color display of the infotainment system.)
- Seats: Comfort driver's seat and multifunctional double passenger seat (comfort driver's seat adjustable in 6 ways, with armrest and lumbar support - multifunctional double passenger seat with pass-through function and DIN A4 desk - headrests, height adjustable)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Missing - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Rear bumper	Bumper - rear right side - Scratch(es) - Loss in value
4	Boot lid / rear door	Rear door - left side - Dent / paintcoat damage - Smart repair
5	Mudguard - left side	Mudguard - left side - Scratch(es) - Smart repair
6	Engine	Engine - Leaking - Perform diagnosis
7	Rear bumper	Bumper - rear left side - Scratch(es) - Smart repair
8	Body	A-pillar - right side - Scratch(es) - Smart repair
9	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Smart repair
10	Roof	Roof - dent(s) - Smooth repair work
11	Trim / covers	Door trim - rear left side - Broken / torn - Replace
12	Front bumper	Front bumper (Inklusive anbauteile) - Scratch(es) - Paint
13	Bonnet	Bonnet - Scratch(es) - Paint
14	Door - front left side	Door - Scratch(es) - Paint
15	Side panel - rear left side	Side panel (Lack löst sich) - Unprofessionally repaired - Repair and paint
16	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Repair and paint
17	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Side panel - Dent / paintcoat damage - No deduction
2	Body	A-pillar - left side - Scratch(es) - No deduction
3	Rear bumper	Rear bumper (unpainted) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 24 Sept 2025	603,90 €
2	Rear, Provided by user / customer, from 20 Dec 2022	1.369,77 €
3	Side - left, Provided by user / customer, from 26 Nov 2025	2.913,96 €

Accident damages

No.	Accident
1	Side right

Repainting

No.	Repainting
1	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear left side	653 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Rear bumper: Bumper - rear right side - Scratch(es) - Loss in value



Damage 3: Rear bumper: Bumper - rear right side - Scratch(es) - Loss in value



Damage 3: Rear bumper: Bumper - rear right side - Scratch(es) - Loss in value



Damage 4: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 4: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 4: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 4: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 4: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 5: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



Damage 5: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



Damage 6: Engine: Engine - Leaking - Perform diagnosis




Damage 7: Rear bumper: Bumper - rear left side - Scratch(es) - Smart repair



Damage 7: Rear bumper: Bumper - rear left side - Scratch(es) - Smart repair




Damage 8: Body: A-pillar - right side - Scratch(es) - Smart repair



Damage 8: Body: A-pillar - right side - Scratch(es) - Smart repair



Damage 9: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 9: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair




Damage 9: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 9: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 10: Roof: Roof - dent(s) - Smooth repair work




Damage 10: Roof: Roof - dent(s) - Smooth repair work




Damage 10: Roof: Roof - dent(s) - Smooth repair work



Damage 10: Roof: Roof - dent(s) - Smooth repair work



Damage 10: Roof: Roof - dent(s) - Smooth repair work



Damage 11: Trim / covers: Door trim - rear left side - Broken / torn - Replace



Damage 11: Trim / covers: Door trim - rear left side - Broken / torn - Replace



Damage 12: Front bumper: Front bumper (Inklusive anbauteile) - Scratch(es) - Paint



Damage 12: Front bumper: Front bumper (Inklusive anbauteile) - Scratch(es) - Paint



Damage 12: Front bumper: Front bumper (Inklusive anbauteile) - Scratch(es) - Paint



Damage 12: Front bumper: Front bumper (Inklusive anbauteile) - Scratch(es) - Paint



Damage 12: Front bumper: Front bumper (Inklusive anbauteile) - Scratch(es) - Paint



Damage 12: Front bumper: Front bumper (Inklusive anbauteile) - Scratch(es) - Paint



Damage 13: Bonnet: Bonnet - Scratch(es) - Paint



Damage 13: Bonnet: Bonnet - Scratch(es) - Paint



Damage 13: Bonnet: Bonnet - Scratch(es) - Paint




Damage 14: Door - front left side: Door - Scratch(es) - Paint



Damage 14: Door - front left side: Door - Scratch(es) - Paint



Damage 14: Door - front left side: Door - Scratch(es) - Paint



Damage 14: Door - front left side: Door - Scratch(es) - Paint




Damage 15: Side panel - rear left side: Side panel (Lack löst sich) - Unprofessionally repaired - Repair and paint




Damage 15: Side panel - rear left side: Side panel (Lack löst sich) - Unprofessionally repaired - Repair and paint



Damage 15: Side panel - rear left side: Side panel (Lack löst sich) - Unprofessionally repaired - Repair and paint




Damage 15: Side panel - rear left side: Side panel (Lack löst sich) - Unprofessionally repaired - Repair and paint



Damage 15: Side panel - rear left side: Side panel (Lack löst sich) - Unprofessionally repaired - Repair and paint



Damage 16: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 16: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 16: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint




Damage 16: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 16: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 17: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 17: Vehicle glazing: Windscreen - Stone chips - Replace



Wear and tear 3: Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction




Wear and tear 3: Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Repainting 1: Side panel - rear left side



Repainting 1: Side panel - rear left side