MACADAM










MERCEDES-BENZ SPRINTER SC: GE-605-VZ

Vinnumber:	**W1V9071531N171340**	Versionname:	**MERCEDES-BENZ SPRINTER SC 514 Chassis cab 37 3,5t Propul. VU [2P] bvm 6-143CH-6cv (chÃ¢ssis cabinesimple cabine)**
First Registrationdate:	**23/02/2022**	Fiscalpower:	
Expertise Mileage:	**120246**	Power Kw:	**105**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**2**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Rear view camera	
Windows electric F		Seat cover lining	**Lining Other**
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**195/75/16/107 R**			
	Fr.L.	**Goodyear: 20%**	Fr.R.	**Goodyear: 25%**
	Re.L.	**Continental: 55%**	Re.R.	**Continental: 35%**

Tyre profile depth FL	**6.8**
Tyre profile depth FR	**6.7**
Tyre profile depth RL	**4.7**
Tyre profile depth RR	**6.0**
Tyre size FL	**195/75 R 16 107 R**
Tyre size FR	**195/75 R 16 107 R**
Tyre size RL	**195/75 R 16 107 R**
Tyre size RR	**195/75 R 16 107 R**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Remote ignition key (no insert), Missing, Repair/replace (lump sum)




Wheel cover FL, Broken, Replace





Bumper F, Scratch(es), Repair and paint (complete)





Bodywork, Not original part, Sticker removal small






ALPHABET

Historique Maintenance

Immatriculation: **GE-605-VZ** Date de 1ère immatriculation: **23/02/2022**

Modèle: **Mercedes SPRINTER SC 514 Chassis cab 37 3,5t Propul. VU [2P] bvm 6-143CH-6cv (châssis cabinesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
13/01/2026	110.751	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
09/07/2025	94.587	HAMECHER MONTAUBAN	PLAQUETTES AV RPLT
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		BALAIS ESSUIE GLACE AV
	0		PLAQUETTES AR RPLT
	0		ADBLUE
27/02/2025	80.253	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE
07/02/2025	78.945	CONTITRADE FRANCE	REPARATION DE ROUE
12/01/2024	50.487	HAMECHER MONTAUBAN	BALAIS ESSUIE GLACE AV
	0		ADBLUE
	0		REVISION ET CLIM