VOLVO XC40




Vehicle information


Brand:	**VOLVO**	License plate:	**2EAS463**
Gearbox:		Body color:	
Model:	**XC40**	LEVEL:	**YV1XZK9VDM2523323**
Fuel type:		Power:	**145 kW**
Version:	**2.0 B4 GEARTRONIC MOMENTUM PRO**	First registration	**26/01/2021**
Mileage:	**107826 km**	Number of doors:	

Summary of damages


Back	5
Before	2
RIGHT	4
LEFT	2
Interior	3
Roof & other	1




Commercial photos

















Options according to the inspector

GPS	**Yes**

Damages

Right rear
wing dent(s)
-
Paintless dent repair




Left front wing

dent(s) and scratch(es)

- Repair and paint (complete

)









Damaged **luggage cover**

E - Replace


Rear







Bodywork
Damaged -
Acceptable.
Roof & other











Ignition key
missing
E - Replace
Interior




Trunk/
Hatchback Dent(s) and Scratch(es)
LI - Repair and Paint (Complete)
Rear











Maintenance, Maintenance , Checking, Interior



Rear cover trim, Smart repair claw(s), rear










Rear bumper trim.
Dent(s) and scratch(es)
E - Replace
Rear











Damaged **Interior**
- Acceptable
Interior



Alloy wheel, right rear, scratch
(es)
, left front - Repair and paint (complete),
right side







Alloy wheel AVD

Scratch(es)

LI - Repair and paint (complete)

Right







Alloy wheel AVG

Scratch(es)

LI - Repair and paint (complete)

Left







Front bumper molding Smart repair
claw(s) front






Rear **bumper with**
scratches
- Repair and paint (complete)









Front bumper:
Dent(s) and scratch(es)
- Paint
front









Right rear door
dent(s) - Paintless
dent repair





Tires

Front Left
Summer
Aluminum
235/55/18/100/V
Pirelli
5.0 mm
Front Right
Summer
Aluminum
235/55/18/100/V
Pirelli
5.0 mm
Left Back
Summer
Aluminum
235/55/18/100/V
Continental
7.0 mm
Rear Right
Summer
Aluminum
235/55/18/100/V
Continental
7.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Vehicle inspection	**OK**
Vehicle inspection	**26/01/2027**	Interview	**NOT OK**
Interview	**0km**	Repair kit	**Yes**
Number of charging cables (220V)	**0**	Number of charging cables (fast charging)	**0**
Total number of keys	**1**	Factory reset	**No, that's not possible.**
Type of maintenance log	**Digital interview**		

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.