TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

# Expertise

Protocol number: 48417707
Order No. / Reference: 27219138
Inspection date: 29 Oct 2026

| Manufacturer: Opel | Model: Insignia Sports Tourer 2.0 Diesel Aut. Elegance |
|---|---|
| VIN: W0VZT8EP0N1043098 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Opel Insignia Sports Tourer 2.0 Diesel Aut. Elegance | |
| **Vehicle Identification number** | W0VZT8EP0N1043098 |
| **Mileage** (Read) | 154,701 km |
| **First registration** | 29 Nov 2022 |
| **Number of holders** | 1 |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,995 ccm / 4 |
| **Power** | 128 kW |
| **Gearbox / Number of gears** | Automatic / 8 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Station wagon |
| **Colour / colour code** | Argonsilber Metallic |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Black-Grey |

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | Available / complete | **Next maintenance in** | |
| **Last service on / at** | 05/2026 at 136,646 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GQ321971 |
| **Previous damage / Accident** | None detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | No |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 1844 / AMC 00298 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,215 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 245/45 R18 100Y | Summer tyres on Light alloy | Pirelli | 4mm / 4mm |
| 2) | 245/45 R18 100Y | Summer tyres on Light alloy | Bridgestone | 5mm / 5mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 225/55 R17 97H | Winter tyres on Light alloy | Dunlop | 6mm / 6mm |
| 2) | 225/55 R17 97H | Winter tyres on Light alloy | Pirelli | 6mm / 6mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| | Tirefit | Expiration date 09/2026 | | |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Storage compartments (storage compartment in the center console, pockets in the front doors suitable for 1.5-liter beverage bottles, pockets in the rear doors suitable for 1-liter beverage bottles, cup holder in the center console, illuminated glove compartment)
- Anti-lock braking system (ABS) (with cornering brake control (CBC) and brake assist)
- Hill Start Assist
- Glasses compartment in the headliner
- Decorative strip hexagon
- Tachometer
- Electronic Stability Program (ESP Plus)
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- Pedestrian protection including active hood
- Noise-reducing, laminated front side windows
- Speed controller
- Back window, heater
- Child safety lock in the rear doors, manual
- Front headrests (height adjustable)
- LED headlights (automatic headlight range control)
- LED daytime running lights including LED indicators, front and LED taillights
- Center armrest, front
- Parkpilot, front and rear parking aid
- Quickheat rapid heating system
- Tire repair kit (including tire sealant and 12-volt compressor (without jack))
- Rear seat backrest folds forward in a 60:40 split
- Seat belts: Three-point seat belts in all seats (belt force limiter and belt tensioner in the front and on the outer rear seats - warning tone and light for unfastened seat belts in all seats)
- Lane Keeping Assist (warning in case of unintentional lane departure (between 60 km/h and 180 km/h) via a warning light in the driver information display. The Lane Keeping Assist also alerts the driver by gently counter-steering, but does not continuously steer the vehicle.)
- Bumpers painted in body color
- Traction Control (TC) Plus (traction control with engine and brake intervention)
- Immobiliser
- Thermal insulation glazing, green tinted
- Adaptive brake light
- Airbag: Front and side airbags, driver and front passenger (front and side airbag, passenger, deactivatable)
- Airbag: Front and rear outer head airbags
- Ambient lighting (dashboard and doors (front))
- Electrically adjustable and heated exterior mirrors for driver and passenger side (manually foldable)
- third brake light
- Roof rails, silver anodized
- Diesel particulate filter
- Electronic brake force distribution (EBD)
- Driver information display, 3.5"
- Front collision warning system with pedestrian detection and automatic emergency braking
- Luggage compartment cover (extendable with comfort operation)
- Transmission: 8-speed automatic transmission
- rear window wiper
- Automatic climate control, two zones
- Rear headrests (3 pieces) (height adjustable)
- LED fog lights
- Steering column adjustable in height and length
- Illuminated makeup mirrors in both sun visors
- Electric parking brake (including 12-volt socket)
- Upholstery: Billy fabric, black
- Radio: Digital radio reception DAB+
- Tire pressure display (with tire pressure warning - direct system with automatic calibration after wheel change)
- Power steering (speed-dependent)
- Safety net (for installation behind the 1st or 2nd row of seats)
- Visibility equipment (rain sensor, front)
- Seats: Ergonomic active seat (AGR) driver (length, height and backrest angle manually adjustable - seat tilt electrically adjustable - lumbar support electropneumatically adjustable in height and length - extendable thigh support, manually adjustable - headrest, height and tilt adjustable)
- Start/Stop system (reinforced starter, high-performance battery, brake energy recuperation, switch to deactivate the start/stop function)
- Pre-installation for child seat mounting system "ISOFIX" (rear)
- Central locking with remote control (and interior switches)

### Extra equipment

- Package: Easy-Access (Keyless locking and starting system (Keyless Open & Start) - Sensor-controlled tailgate, electric - Loading sill protection, stainless steel)
- Package: Ultimate (18" high-gloss black alloy wheels (multi-spoke), 8.5 J x 18 with 245/45 R 18 tires - Brushed Ice trim strip - Solar Protect heat-insulating glazing, heavily tinted, in the rear - GS Line interior equipment: GS Line sport leather steering wheel, heated; aluminum sport pedals; black headliner)
- Radio: Multimedia Navi Pro with 8" color touchscreen display (voice control for audio, telephone and navigation, USB port, Bluetooth audio streaming, navigation system with SD card storage, connected navigation services, predictive navigation, online map updates, real-time traffic information, 8" driver information display, steering wheel controls, Apple CarPlay and Android Auto)
- Package: Innovations 2 (automatic transmission) (Head-up display - Adaptive cruise control (Generation 3), Stop & Go function - Forward collision warning with pedestrian detection and automatic emergency braking, active from 4 km/h, range 150 m. In case of risk of collision, the braking system is prepared and, if necessary, emergency braking / automatic emergency braking is initiated - Traffic sign recognition)
- Package: Winter 1 (Heated seats, multi-stage, driver and front passenger - Heated leather steering wheel - Heated ThermaTec windshield)
- Paint finish: Metallic
- Swiveling trailer hitch (including trailer stability program)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Misc. | Main inspection - No evidence - No deduction |
| 2 | Equipment | Tirefit filler - Expired - Replace |
| 3 | Side panel - rear right side | Side panel - dent(s) - Smooth repair work |
| 4 | Wheel / tyres | Alloy rim - front right side - Scratch(es) - Loss in value |
| 5 | Side panel - rear left side | Side panel - Deformed - Repair and paint |
| 6 | Door - rear left side | Door - Deformed - Repair and paint |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Roof | Roof (Steinschlag) - dent(s) - No deduction |
| 2 | Boot lid / rear door | Boot lid - dent(s) - No deduction |
| 3 | Bonnet | Bonnet - Stone chips - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Missing parts

**Description**

Equipment - Towing eye (Abdeckkappe Abschleppöse vorne)

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Aufgrund des niedrigen Kraftstofftankinhalts und der zugehörigen Warnmeldung im Kombiinstrument ist das Ablesen des Ölzustands bzw. der Service Restlaufzeit zum Zeitpunkt der Besichtigung nicht durchführbar. Mehrkosten sind möglich.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN



**Figure 12:** Mounted tyres





**Figure 13:** Documents





**Figure 14:** Documents





**Figure 15:** Documents



**Figure 16:** Additional tyres





**Figure 17:** Navigation




**Figure 18:** Misc.



**Figure 19:** Misc.




**Figure 20:** Misc.



**Figure 21:** Misc.



**Figure 22:** Misc.



**Figure 23:** Misc.



**Figure 24:** Misc.




**Figure 25:** Misc.




**Figure 26:** Misc.




**Figure 27:** Misc.




**Damage 2:** Equipment: Tirefit filler - Expired - Replace



**Damage 3:** Side panel - rear right side: Side panel - dent(s) - Smooth repair work



**Damage 3:** Side panel - rear right side: Side panel - dent(s) - Smooth repair work



**Damage 4:** Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



**Damage 4:** Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



**Damage 4:** Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



**Damage 4:** Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



**Damage 5:** Side panel - rear left side: Side panel - Deformed - Repair and paint



**Damage 5:** Side panel - rear left side: Side panel - Deformed - Repair and paint

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel




**Damage 6:** Door - rear left side: Door - Deformed - Repair and paint



**Damage 6:** Door - rear left side: Door - Deformed - Repair and paint



**Wear and tear 3:** Bonnet: Bonnet - Stone chips - No deduction



**Wear and tear 3:** Bonnet: Bonnet - Stone chips - No deduction



**Missing part 1:** Equipment: Towing eye (Abdeckkappe Abschleppöse vorne) - Missing - Replace