

MACDAM

Tesla Model Y '21 BEV

Vehicle information


Make:	Tesla	License:	
Gearbox:	Automatic	Body color:	
Model:	Model Y '21 BEV	VIN:	LRWYGCEK5MC150441
Fuel type:	Electric	Power:	0 kW
Version:	Model Y 75kWh 4WD Long Range	First registration	24/12/2021
Mileage:	186088 km	N° of doors:	

Damage summary

Front	3
Left	5
Rear	5
Right	6

Commercial pictures






Options according to the inspector				
Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser
Hook	Yes	Panoramic roof	Yes	Radio multimedia
Telephone equipment	Yes			

Damages				
Alloy rim FL Scratch(es) Repair and paint (complete) Left	 			
Alloy rim FR Scratch(es) Repair and paint (complete) Right	 			
Alloy rim RR Scratch(es) Repair and paint (complete) Right	 			
Bonnet Stone chip(s) Repair and paint (complete) Front	 			
Bumper F Scratch(es) Repair and paint (complete) Front	 			

Bumper R
Scratch(es)
Repair and paint (complete)
Rear




Bumper RM
Scratch(es)
Replace
Rear



Charging cable (normal)
Missing
Replace
Rear



Door FL
Scratch(es)
Repair and paint (complete)
Left



Door FR
Scratch(es)
Repair and paint (complete)
Right



Door RL
Scratch(es)
Repair and paint (complete)
Left



Door RR
Scratch(es)
Repair and paint (complete)
Right



Rear spoiler
Scratch(es)
Repair and paint (complete)
Rear



Tailgate / Boot
Scratch(es)
Repair and paint (complete)
Rear



Windscreen
Crack
Replace
Front



Wing RL
Scratch(es)
Repair and paint (complete)
Left



Wing trim RL
Scratch(es)
Replace
Left



Wing trim RR
Scratch(es)
Replace
Right



Wing trim RR
Scratch(es)
Replace
Right



Tyres

Front Left

Winter

255/45/19/101/W

Bridgestone

3.3 mm

Front Right

Winter

255/45/19/101/W

Bridgestone

6.2 mm

Rear Left

Winter

255/45/19/101/W

Bridgestone

2.3 mm

Rear Right

Winter

255/45/19/101/W

Bridgestone

0.9 mm

Checks		
CO2 Emission	0	Digital maintenance Yes
GPS storage	Yes	Luggage cover Yes
Number head rests	1	Number of charging cables (rapid charge) 1
Number of keys total	1	Service book N/A
User's manual	Yes	

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.