TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

# Expertise

Protocol number: 48405720
Order No. / Reference: 27245153
Inspection date: 30 Oct 2026

| Manufacturer: Mercedes-Benz | Model: Vito 119 CDI 4MATIC Tourer Extralang Aut. PRO |
|---|---|
| VIN: W1V44770514101906 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Mercedes-Benz Vito 119 CDI 4MATIC Tourer Extralang Aut. PRO | |
| **Vehicle Identification number** | W1V44770514101906 |
| **Mileage** (Read) | 113,297 km |
| **First registration** | 27 Sept 2022 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** | 09/2027 |
| (Report on hand) | |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,950 ccm / 4 |
| **Power** | 140 kW |
| **Gearbox / Number of gears** | Automatic / 9 |
| **Type of drive** | All-wheel drive |
| **Type of vehicle** | Van |
| **Colour / colour code** | Obsidian black metallic |
| **Doors / Seats** | 4 / 8 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Black-Grey |

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 257 Tag(e) |
| **Last service on / at** | 07/2025 at 86,495 km | | |
| **Key is / should be** | 1 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GH892421 |
| **Previous damage / Accident** | Detectable | **Repainting** | Detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 2222 / ABQ 00838 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 3,100 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 225/55 R17 107T | Summer tyres on Light alloy | Pirelli | 7mm / 7mm |
| 2) | 225/55 R17 107T | Summer tyres on Light alloy | Pirelli | 7mm / 7mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 225/55 R17 101V | Winter tyres on Steel | Pirelli | 7mm / 7mm |
| 2) | 225/55 R17 101V | Winter tyres on Steel | Pirelli | 7mm / 7mm |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- ABS, ESP, ASR, EBV, BAS (Anti-lock Braking System (ABS) - Electronic Stability Program (ESP) - Traction Control (ASR) - Electronic Brakeforce Distribution (EBV) - Brake Assist (BAS))
- Airbag: Thorax-pelvis-sidebag for driver
- Airbag: Windowbag for driver and front passenger
- ATTENTION ASSIST (ATTENTION ASSIST can assist the driver on long, monotonous journeys by monitoring attention. If signs of fatigue or increasing inattention are detected, it suggests a break.)
- Outdoor temperature display
- Battery: fleece battery 12 V / 92 Ah
- third brake light
- Front cupholder
- Diesel particulate filter and SCR
- Entry grab handle for the cargo area sliding door
- Window in rear door/tailgate (with wiper/washer system)
- Left/right window in SW/ Cargo area sliding door
- Front right window fixed in SW/ cargo area sliding door
- Parking brake
- Generator 14 V / 200 A
- Transmission: 9G-TRONIC
- Seatbelt warning device for front passenger seat
- Seatbelt warning device for driver's seat
- Grab handle for entry of driver and passenger
- Grab handle in the rear
- Lockable glove box
- Main tank 57 liters
- Boot lid
- Interior lights in the rear
- Interior trim, high-end finish
- Instrument cluster with pixel matrix display (operated via the buttons on the multifunction steering wheel - round instruments for speedometer and tachometer or fuel level and coolant temperature - high-quality pixel matrix display in white and red between the large round instruments)
- Mercedes-Benz emergency call system
- Package: Aerodynamics
- Breakdown management
- Radio: Radio Generation 2
- Rain sensor
- Tires: 225/55R17
- Tires: Premium protection tires (3 years)
- Tire pressure monitoring (on front and rear axles (wireless))
- Sliding door: Active stop
- Crosswind Assist
- Seats: 3-seater bench in the 1st row of the passenger compartment (with individual seat elements - folding outer seat)
- Seats: Rear seat mounting with quick-release fasteners, 2 rows of seats
- Cruise control
- Pre-installation for Remote Services Plus
- Screw-in towing eye front/rear
- Passenger side airbag
- Driver's side airbag
- Airbag: Thorax airbag - Pelvis side airbag for front passenger
- Permanent all-wheel drive
- Upgrading/downgrading (upgrading to 3.2 t GVW)
- Increased load capacity to 3,100 kg
- Attention Assistant
- Electrically adjustable and heated exterior mirrors, left and right
- Hill start assist
- Brake lights, adaptive
- Roof cladding
- Electronic tachometer
- Driving light assistant (automatically switching on driving lights)
- Front left window fixed in SW/ cargo area sliding door
- Electric window regulator driver/passenger (with anti-pinch protection, quick lowering and raising)
- Generator management (Generator management helps reduce fuel consumption and CO2 emissions. The generator is switched off and the vehicle's electrical system is powered by the battery when it is sufficiently charged. This relieves the engine of the burden of charging the battery, for example, during acceleration. - When braking and during coasting downhill, the generator is switched on and the vehicle's kinetic energy is recuperated to charge the battery.)
- Interior mirror (rearview mirror)
- Child safety locks on doors in the passenger compartment
- Communication module (LTE) for digital services
- Headrests (2), front
- Plastic floor TPO passenger compartment
- Steering wheel adjustable for tilt and height
- Headlight range control
- Multifunction steering wheel (with trip computer)
- Package: BlueEFFICIENCY (Efficiency Package)
- Upholstery: Caluma fabric, black
- Radio: Pre-installation for digital radio DAB (with 2-way speakers at the front)
- Tires: Tires without specified make
- Tires: Summer tires
- Wheels: Steel rims 6.5 J x 17
- Headlights: halogen technology
- Sliding door on the right, cargo/passenger compartment
- electromechanical power steering
- Seats: 3-seater bench, 2nd row
- Seats: Adjustable passenger seat
- Seats: Driver's seat
- Start-stop function
- 12V socket
- First aid kit
- Warm air duct to the passenger compartment
- Windshield washer fluid level warning light

- Warning triangle
- ASSYST maintenance interval indicator
- Heat-insulating glass
- Auxiliary heater, electric
- Immobiliser
- Central locking with radio remote control

### Extra equipment

- Tinted rear windows, black glass
- Double cup holder in the center of the cockpit
- Large fuel tank, approx. 70 liters
- Paint finish: Metallic
- LED Intelligent Light System (ILS) (including dynamic cornering lights, country road and motorway lights, turning lights, dynamic headlight range control, automatic high beam assist, LED taillights)
- Package: Chrome Interior Package (chrome trim: in instrument panel and door trim, air vents, climate control elements, door control panel surround, center console in gloss black)
- Package: DRIVER COMFORT (Heat-insulating glass - Comfort driver's seat - Heated driver's seat - Leather steering wheel and leather gearshift lever - Multifunction steering wheel with trip computer - Instrument cluster with pixel matrix display - Active parking assistant - Comfort opening and closing with IR remote control - Rain sensor - Driving light assistant - Comfort overhead control unit)
- Radio accessories: 2-way speakers front + rear.
- Wheels: Alloy wheels 7 J x 17, 5-twin-spoke design (aero wheel, diamond-cut finish)
- Seats: Passenger compartment 2nd row, 3-seater bench / Comfort (outer seat foldable)
- Seats: Comfort driver's seat
- Sun visor, driver/passenger side, illuminated mirror
- Roof rails (instead of C-rails)
- Interior and ambient lighting (comfort roof control unit, - tailgate approach lighting - exit lights - front footwell lighting - lighting in rear grab handle with reading light)
- Center console with storage compartment
- Navigation accessories: Live Traffic Information
- Package: CABIN COMFORT for Tourer (THERMOTRONIC automatic climate control - TEMPMATIC semi-automatic air conditioning in the rear - auxiliary water heater - remote control for auxiliary heater - "Audio 10" radio or optional Audio 15 - 2-way speakers front and rear - comfort overhead control unit - multifunction steering wheel with trip computer - instrument cluster with pixel matrix display - comfort opening and closing with IR remote control - driving light assistant - heat-insulating glass all around)
- Parktronic (with optical and acoustic warning signals, PARKTRONIC assists the driver when parking and maneuvering)
- Radio/Navigation: Multimedia radio and navigation system "Audio 40"
- Seats: 4-seat rail system (with quick-release mechanism)
- Seats: Passenger compartment 1st row, 3-seater bench / Comfort (outer seat foldable)
- Seats: Comfort passenger seat
- Seat heating on passenger side
- Bumpers painted in body color

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Instrument panel | Indicator light (Reifendruckkontrolle) - Non-operational - Perform diagnosis |
| 2 | Door - front left side | Door edge - Scratch(es) - Smart repair |
| 3 | Mudguard - left side | Mudguard - left side - Scratch(es) - Smart repair |
| 4 | Front bumper | Front bumper (Unterhalb) - Scratch(es) - Paint |

## Missing parts

**Description**

Equipment - Vehicle key

## Previous damages

| No. | Previous damage | Extent of damage (Net) |
|---|---|---|
| 1 | Rear, Provided by user / customer, from 26 Aug 2026 | 1.568,29 € |
| 2 | Side right, Provided by user / customer, from 21 Jun 2023 | 4.663,18 € |

## Repainting

| No. | Repainting |
|---|---|
| 1 | Boot lid / rear door, Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent |

## Paint coat thickness measurement

| | | | |
|---|---|---|---|
| Boot lid / rear door | 474 µm | Side panel - rear right side | 313 µm |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)




**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area




**Figure 11:** VIN




**Figure 12:** Mounted tyres




**Figure 13:** Documents





**Figure 14:** Documents





**Figure 15:** Documents



**Figure 16:** Additional tyres




**Figure 17:** Navigation



**Figure 18:** Misc.





**Figure 19:** Misc.




**Figure 20:** Misc.



**Figure 21:** Misc.




**Figure 22:** Misc.




**Figure 23:** Misc.



**Figure 24:** Misc.



**Figure 25:** Misc.




**Figure 26:** Misc.



**Figure 27:** Misc.



**Figure 28:** Misc.



**Figure 29:** Misc.




**Figure 30:** Misc.




**Damage 1:** Instrument panel: Indicator light (Reifendruckkontrolle) - Non-operational - Perform diagnosis




**Damage 2:** Door - front left side: Door edge - Scratch(es) - Smart repair



**Damage 2:** Door - front left side: Door edge - Scratch(es) - Smart repair



**Damage 2:** Door - front left side: Door edge - Scratch(es) - Smart repair




**Damage 3:** Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



**Damage 3:** Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



**Damage 3:** Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



**Damage 4:** Front bumper: Front bumper (Unterhalb) - Scratch(es) - Paint



**Damage 4:** Front bumper: Front bumper (Unterhalb) - Scratch(es) - Paint





**Missing part 1:** Equipment: Vehicle key - Missing - Replace



**Repainting 1:** Boot lid / rear door, Side panel - rear right side




**Repainting 1:** Boot lid / rear door, Side panel - rear right side




**Repainting 1:** Boot lid / rear door, Side panel - rear right side




**Repainting 1:** Boot lid / rear door, Side panel - rear right side