TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48443633
Order No. / Reference: 27198658
Inspection date: 28 Oct 2026

Manufacturer: Seat	Model: Arona 1.0 TSI OPF Xperience
VIN: VSSZZZKJZNR046573	





Vehicle details

Manufacturer / Type / Model / Equipment	
Seat Arona 1.0 TSI OPF Xperience	
Vehicle Identification number	VSSZZZKJZNR046573
Mileage (Read)	146,917 km
First registration	7 Jul 2022
Number of holders	1
Next periodical technical inspection (Report on hand)	10/2027
Fuel type	Petrol
Engine displacement / Cylinder	999 ccm / 3
Power	70 kW
Gearbox / Number of gears	Manual / 5
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Dark Camouflage Metallic / Midnight Schwarz
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Grey-Black
readiness to drive	Not roadworthy / moveable

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	4,400 km
Last service on / at	10/2025 at 121,314 km		
Key is / should be	1 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG161175
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	7593 / ANP 00681		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,710 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 95V	All-season tyres on Light alloy	Pirelli	5mm / 5mm
2)	205/55 R17 95V	All-season tyres on Light alloy	Pirelli	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 12V socket at the front
- Storage pocket on the back of the front seats
- Ambient lighting (two-tone) in the front doors
- Exterior mirror housings in body color
- Lighting in the storage compartment of the center console and front footwell
- On-board computer
- Black headliner
- Tachometer
- Three-point automatic seat belts, front and rear
- Electronic Stability Control (ESC)
- luggage compartment cover
- Speed limiter
- Transmission: 5-speed transmission
- LED taillights
- Rear window wiper/washer system with intermittent function
- illuminated trunk
- Radiator grille in chrome diamond design
- LED technology for headlights and daytime running lights
- Steering wheel: Steering column with height and reach adjustment
- light sensor
- Multi-collision brake
- Emergency call service
- Package: Storage package (front center armrest - storage compartment under the passenger seat - owner's manual holder under the driver's seat - lashing eyes in the luggage compartment)
- Pollen filter
- Upholstery: Cloth
- Radio: Digital radio reception DAB+
- Wheels: 4 alloy wheels "Dynamic 20/1" (6.5J x 17", tires 205/55 R 17)
- Keyless locking and starting system "Kessy"
- Seats: Passenger seat with height adjustment
- Seats: Rear seat backrest split 1/3 to 2/3, foldable
- Start-stop technology
- Door handles in car color
- Front Assist area monitoring system with City Emergency Braking function and pedestrian detection
- Central locking with remote control and comfort closing
- Storage compartment in the front doors
- Airbags
- Electrically adjustable exterior mirrors
- Outdoor temperature display
- Hill Start Assist (HHC)
- Turn signals in the wing mirrors
- Chrome trim on the side windows
- Roof rails and design element in the C-pillar in chrome colors
- Third brake light integrated into the rear spoiler
- Electric window regulator with anti-pinch protection and one-touch function
- Cruise control
- Cup holders, 2 front
- Heated rear window with timer function
- ISOFIX child seat restraint system
- Child safety locks on the rear doors
- Height-adjustable headrests, front and rear
- Paint finish: Vehicle roof painted in Midnight Black Metallic, Magnetic Grey Metallic or White
- Steering wheel: Multifunction steering wheel in nappa leather
- Air vents in the dashboard
- Fatigue detection
- Otto particulate filter
- Package: Climate Comfort Package (Heated and electrically folding exterior mirrors - Automatic coming home and leaving home function - Climatronic with electronic temperature control, separate temperature control for driver and front passenger - Automatically dimming interior mirror - Rain sensor)
- Tire pressure monitoring system
- Wheels: Tyre fit
- Front windshield wipers with intermittent function
- Electromechanical power steering
- Seats: Driver's seat with height adjustment
- Lane departure warning system
- Bumpers in body color
- Ultrasonic rear parking aid
- Electronic immobilizer
- thermal insulation glazing

Extra equipment

- Deletion of the colored air vents in the dashboard (air vents in neutral, unlit grey)
- Package: Winter (passenger seat with height adjustment - heated front seats)
- Paint finish: Metallic with vehicle roof in a different color
- Navigation: Navigation data for Europe including MAPCARE (on SD card) for navigation systems
- Package: Xperience Pro (9.2" media system with navigation system and Full Link (Android Auto and Apple CarPlay including Full Link Wireless) - full LED headlights - wireless charger)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Wing mirror - left side	Cap - Stone chips - Smart repair
2	Door - front right side	Door handle - outside - Scratch(es) - Smart repair
3	Steering system	Steering system - Play - Perform diagnosis
4	Instrument panel	Indicator light (Reifendruckkontrolle aktiv) - on - Perform diagnosis
5	Trim / covers	Cowl (Windschutzscheibe links) - Scratch(es) - Replace
6	Door - rear left side	Door - dent(s) - Smooth repair work
7	Seat - front	armrests (Abdeckung hinten, materialabtrag) - Scratched - Replace
8	Mudguard - right side	Wheel well extension - Scratched - Replace
9	Roof	Roof rail - left side - dent(s) - Smooth repair work
10	Roof	Roof rail - right side - dent(s) - Smooth repair work
11	Side panel - rear right side	Sill - Scratch(es) - Smart repair
12	Wheel / tyres	Tyre - front right side (Flanke, verkratzt) - Damaged - Replace
13	Wheel / tyres	Tyre - rear right side (Flanke, verkratzt) - Damaged - Replace
14	Side panel - rear left side	Sill - Dent / paintcoat damage - Smart repair
15	Trim / covers	Boot lid - interior trim - Scratched - Replace
16	Wheel / tyres	Alloy rim - front right side (Materialabtrag) - Scratched - Loss in value
17	Wing mirror - right side	Cap (Soll Schwarz sein) - Unprofessionally repaired - Replace
18	Rear bumper	Rear bumper - Scratched - Paint
19	Door - front left side	Door - Scratch(es) - Paint
20	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
21	Bonnet	Bonnet (Kratzer) - Deformed - Repair and paint

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	Door - rear left side	Door (Keine Kratzer) - Abrasion - No deduction
3	Roof	Roof - dent(s) - No deduction
4	Rear bumper	Spoiler - Scratch(es) - No deduction
5	Interior	Interior - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Vehicle key with remote control

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 16 Jan 2024	1.276,80 €
2	Side right, Provided by user / customer, from 11 Sept 2023	2.970,06 €

Repainting

No.	Repainting
1	Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent
2	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - right side	158 µm	Door - front right side	161 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Das Fahrzeug befand sich zum Besichtigungszeitpunkt in beschädigtem, nicht demontiertem Zustand. Schadenausweitung möglich, Zusatzkosten können entstehen



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Damage 1: Wing mirror - left side: Cap - Stone chips - Smart repair



Damage 1: Wing mirror - left side: Cap - Stone chips - Smart repair



Damage 2: Door - front right side: Door handle - outside - Scratch(es) - Smart repair




Damage 2: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 4: Instrument panel: Indicator light (Reifendruckkontrolle aktiv) - on - Perform diagnosis




Damage 5: Trim / covers: Cowl (Windschutzscheibe links) - Scratch(es) - Replace




Damage 5: Trim / covers: Cowl (Windschutzscheibe links) - Scratch(es) - Replace



Damage 6: Door - rear left side: Door - dent(s) - Smooth repair work



Damage 6: Door - rear left side: Door - dent(s) - Smooth repair work




Damage 7: Seat - front: armrests (Abdeckung hinten, materialabtrag) - Scratched - Replace



Damage 7: Seat - front: armrests (Abdeckung hinten, materialabtrag) - Scratched - Replace



Damage 7: Seat - front: armrests (Abdeckung hinten, materialabtrag) - Scratched - Replace



Damage 8: Mudguard - right side: Wheel well extension - Scratched - Replace



Damage 8: Mudguard - right side: Wheel well extension - Scratched - Replace



Damage 9: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 9: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 10: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage 10: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage 10: Roof: Roof rail - right side - dent(s) - Smooth repair work




Damage 10: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage 11: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 11: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 12: Wheel / tyres: Tyre - front right side (Flanke, verkratzt) - Damaged - Replace



Damage 12: Wheel / tyres: Tyre - front right side (Flanke, verkratzt) - Damaged - Replace



Damage 12: Wheel / tyres: Tyre - front right side (Flanke, verkratzt) - Damaged - Replace



Damage 13: Wheel / tyres: Tyre - rear right side (Flanke, verkratzt) - Damaged - Replace



Damage 13: Wheel / tyres: Tyre - rear right side (Flanke, verkratzt) - Damaged - Replace



Damage 13: Wheel / tyres: Tyre - rear right side (Flanke, verkratzt) - Damaged - Replace



Damage 14: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair




Damage 14: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 14: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 14: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 14: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 15: Trim / covers: Boot lid - interior trim - Scratched - Replace



Damage 15: Trim / covers: Boot lid - interior trim - Scratched - Replace



Damage 15: Trim / covers: Boot lid - interior trim - Scratched - Replace



Damage 16: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Loss in value




Damage 16: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Loss in value




Damage 16: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Loss in value



Damage 16: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Loss in value



Damage 17: Wing mirror - right side: Cap (Soll Schwarz sein) - Unprofessionally repaired - Replace



Damage 17: Wing mirror - right side: Cap (Soll Schwarz sein) - Unprofessionally repaired - Replace




Damage 17: Wing mirror - right side: Cap (Soll Schwarz sein) - Unprofessionally repaired - Replace



Damage 17: Wing mirror - right side: Cap (Soll Schwarz sein) - Unprofessionally repaired - Replace



Damage 17: Wing mirror - right side: Cap (Soll Schwarz sein) - Unprofessionally repaired - Replace



Damage 18: Rear bumper: Rear bumper - Scratched - Paint



Damage 18: Rear bumper: Rear bumper - Scratched - Paint



Damage 18: Rear bumper: Rear bumper - Scratched - Paint



Damage 18: Rear bumper: Rear bumper - Scratched - Paint




Damage 18: Rear bumper: Rear bumper - Scratched - Paint



Damage 18: Rear bumper: Rear bumper - Scratched - Paint




Damage 18: Rear bumper: Rear bumper - Scratched - Paint




Damage 19: Door - front left side: Door - Scratch(es) - Paint




Damage 19: Door - front left side: Door - Scratch(es) - Paint



Damage 19: Door - front left side: Door - Scratch(es) - Paint



Damage 19: Door - front left side: Door - Scratch(es) - Paint




Damage 20: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 20: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 20: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 20: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 21: Bonnet: Bonnet (Kratzer) - Deformed - Repair and paint




Damage 21: Bonnet: Bonnet (Kratzer) - Deformed - Repair and paint




Damage 21: Bonnet: Bonnet (Kratzer) - Deformed - Repair and paint




Damage 21: Bonnet: Bonnet (Kratzer) - Deformed - Repair and paint



Damage 21: Bonnet: Bonnet (Kratzer) - Deformed - Repair and paint



Damage 21: Bonnet: Bonnet (Kratzer) - Deformed - Repair and paint



Damage 21: Bonnet: Bonnet (Kratzer) - Deformed - Repair and paint



Damage 21: Bonnet: Bonnet (Kratzer) - Deformed - Repair and paint




Wear and tear 2: Door - rear left side: Door (Keine Kratzer) - Abrasion - No deduction

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Wear and tear 2: Door - rear left side: Door (Keine Kratzer) - Abrasion - No deduction



Missing part 1: Equipment: Vehicle key with remote control - Missing - Replace



Repainting 1: Mudguard - right side



Repainting 2: Door - front right side