MACADAM








## BMW 5 Reeks (MKL): 2CLE275

| | | | |
|---|---|---|---|
| Vinnumber: | **WBA31CG020CL14455** | Versionname: | **530e Touring (G31) 2.0i 272pk/cv 5p xDrive Aut.** |
| First Registrationdate: | **1/09/2022** | Fiscalpower: | |
| Expertise Mileage: | **76193** | Power Kw: | **120** |
| Bodytype: | | Type of rims (mounted) | **Aluminium** |
| Gearbox: | **Automatic** | | |
| Transmission: | | | |
| Fueltype: | **Plug-in Hybrid Petrol** | | |
| Maintenance | **OK** | | |
| Battery functioning | **Yes** | | |
| Type of rims (mounted) | **Aluminium** | | |
| Certificate of Conformity | **Yes** | | |
| Category | **Passenger Car** | | |
| Registration Certificate Car (BE) | **Yes** | | |

## Options

| | | | |
|---|---|---|---|
| Number of keys total | **2** | Luggage cover | |
| GPS | | Type of Tow bar | **No Tow bar** |
| Type of Maintenance book | **Digital maintenance** | | |
| Type of GPS storage | **HD** | | |

## Tyres

| | | | | |
|---|---|---|---|---|
| Summer tyres: | **245/45/18/100 Y** | | | |
| | Fr.L. | **Goodyear: 2 mm** | Fr.R. | **Goodyear: 2 mm** |
| | Re.L. | **Goodyear: 2 mm** | Re.R. | **Goodyear: 2 mm** |

| | |
|---|---|
| Tyre profile depth FL | **2.0** |
| Tyre profile depth FR | **2.0** |
| Tyre profile depth RL | **2.0** |
| Tyre profile depth RR | **2.0** |
| Tyre size FL | **245/45 R 18 100 Y** |
| Tyre size FR | **245/45 R 18 100 Y** |
| Tyre size RL | **245/45 R 18 100 Y** |
| Tyre size RR | **245/45 R 18 100 Y** |
| Tyre type FL | **Summer** |
| Tyre type FR | **Summer** |
| Tyre type RL | **Summer** |
| Tyre type RR | **Summer** |
| Tyre make FL | **259** |
| Tyre make FR | **259** |
| Tyre make RL | **259** |
| Tyre make RR | **259** |

## Assistance equipment

| | |
|---|---|
| Number of charging cables (normal) | **0** |
| Number of charging cables (rapid charge) | **1** |

### Ignition key, Worn, Acceptable




### Bonnet, Chemical polution, Acceptable





Bumper F, Scratch(es), Acceptable








Door RL, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable






Charging cable (normal), Missing, Check



Tyre FR, Tear, Replace




Wing RR, Dent(s), Acceptable




Door RR, Bad repair, Repair and paint (complete)






Bodywork, Paint measurement, Check



# Onderhoudshistorie van: WBA31CG020CL14455

ALPHABET

| | |
|---|---|
| **Kenteken** | 2CLE275 |
| **Merk Model** | BMW 530e Touring (G31) 2.0i 272pk/cv 5p xDrive Aut. |
| **Brandstofsoort** | Benzine |
| **Datum deel1** | 9/1/22 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving | Bewerking |
|---|---|---|---|
| 9/16/25 | 57,493 | batterij | Vervangen |
| 9/16/25 | 57,493 | BMW/MINI service standaard omvang | Uitvoeren |
| 9/16/25 | 57,493 | BMW/MINI service voertuig-check | Uitvoeren |
| 9/16/25 | 57,493 | bougie | Vervangen |
| 9/16/25 | 57,493 | klein materiaal | |
| 9/16/25 | 57,493 | ruitenwisserrubber vooraan | Vervangen |
| 9/16/25 | 57,493 | service luchtfilter | Uitvoeren |
| 9/16/25 | 57,493 | service microfilter | Uitvoeren |
| 9/16/25 | 57,493 | service motorolie | Uitvoeren |
| 7/17/25 | 52,524 | BMW/MINI service standaard omvang | Uitvoeren |
| 7/17/25 | 52,524 | controle niveaus | Uitvoeren |
| 7/17/25 | 52,524 | remvloeistof | Vervangen |
| 2/7/25 | 43,484 | controle niveaus | Uitvoeren |
| 4/11/24 | 29,129 | batterij | Vervangen |
| 4/11/24 | 29,129 | BMW/MINI service standaard omvang | Uitvoeren |
| 4/11/24 | 29,129 | klein materiaal | |
| 4/11/24 | 29,129 | service microfilter | Uitvoeren |
| 4/11/24 | 29,129 | service motorolie | Uitvoeren |
| 1/10/24 | 23,159 | controle niveaus | Uitvoeren |
| 8/2/23 | 13,506 | controle niveaus | Uitvoeren |