MACADAM

BYD Atto 3 '22 BEV

Vehicle information

Make:**BYD**
License:**R808XP**
Gearbox:**Automatic**
Body color:
Model:**Atto 3 '22 BEV**
VIN:**LGXCE4CB1N2065246**
Fuel type:**Electric**
Power:**150 kW**
Version:**ETP3 # ATTO 3 # 60,48 kWh**
First registration**15/12/2022**
Mileage:**138100 km**
N° of doors:

Damage summary

Front	2
Interior	1
Left	3
Rear	2
Right	3

Commercial pictures










R-808-XP










08:52
km/h
0
kW
121
km
Standard OK NORMAL P
000 138100 km





BYD AUTO CO.,LTD.
e9*2018/858*11147*00
LGXCE4CB1N2065246
2 160 kg
- kg
1 - 1 070 kg
2 - 1 110 kg









AVM
Instellingen
P

Zoeken naar...
Nijkerk, Gelderland









Options according to the inspector

Central consol F**Yes**
GPS**Yes**
Headlights Xenon/LED/Laser**Yes**
Panoramic roof**Yes**
Radio multimedia**Yes**
Rear view camera**Yes**
Sun Roof electric**Yes**
Telephone equipment**Yes**


Damages

Alloy rim FR
Scratch(es)
Repair and paint (complete)
Right





Bonnet
Chemical polution
Repair and paint (complete)
Front





Boot lid covering R
Scratch(es)
Smart repair
Rear






Bumper moulding F
Scratch(es)
Replace and paint
Front





Door FL
Dent(s) and scratch(es)
Repair and paint (complete)
Left










Door FR
Dent(s) and scratch(es)
Repair and paint (complete)
Right








Door RL
Dent(s) and scratch(es)
Repair and paint (complete)
Left












Rear spoiler
Dent(s)
Repair and paint (complete)
Rear







Roof pillar R
Dent(s)
Repair and paint (complete)
Right







Steering wheel
Worn
Replace
Interior





Wing RL
Scratch(es)
Repair and paint (complete)
Left





Tyres

Location	Type	Rim	Measures	Make	Depth
Front Left					
Summer					
235/50/18/101/V					
Goodyear					
1.8 mm					
Front Right					
Summer					
235/50/18/101/V					
Goodyear					
1.8 mm					
Rear Left					
Summer					
235/50/18/101/V					
Continental					
4.5 mm					
Rear Right					
Summer					
235/50/18/101/V					
Continental					
4.0 mm					

Checks

CO2 Emission	**0**
Digital maintenance	**Yes**
Luggage cover	**Yes**
Number head rests	**3**
Number of charging cables (rapid charge)	**1**
Number of keys total	**2**
Reset to factory settings	**Yes, vehicle is reset to factory settings**
Service book	**N/A**
User's manual	**N/A**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.