TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48587171
Order No. / Reference: 27156705
Inspection date: 10 Nov 2026

Manufacturer: Skoda	Model: Octavia Combi 2.0 TDI DSG RS
VIN: TMBJK8NXXRY043195	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG RS	
Vehicle Identification number	TMBJK8NXXRY043195
Mileage (Read)	161,734 km
First registration	20 Sept 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	09/2028
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	147 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Black Magic Pearlescent (F9R)
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	528 Tag(e)
Last service on / at	09/2026 at 159,874 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT130164
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AVI 00125		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,005 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R19 91Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	225/45 R19 91Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 95H	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	205/55 R17 95H	Winter tyres on Light alloy	Pirelli	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- Storage compartment in the luggage compartment
- Airbag, driver and passenger
- Airbag, head airbags
- Airbag: Center airbag front
- Anti-lock braking system (ABS)
- Automatically dimming exterior mirror (driver's side)
- Exterior mirrors painted black, door handles in body color
- Heated windshield washer nozzles including 5l washer fluid reservoir
- roof grab handles four
- AERO roof rails in black
- Diesel particulate filter
- Tachometer
- Ice scraper in the fuel filler flap
- Electronic transverse differential lock (XDS+)
- Driving profile selection
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Front and rear footwell lighting
- Removable luggage roller blind
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec: Start/stop system including brake energy recuperation
- Interior: Design Selection RS
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Climatronic air conditioning (2-zone)
- Paint finish: Special paint finish, solid color
- LED matrix headlights and dynamic high beam assist (AFS)
- Steering wheel: Height and reach adjustable leather steering wheel with multifunction buttons including paddle shifters
- Multi-collision brake
- Front and rear parking sensors
- Progressive steering
- Radio accessories: 2 USB ports at the front
- Radio accessories: 8 speakers
- Radio accessories: Bluetooth hands-free system
- Radio accessories: Wireless & Wired SmartLink
- Rain sensor and driving light assistant (Easy Light Assist)
- Tire mobility kit
- Electromechanical power steering
- Safety lights in the front side doors
- Seats: Rear seat backrest split 60:40, foldable
- Seats: Pockets on the backs of the front seats including smartphone pockets
- SKODA Care Connect
- Sound generator in the interior
- Lane keeping assistant (Lane Assist)
- Telephone: Phonebox with inductive charging function (connection via external antenna)
- Glazing: Acoustic glazing in the front side windows and Sunset
- Storage compartments
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Ambient lighting
- Traction control (ASR)
- Electrically adjustable and heated exterior mirrors
- Electrically folding exterior mirrors
- Hill start assist
- Glasses compartment in the headliner
- black headliner
- AERO roof rails in gloss black
- Digital Cockpit Plus
- Third brake light
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Chassis: Sport chassis
- Dynamic High Beam Assist (Dynamic Light Assist)
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection
- Cruise control system (cruise control) including speed limiter
- Heated rear window
- Rear window wiper including windshield washer system
- Interior mirror automatically dimming
- Kessy, keyless entry and start-stop system
- Child safety lock for the rear doors and windows
- Black radiator grille frame
- LED taillights in crystal glass look and animated turn signals
- Remote release of the rear seat backrests in the trunk
- Reading lights two at the front
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Fatigue detection
- Pedals in stainless steel look
- Radio: Infotainment system
- Radio accessories: 2 x USB charging ports in the rear and USB charging port in the rearview mirror
- Radio accessories: Digital radio reception DAB+
- Umbrella and broom compartments in the front doors
- Tire pressure monitoring
- Wheels: 18" Comet alloy wheels, black
- Seat belts
- Seats: Heated front seats
- Seats: Sports seats with integrated headrests in the front and height-adjustable headrests in the rear.
- Seats: Front seats are height-adjustable
- Sun visors with illuminated make-up mirror on driver and passenger side
- 12V socket in the trunk
- Textile floor mats
- Front door sill trims

- Central locking including remote control integrated into the key and EASY Start
- Lashing eyes in the trunk
- Immobiliser

Extra equipment

- Luggage net partition
- Paint finish: Pearl effect
- Package: Infotainment package Business Columbus (Style, RS, Scout) (Columbus navigation system - Infotainment Online (3-year term) - 3 USB charging ports - Head-Up Display - Adaptive Cruise Control (ACC) - Traveller Assist system)
- Package: Parking & Lights (for RS) (cornering lights in the fog lights - reversing camera)
- Comfort opening with electric tailgate operation (The electric tailgate opens and closes at the touch of a button via remote control, a button in the driver's door, and by foot movement at the rear. The integrated comfort opening gives you all the options.)
- Package: Comfort (RS) (3-zone Climatronic - Heated outer rear seats - Heated steering wheel)
- Panoramic sunroof, electric (deletion of the glasses compartment in the headliner)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - No deduction
2	Door - rear right side	Door - dent(s) - Smooth repair work
3	Bonnet	Bonnet - dent(s) - Smooth repair work
4	Door - front left side	Door seal - Damaged - Replace
5	Rear bumper	Spoiler - Dent / paintcoat damage - Smart repair
6	Rear bumper	Rear bumper - Scratched - Smart repair
7	Trim / covers	Brightware / decorative strip - Scratched - Replace
8	Equipment	Vehicle key with remote control - Damaged - Replace

Wear and tear

No.	Component group	Description
1	2nd wheel set	1 alloy rim - Scratched - No deduction
2	Front bumper	Spoiler - Scratch(es) - No deduction
3	Boot lid / rear door	Boot lid - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 28 Nov 2024	1.603,03 €
2	Side - left, Provided by user / customer, from 2 Oct 2025	2.988,31 €

Repainting

No.	Repainting
1	Roof rail - left side, Mudguard - right side, Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof rail - left side	163 µm	Mudguard - right side	214 µm
Side panel - rear left side	387 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Mounted tyres



Figure 13: Mounted tyres



Figure 14: Mounted tyres



Figure 15: Documents



Figure 16: Documents




Figure 17: Documents




Figure 18: Documents




Figure 19: Documents



Figure 20: Additional tyres



Figure 21: Additional tyres



Figure 22: Navigation



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - No deduction



Damage 1: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - No deduction



Damage 2: Door - rear right side: Door - dent(s) - Smooth repair work



Damage 2: Door - rear right side: Door - dent(s) - Smooth repair work



Damage 3: Bonnet: Bonnet - dent(s) - Smooth repair work




Damage 3: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 4: Door - front left side: Door seal - Damaged - Replace



Damage 4: Door - front left side: Door seal - Damaged - Replace



Damage 5: Rear bumper: Spoiler - Dent / paintcoat damage - Smart repair



Damage 5: Rear bumper: Spoiler - Dent / paintcoat damage - Smart repair



Damage 5: Rear bumper: Spoiler - Dent / paintcoat damage - Smart repair



Damage 6: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 6: Rear bumper: Rear bumper - Scratched - Smart repair




Damage 6: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 7: Trim / covers: Brightware / decorative strip - Scratched - Replace



Damage 7: Trim / covers: Brightware / decorative strip - Scratched - Replace



Damage 8: Equipment: Vehicle key with remote control - Damaged - Replace



Wear and tear 1: 2nd wheel set: 1 alloy rim - Scratched - No deduction



Wear and tear 1: 2nd wheel set: 1 alloy rim - Scratched - No deduction




Wear and tear 1: 2nd wheel set: 1 alloy rim - Scratched - No deduction



Wear and tear 2: Front bumper: Spoiler - Scratch(es) - No deduction



Wear and tear 2: Front bumper: Spoiler - Scratch(es) - No deduction



Wear and tear 3: Boot lid / rear door: Boot lid - Scratch(es) - No deduction



Wear and tear 3: Boot lid / rear door: Boot lid - Scratch(es) - No deduction



Repainting 1: Roof rail - left side, Mudguard - right side, Side panel - rear left side



Repainting 1: Roof rail - left side, Mudguard - right side, Side panel - rear left side



Repainting 1: Roof rail - left side, Mudguard - right side, Side panel - rear left side



Repainting 1: Roof rail - left side, Mudguard - right side, Side panel - rear left side



Repainting 1: Roof rail - left side, Mudguard - right side, Side panel - rear left side



Repainting 1: Roof rail - left side, Mudguard - right side, Side panel - rear left side



Roof rail - left side: 163 µm



Mudguard - right side: 214 µm



Side panel - rear left side: 387 µm