TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48502710
Order No. / Reference: 27244469
Inspection date: 3 Nov 2026

Manufacturer: CUPRA	Model: Leon Sportstourer 1.4 e-Hybrid (150 kW System)
VIN: VSSZZZKL5PR019737	





Vehicle details

Manufacturer / Type / Model / Equipment	
CUPRA Leon Sportstourer 1.4 e-Hybrid (150 kW System)	
Vehicle Identification number	VSSZZZKL5PR019737
Mileage (Read)	63,454 km
First registration	25 Nov 2022
Number of holders	1
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,395 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Red metallic (0X1)
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	7,900 km
Last service on / at	07/2026 at 56,296 km		
Key is / should be	1 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GN388536
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	7593 / ART 00030		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,090 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92V	Winter tyres on Light alloy	Dunlop	6mm / 6mm
2)	225/40 R18 92V	Winter tyres on Light alloy	Dunlop	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92Y	Summer tyres on Light alloy	Bridgestone	5mm / 5mm
2)	225/40 R18 92Y	Summer tyres on Light alloy	Bridgestone	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the doors
- Airbag: Passenger airbag deactivation
- Electrically adjustable, folding and heated exterior mirrors (including passenger-side mirror lowering function)
- third brake light
- CUPRA CONNECT (prepared for activation of the security/ assistance and remote access service packages)
- Roof rails in Glossy Black
- Drive Profile CUPRA (Driving profiles can be individually selected - Selected driving profile influences steering assistance and throttle response, chassis control (with DCC), and shift characteristics (with DSG))
- Luggage compartment lighting
- luggage compartment roller blind
- Cruise control system (CCS)
- Illuminated glove compartment
- rear window wiper
- Keyless Go (engine start/stop button)
- Climatronic air conditioning with 3-zone temperature control
- Trim strips on the side windows (outside) in Glossy Black
- Steering wheel: CUPRA sport multifunction steering wheel with shift paddles
- front center armrest
- Navigation system (prepared for activation of the CUPRA CONNECT online infotainment service package - navigation system with 12" display - 3D navigation - voice control - MAPCARE with integrated map for Europe)
- Package: Light and Sight Package (Rain sensor - Automatically dimming interior mirror - Light sensor with automatic headlight control - Automatic Coming Home and Leaving Home function)
- PreCrash Assist (Proactive occupant protection system)
- Radio: Digital radio reception DAB+
- Radio accessories: 6 speakers
- Radio accessories: Connectivity Box in the center console storage compartment including wireless charger
- Tire pressure monitoring system
- Wheels: Tyre fit
- Keyless locking and opening system, Kessy Advanced
- Servotronic
- Seat belts - three-point automatic, front and rear (warning tone for unfastened seat belts)
- Seats: Remote release for folding down the rear seat backrest into the boot
- Seats: Front sports bucket seats in "Sharp Textil"
- Smart Ambient Light (All-around ambient lighting in the interior - CUPRA Welcome Light - Interaction with assistance systems and Drive Profile)
- Start-stop system
- Illuminated door sill trims, front
- Ultrasonic parking aid, rear
- Airbag: Airbag for driver and front passenger (center airbag - side airbag for driver and front passenger - head airbag system, front and rear)
- Exterior mirror caps painted in "Dark Aluminium"
- CUPRA front brake caliper in black
- CUPRA pedals and footrest in silver/black
- Black headliner
- Electronic differential lock (XDS) for front axle
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC) (Anti-lock Braking System (ABS) - Traction Control System (ASR))
- Electric window regulator with anti-pinch protection and one-touch function
- Speed limiter
- Transmission: 6-speed DSG
- Heated rear window
- ISOFIX child seat restraint system, in the 2nd row left and right (incl. top tether anchor points)
- Headrests, 2 front
- Headrests, 3 rear
- Heated steering wheel
- Front/rear reading lights
- Rear center armrest with pass-through option
- Fatigue detection
- Emergency call service (no registration required - service is activated upon delivery)
- Otto particulate filter
- Package: Dynamic (Adaptive Chassis Control DCC - Progressive Steering)
- Package: Full LED package (Full LED headlights - Full LED taillights - Turn signals with LED technology integrated into exterior mirrors - Rear turn signals with dynamic LED technology - Infinite Light; Dynamic LED light strip at the rear - Fog lights with cornering light function in LED technology - Dynamic headlight range control)
- Radio accessories: 2 USB-C ports front / 2 rear (charging function)
- Wheels: Alloy wheels (4) 7.5J x 18" "Performance I Black/Silver", diamond-turned (tires 225/40 R 18)
- Side windows from the 2nd row of seats and rear window are dark tinted.
- Seats: Passenger seat with height adjustment
- Seats: Driver's seat with height adjustment
- Seats: Lumbar support for driver/passenger seat
- Seats: Rear seat backrest asymmetrically split and foldable
- Sun visor on driver and passenger side with make-up mirror and lighting
- Lane departure warning system
- 12V socket in the trunk
- Door trim in leather look
- Front Assist area monitoring system with City Emergency Braking function

- Lashing eyes in the luggage compartment
- Virtual Cockpit (Fully digital instrument cluster with 10.25" TFT display)
- Central locking with remote control
- Electronic immobilizer
- thermal insulation glazing

Extra equipment

- Airbag: Rear side airbag and driver's side knee airbag
- Anti-theft alarm system including interior monitoring, backup horn and tow-away protection
- Paint finish: Exclusive
- Mode 3 Type 2 charging cable, 16 A
- Package: Winter Package (heated front seats)
- Radio accessories: Wireless Full Link Connectivity (Android Auto - Apple CarPlay)
- 230V power outlet in the luggage compartment
- Swiveling towbar (with electric release)
- Luggage partition net
- Electrically operated tailgate (opening & closing) (sensor-controlled opening & closing (virtual pedal))
- Package: Driving Assistance Package M for navigation system (Adaptive Cruise Control up to 210 km/h with predictive speed control PCC - High Beam Assist - Traffic Sign Recognition)
- Vision Plus (reversing camera - parking assist with front parking aid)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
3	Door - rear left side	Door edge - Scratch(es) - Smart repair
4	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value
5	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value
6	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value

Wear and tear

No.	Component group	Description
1	Body	A-pillar - left side - Stone chips - No deduction
2	Wheel / tyres	Wheelset - complete - Scratch(es) - No deduction
3	Front bumper	Spoiler - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Vehicle key

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation




Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Damage 1: Equipment: Tirefit filler - Expired - Replace




Damage 2: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 2: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 3: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 4: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 4: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 5: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 5: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 6: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value




Damage 6: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Wear and tear 3: Front bumper: Spoiler - Scratch(es) - No deduction



Wear and tear 3: Front bumper: Spoiler - Scratch(es) - No deduction