ARVAL
BNP PARIBAS GROUP

2CKM616

INSPECTION REPORT

End of contract


GENERAL INFO

File	324230
License plate	2CKM616
Vehicle identification number	TMBJP7NX2NY097872
Dossier	2021063069
Make	Skoda Oct.Com.1.0 eTec 81kW Cl
Mileage	113916
First registration	25/08/2022
client availability date	15/10/2026
inspectionDate	20/10/2026








CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	



08:01
330 km
Autonomie
0
km/h
L'appareil n'est pas connecté.
118916 km
15.0°C


B
2-CKM-616
BELCAR

DAMAGES

Damages	Type	Acceptable
83	Door Front Left // Painting	N
103	Door Rear Left // Painting	N
801	See External Expertise	N
891	Lettering Removal 15min	N
13	Bumper Front // Painting	N
41	Windshield // Replace	Y
54	Headlight / Front left / Replace	N
66	Wing Front Left // Polish	Y
77	Side View Mirror Left / Shell / Replace Not Painted	N
91	Rocker Panel Left // Smart Repair Medium	Y
109	Door Rear Left / Window / Replace	Y
110	Wing Rear Left // Smart Repair Small	Y
161	Roof // Smart Repair Medium	Y
180	Wing Rear Right // Smart Repair Small	Y
196	Door Rear Right // Polish	Y
197	Door Rear Right / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
222	Side View Mirror Right // Painting	Y
236	Wing Front right // Polish	Y
341	Wheel Alloy Front Right // Repair	N
346	Tyre Front Right // Replace	Y
554	Central Console // Replace Completely	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
634	Rear Left Door Interior Coating // Replace Completely	Y
641	Rear Right Door Interior Coating // Repair	N
644	Rear Right Door Interior Coating // Replace Completely	Y
774	Interior / Side Cover rear Seat / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures

Side View Mirror Right // Painting-scratch




Door Rear Right // Polish-scratch




Door Front Right // Polish-scratch




Door Rear Right / Trim / Replace-scratch





Wheel Alloy Front Right // Repair-scratch




Wing Front right // Polish-scratch







Bumper Front // Painting-scratch




Headlight / Front left / Replace-scratch




Windshield // Replace-scratch

Wing Front Left // Polish-scratch




Door Rear Left / Window / Replace-scratch






Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rear Right Door Interior Coating // Replace Completely-scratch




Rear Right Door Interior Coating // Repair-scratch




Interior / Side Cover rear Seat / Replace-scratch






Central Console // Replace Completely-scratch




Rear Left Door Interior Coating // Replace Completely-scratch




Rocker Panel Left // Smart Repair Medium-dent





Wing Rear Left // Smart Repair Small-dent





Rocker Panel Right // Smart Repair Medium-dent

Wing Rear Right // Smart Repair Small-dent






Roof // Smart Repair Medium-scratch + dent




Side View Mirror Left / Shell / Replace Not Painted-cracked




Tyre Front Right // Replace-tear





Interior Cleaning // Small-stain




Door Front Left // Painting-scratch












Door Rear Left // Painting-scratch






Lettering Removal 15min-


See External Expertise-dent