TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 47969545
Order No. / Reference: 26684276
Inspection date: 5 Oct 2026

Manufacturer: Citroën	Model: Spacetourer XL 2.0 BlueHDi 180 EAT8 Plus
VIN: VF7VKEHZ5RZ100494	





Vehicle details

Manufacturer / Type / Model / Equipment	
Citroën Spacetourer XL 2.0 BlueHDi 180 EAT8 Plus	
Vehicle Identification number	VF7VKEHZ5RZ100494
Mileage (Read)	43,096 km
First registration	12 Feb 2025
Number of holders	2
Next periodical technical inspection	02/2028
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,997 ccm / 4
Power	130 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Multipurpose vehicle
Colour / colour code	Perla Nera Schwarz Metallic
Doors / Seats	5 / 8
Upholstery type	Cloth
Colour of upholstery	Black
Re-import	no
Type of use	rental car
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	Available / incomplete	**Next maintenance in**	44,900 km
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY833036
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	3001 / AWN 00861		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,896 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101V	Winter tyres on Light alloy	Sonstige	5mm / 5mm
2)	225/55 R17 101V	Winter tyres on Light alloy	Sonstige	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS and ESC
- Airbag: Curtain airbags in rows 2 and 3
- Exterior mirror caps painted in Perla Nera black
- Hill start assist
- third brake light
- Color glass
- Digital instrument cluster with high-resolution 10" screen
- Windows: Side windows in rows 2 and 3, as well as the rear window, are more heavily tinted.
- Rubber floor covering
- Transmission: 8-speed automatic
- Manual air conditioning
- Steering wheel with height and reach adjustment
- Engine guard (metal underride guard)
- Fog light
- Package: Visible Package
- Particulate filter: Soot particle filter for diesel engines
- Tire repair kit with puncture spray
- Side moldings painted in Perla Nera black
- Sunshades with lighting
- 12-volt power outlet in the lower glove compartment
- Doors: Sliding door on the right and left, manual
- Central locking with remote control
- Driver and passenger side airbags
- Exterior mirrors, electrically adjustable, heated and foldable
- On-board computer
- CITROËN Connect Box: Emergency call and assistance system
- Rear parking aid, acoustic
- Electric front windows
- electric parking brake
- Cruise control system with speed limiter
- Glazed tailgate, heated and with windshield wiper
- LED headlights, LED daytime running lights
- Reading lamps (individually) in rows 2 and 3
- MyCitroen Play Plus
- Package: Safety
- Electric parking brake
- Tire pressure monitoring system
- Headlights: Eco-LED
- Power steering
- 12-volt power outlet, 3rd row of seats
- Front and rear bumpers painted in body color
- Immobiliser

Extra equipment

- Package: Climate control (additional rear air conditioning - automatic climate control (2 zones) including heated rear window - 2x USB Type C ports in row 2 (rechargeable))
- Package: Comfort (Electric sliding doors right and left with opening sensor - Keyless system - 2 USB ports (Type C) in row 2)
- Package: Design Max (rear window can be opened separately - rear and side windows, extra-dark tinted - 17-inch "Phoenix" silver-black polished alloy wheels with summer tires)
- Package: Drive Assist (Adaptive Cruise Control (ACC) incl. Stop&Go - Multifunction leather steering wheel, heated)
- Package: Driver (multifunction leather steering wheel, heated - keyless system - automatically dimming interior mirror - grip control - inductive charging for smartphones)
- Paint finish: Metallic paint
- Towbar with gooseneck and trailer stabilization (removable without tools, including conversion socket)
- Package: Connect (MyCitroën Drive: - 10" HD touchscreen - DAB - Wireless or wired Android Auto and Apple CarPlay - Bluetooth hands-free system - Steering wheel controls - Row 1: USB-C (rechargeable/ data transfer) + USB-C (rechargeable) - Row 2: USB-C (rechargeable) + USB-C (rechargeable) - 3D navigation system - Integrated EU map - Blind spot assist - 10" digital instrument cluster - Rear and rear parking sensors including side and obstacle detection - 180° surround view reversing camera)
- Package: Family Plus (8-seater in "Rimini" fabric) Row 1: Height-adjustable driver's seat with armrest and single passenger seat with armrest, foldable. Rows 2 and 3: 60/40 split bench seat, foldable and removable on rails. - Floor mats in rows 2 and 3 - Carpet in rows 1, 2, and 3 - Sunshades in row 2 - Closed storage compartments: central dashboard, lower passenger side - Luggage compartment cover - Heated front seats - Folding table behind individual seats in row 1 - Heated multifunction leather steering wheel)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid - dent(s) - Smart repair
2	Wheel / tyres	Alloy rim - front left side - Scratched - Replace
3	Wheel / tyres	Alloy rim - rear left side - Scratched - Replace
4	Braking system	Brake discs and pads - rear - Corrosion - Replace
5	Door - front right side	Door - Scratch(es) - Repair and paint
6	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No.	Accident
1	Side - left

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents




Figure 16: Documents



Figure 17: Documents



Figure 18: Documents




Figure 19: Documents



Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.




Figure 37: Misc.




Figure 38: Misc.



Damage 1: Boot lid / rear door: Boot lid - dent(s) - Smart repair



Damage 1: Boot lid / rear door: Boot lid - dent(s) - Smart repair



Damage 1: Boot lid / rear door: Boot lid - dent(s) - Smart repair



Damage 2: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 2: Wheel / tyres: Alloy rim - front left side - Scratched - Replace




Damage 2: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - rear left side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - rear left side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - rear left side - Scratched - Replace



Damage 4: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 4: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 4: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 4: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 4: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 4: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 4: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 4: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 5: Door - front right side: Door - Scratch(es) - Repair and paint




Damage 5: Door - front right side: Door - Scratch(es) - Repair and paint



Damage 5: Door - front right side: Door - Scratch(es) - Repair and paint



Damage 5: Door - front right side: Door - Scratch(es) - Repair and paint



Damage 6: Vehicle glazing: Windscreen - Stone chips - Replace




Damage 6: Vehicle glazing: Windscreen - Stone chips - Replace




Damage 6: Vehicle glazing: Windscreen - Stone chips - Replace



Accident 1: Side - left



Accident 1: Side - left




Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left




Accident 1: Side - left



Accident 1: Side - left




Accident 1: Side - left



Accident 1: Side - left

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz



Accident 1: Side - left



Accident 1: Side - left