Volkswagen

VIN: WVGZZZA1ZNV073362

Estimated repair cost

624.00 EUR
TOTAL



Description

Registration number 2CPM903	**Registration date** -	**Odometer** 88207 km
Color -	**Year** -	**Upholstery** -
Number of doors -	**Number of seats** -	**Generation** -

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction	net cost
001	Rim / Front Left Material : Aluminium alloy / Rim/Tyre diameter : 16 " / Surface : Painted	Scratched	Smart repair	165.00 EUR



Bodywork time -	Paint time -	Part Price -	Lumpsum **165.00 EUR**
Bodywork cost -	Paint cost -	MaterialCost -	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

002	Door sill / Back Left	Dent	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

003	Tailgate / Boot door / - Material : Steel / Windowed : Yes	Scratched	Painting	245.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
1.00 h	**2.00 h**	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
75.00 EUR	**170.00 EUR**	-	

004	Bumper / Back Painted : Yes	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

005	Door sill / Back Right	Dent	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

006	Door sill / Front Right	Dent	Smart repair	49.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	**49.00 EUR**
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

007	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 16 " / Surface : Painted	Scratched	Smart repair	165.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	**165.00 EUR**
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Loose Items

- [x] Compressor tyre repair kit
- [x] Document holder
- [x] First aid kit
- [x] Rear parcel shelf
- [x] Refill tyre repair kit
- [x] Registration certificate
- [x] Registration certificate owner
- [x] Spare Key
- [x] Triangle
- [x] Tyre repair kit complete
- [x] User manual

Main set of tyres

Front Left	HANKOOK	215/60/16 99 V All-season	5 mm
Front Right	HANKOOK	215/60/16 99 V All-season	5 mm
Back Left	HANKOOK	215/60/16 99 V All-season	7 mm
Back Right	HANKOOK	215/60/16 99 V All-season	7 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat



Front passenger compartment


Front right


Odometer


Navigation


Spare Tyre



Vin

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Door sill / Back Left / Dent



Tailgate / Boot door / - / Scratched



Tailgate / Boot door / - / Scratched



Tailgate / Boot door / - / Scratched



Tailgate / Boot door / - / Scratched



Tailgate / Boot door / - / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Door sill / Back Right / Dent



Door sill / Front Right / Dent



Door sill / Front Right / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.