DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	VR3FPHNS2 RY588611	Registration date	13/08/2024	Exterior Color	Unknown
Brand	PEUGEOT	Licence Plate	KW-HP 308	Odometer	14 314 km
Model	308 PureTech 130 EAT8 Allure				

Inspection Details

Arrival Date	14/07/2026	Inspection ID	7066502	Inspection date	21/07/2026
Assign Date	15/07/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys SLC Essen



Generic equipment

Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓


Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Remote key	✓
Service	✓

Tyres

Goodyear 205/55/16 V All seasons 6.0 mm

Goodyear 205/55/16 V All seasons 6.0 mm





Goodyear 205/55/16 V All seasons 7.0 mm

Goodyear 205/55/16 V All seasons 7.0 mm

Exception / Damage

1



Part	Windscreen	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	-

2



Part	Bonnet	Repair Time	2.80	Part Cost	-
Position	-	Repair Cost	392.00€	Gross Cost	392.00€
Damages	Dented	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	392.00€	**Net Cost**	**392.00€**

3



Part	Roof	Repair Time	6.00	Part Cost	-
Position	-	Repair Cost	840.00€	Gross Cost	840.00€
Damages	Dented	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	840.00€	**Net Cost**	**840.00€**

incl. Himmel lösen

4



Part	Roof post A/B/C	Repair Time	1.10	Part Cost	-
Position	Right	Repair Cost	154.00€	Gross Cost	154.00€
Damages	Dented	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	154.00€	**Net Cost**	**154.00€**

5



Part	Roof post A/B/C	Repair Time	1.80	Part Cost	-
Position	Left	Repair Cost	252.00€	Gross Cost	252.00€
Damages	Dented	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	252.00€	**Net Cost**	**252.00€**

6



Part	Door	Repair Time	1.10	Part Cost	-
Position	Front left	Repair Cost	154.00€	Gross Cost	154.00€
Damages	Dented	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	154.00€	**Net Cost**	**154.00€**

7



Part	Door	Repair Time	0.80	Part Cost	-
Position	Back left	Repair Cost	112.00€	Gross Cost	112.00€
Damages	Dented	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	112.00€	**Net Cost**	**112.00€**

8



Part	Wing	Repair Time	0.90	Part Cost	-
Position	Back left	Repair Cost	126.00€	Gross Cost	126.00€
Damages	Dented	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	126.00€	**Net Cost**	**126.00€**

DEKRA Automotive Solutions

9							
		Part	Door	Repair Time	1.00	Part Cost	-
		Position	Back right	Repair Cost	140.00€	Gross Cost	140.00€
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	140.00€	**Net Cost**	**140.00€**

Comments

Hagelschaden

Summary Inspection

Gross Price	2,170.00€	Depreciation	-	Net Price	2,170.00€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	15.50	2,170.00€	-	-	2,170.00€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	0.00€	-	-	0.00€
Flat Rate	0.00€	-	-	0.00€