TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48579005
Order No. / Reference: 27294767
Inspection date: 6 Nov 2026

Manufacturer: Volkswagen	Model: Crafter 35 TDI VA
VIN: WV1ZZZSYZN9002104	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Crafter 35 TDI VA	
Vehicle Identification number	WV1ZZZSYZN9002104
Mileage (Read)	144,244 km
First registration	6 Sept 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	103 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy White (B9A)
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	300 km
Last service on / at	03/2026 at 116,710 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GE682364
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CBY 47163		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/75 R16 110R	Winter tyres on Steel rim with wheel cover	Goodyear	3mm / 3mm
2)	205/75 R16 110R	Winter tyres on Steel rim with wheel cover	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/75 R16 113R	All-season tyres on Steel	Continental	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Driver's side
- Hill Start Assist
- third brake light
- Electronic Stability Program and ABS
- Omission: Without tachograph
- Electric windows, front
- Transmission: 6-speed transmission
- Weight class front axle (front axle (1,800 kg load capacity))
- Rear doors/tailgate: Hinges for rear doors
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Steering wheel adjustable in height and reach
- Multifunction display "Plus"
- Wheel cover center
- Wheels/Tires: 205/75 R 16 C 113/111, optimized for low rolling resistance
- Wheels: Tire Mobility Set (12-volt compressor and tire sealant)
- Crosswind assist
- Seat belt monitoring system (warning buzzer and light when front seat belts are not fastened)
- Power outlet: 12V socket and 4 cup holders in the dashboard
- Daytime running light
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control and interior operation
- Accessories: On-board tools
- Exterior mirrors, adjustable from the outside
- Floor coverings: Rubber floor covering in the driver's cab
- Three-point automatic seat belts (with belt height adjustment and belt tensioners for driver and front passenger)
- Total weight: Vehicle registration with a permissible total weight of 3.5 t
- Rear wing door without window cutout
- High roof, painted exterior in car color
- Headrests (2)
- Paint finish: Solid
- Headlight range control
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- Wheels: Steel wheels 6.5 J x 16, in silver (load capacity 1,050 kg)
- Sliding door, on the right in the passenger/cargo area
- Keys for locking system: 2 remote control flip keys
- electromechanical power steering
- Seats 1st row: Seat on the right
- Start-stop system (with brake energy recuperation)
- Power outlets: 2 12V sockets in the driver's cab (in the dashboard)
- Partition walls: Partition wall
- Lashing eyes for securing cargo
- Heat-insulating glazing (front and rear side windows and rear window in heat-insulating glass (if fitted))
- Registration as a truck (with an N1 registration (up to and including 3.5 t permissible total weight))

Extra equipment

- Storage compartments: Glove compartment with lockable, illuminated flap
- Airbag for driver and front passenger (with passenger airbag deactivation)
- Conti tires
- Driver assistance systems: Front Assist area monitoring system with City Emergency Braking function
- Floor mats: All-weather mats in the driver's cab (made of rubber)
- Heating: Auxiliary heating for cargo/passenger compartment
- Air conditioning with manual control in the driver's cab
- Fatigue detection
- ParkPilot in the front and rear areas
- "Discover Media" radio navigation system including "Streaming & Internet" with 4 speakers (voice control - 2 USB ports (Type C) in the dashboard - illuminated glove compartment with lockable flap - "Discover Media" radio navigation system with 20.3 cm (8 inch) touchscreen including "Streaming and Internet" - 4 speakers: 2 tweeters, 2 woofers - Wired & Wireless App-Connect - mobile phone interface)
- Seats 1st row: Comfort seat on the right, in the 1st row
- Auxiliary heaters/parking heaters: Electric air auxiliary heater (1,400 W)
- First aid kit, warning triangle, high-visibility vest and warning light
- Storage package 2: Roof gallery with two 1-DIN slots and reading light
- Rigid towbar (including trailer stabilization)
- Electrically adjustable and heated exterior mirrors
- Deletion: Lettering on the rear (Without lettering for type designation)
- Suspension/damping, reinforced and stabilization, reinforced
- Cruise control system including speed limiter
- Instrument panel: Control panel with additional console (including 1 DIN slot and 4 additional switch positions)
- Marker lights, side
- Fog lights including cornering lights
- Upholstery: Durable fabric seat covers, "Marathon" design
- Radio accessories: Digital radio reception DAB+
- Wheels, tires: All-season tires
- Wheels, tires: spare wheel (steel rim) with driving tires, as well as on-board tools and jack
- Rear View reversing camera
- Hinges for rear doors with an increased opening angle (270°)
- Mud flaps, front and rear
- Seats 1st row: "ergoComfort" suspension seat on the left, in the 1st row
- Tachograph: Preparation for Digital Tachograph (Smart TCO) (for retrofitting a tachograph from VDO or Intellic)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Sill - right side	Sill - dent(s) - Smart repair
3	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
4	Roof	Roof rail - left side - dent(s) - Smart repair
5	Body	Body - Paint defect - Conditioning
6	Side panel - rear left side	Side panel - dent(s) - Smart repair
7	Door - front right side	Door - Dent / paintcoat damage - Smart repair
8	Body	Body - Glued / labelled - De-glue / neutralise
9	Sliding door, right	Sliding door - Dent / paintcoat damage - Smart repair
10	Wheel / tyres	Tyre - front - Does not meet the leasing specifications - Replace
11	Seat - front	Seat cover - left side (inkl. Kissen) - Broken / torn - Replace
12	Roof	Roof - dent(s) - Smooth repair work

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper (unpainted) - Scratch(es) - No deduction
2	Boot lid / rear door	Rear door - right side - dent(s) - No deduction
3	Rear bumper	Rear bumper (unpainted) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 21 Oct 2021	1.350,82 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Navigation




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.




Figure 36: Misc.




Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Damage 2: Sill - right side: Sill - dent(s) - Smart repair



Damage 2: Sill - right side: Sill - dent(s) - Smart repair



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 4: Roof: Roof rail - left side - dent(s) - Smart repair



Damage 4: Roof: Roof rail - left side - dent(s) - Smart repair



Damage 5: Body: Body - Paint defect - Conditioning



Damage 5: Body: Body - Paint defect - Conditioning



Damage 6: Side panel - rear left side: Side panel - dent(s) - Smart repair




Damage 6: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 7: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 7: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 7: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 8: Body: Body - Glued / labelled - De-glue / neutralise



Damage 8: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair



Damage 9: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair



Damage 9: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair



Damage 9: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair



Damage 10: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace



Damage 11: Seat - front: Seat cover - left side (inkl. Kissen) - Broken / torn - Replace




Damage 11: Seat - front: Seat cover - left side (inkl. Kissen) - Broken / torn - Replace



Damage 12: Roof: Roof - dent(s) - Smooth repair work



Damage 12: Roof: Roof - dent(s) - Smooth repair work



Wear and tear 1: Front bumper: Front bumper (unpainted) - Scratch(es) - No deduction



Wear and tear 2: Boot lid / rear door: Rear door - right side - dent(s) - No deduction

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Wear and tear 2: Boot lid / rear door: Rear door - right side - dent(s) - No deduction