TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

# Expertise

Protocol number: 48541610
Order No. / Reference: 27157170
Inspection date: 4 Nov 2026

| | |
|---|---|
| Manufacturer: Skoda | Model: Kodiaq 2.0 TDI DSG Sportline |
| VIN: TMBJJ9NS0P8031602 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Skoda Kodiaq 2.0 TDI DSG Sportline | |
| **Vehicle Identification number** | TMBJJ9NS0P8031602 |
| **Mileage** (Read) | 160,836 km |
| **First registration** | 16 Mar 2023 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** (Report on hand) | 02/2028 |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,968 ccm / 4 |
| **Power** | 110 kW |
| **Gearbox / Number of gears** | Automatic / 7 |
| **Type of drive** | Front drive |
| **Type of vehicle** | SUV |
| **Colour / colour code** | Graphite Grau Metallic (F7C) |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Black-Anthracite |

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 7,000 km |
| **Last service on / at** | 05/2026 at 140,401 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GQ542190 |
| **Previous damage / Accident** | None detectable | **Repainting** | Detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | short drive on the company premises | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 8004 / ART 03925 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,360 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 235/50 R19 99V | Summer tyres on Light alloy | Hankook | 6mm / 6mm |
| 2) | 235/50 R19 99V | Summer tyres on Light alloy | Hankook | 6mm / 6mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/65 R17 99H | Winter tires (with run-flat tires) on Light alloy | Pirelli | 5mm / 5mm |
| 2) | 215/65 R17 99H | Winter tires (with run-flat tires) on Light alloy | Pirelli | 5mm / 5mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| | Tirefit | Expiration date 10/2026 | | |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

## Standard equipment

- 12V socket in the center console and in the trunk
- Storage compartments behind the wheel arches in the trunk
- Airbag, driver's knee airbag
- Airbag, head airbags
- Allergen filter
- Traction control (ASR)
- Electrically folding exterior mirrors including interior and driver's side mirrors with automatic dimming
- Hill start assist
- Hydraulic brake assist (HBA)
- Black headliner
- Roof rails, black
- Diesel particulate filter
- Tachometer
- Easy Start (start-stop button)
- Electronic parking brake including auto-hold function
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor ((tunnel light, coming and leaving home function))
- Electric windows front and rear (including anti-pinch protection and child safety lock)
- Front radar assistant including city emergency braking function with pedestrian detection
- Closed storage compartment on the driver's side
- Transmission: 7-speed dual-clutch transmission (DSG)
- Illuminated glove compartment
- Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger including humidity sensor and odor and allergen filter)
- Paint finish: Special paint finish, solid color
- LED ambient lighting (decorative strips in the door panels with selectable color climate, LED reading lights in the front, LED lighting for the make-up mirrors in the sun visors)
- Steering wheel: Sport leather steering wheel with multifunction buttons including paddle shifters (height and reach adjustable)
- Engine drag torque control (MSR)
- Fog lights with integrated LED daytime running lights
- Stainless steel pedal design
- Progressive steering
- Radio accessories: 8 speakers
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring
- Rear seat backrest split 60:40, foldable, longitudinally adjustable, backrest angle adjustable
- Headlights washer / wiper system
- Kodiaq safety belts (Height-adjustable three-point seat belts in the front, with belt tensioners - Three three-point seat belts in the rear - Belt fastening indicator in the front and in the second row of seats)
- Seats: Height-adjustable front seats
- Storage compartment on the left wheel arch
- front aero windshield wipers
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Dashboard in black / black, door trim in black with microfiber inlay
- Electrically adjustable and heated exterior mirrors with integrated side indicators
- Care Connect: Proactive services (10-year term) (Remote Access (1-year term))
- Dark carbon decorative inlay
- Digital Cockpit (8")
- Third brake light (in the rear spoiler (LED))
- eCall (automatic emergency call function in case of an accident with airbag deployment)
- ESC Electronic Stability Control
- Driving profile selection
- Chassis: Adaptive chassis DCC including driving profile selection
- High Beam Assist (Light Assist)
- front and rear floor mats
- Front and rear footwell lighting
- Cruise control
- Tinted windows
- Isofix anchorage on the outer rear seats including top tether
- Boot cover, roll-up and removable
- Front headrests are fixed, rear headrests are height-adjustable.
- LED matrix headlights and dynamic high beam assist (Light Assist)
- LED taillights in crystal glass look with animated turn signals
- Reading lights at the front of the headliner
- Rear center armrest with cup holders
- Front center armrest, including storage compartment
- Multi-collision brake
- Rear parking sensors
- Upholstery: Microfiber Sport-Black
- Radio: Bolero infotainment system (Bolero music system - 8" capacitive color display - voice control)
- Radio accessories: Wireless SmartLink
- Wheels: 19" alloy wheels Triglav anthracite polished (7Jx19 tires 235/50 R19 99V ET43)
- Heated windshield washer nozzles, front
- Electromechanical power steering
- Seats: Heated front and outer rear seats
- Seats: Adjustable lumbar support in the front seats
- Seats: Electrically adjustable front seats with memory function
- Seats: Remote release of the rear seat backrests (2nd row) in the boot
- Sun visor on driver and passenger side with illuminated vanity mirror
- Speed limiter

- Skoda Care Connect (SOS emergency call function (eCall, including automatic activation in the event of an accident with airbag deployment) - Mobility service (connection for rapid assistance in case of breakdown) - Information service (connection to the hotline for all questions regarding vehicle functions) - Free remote vehicle access for one year with access to vehicle data/functions via smartphone, e.g., parking position, activating hazard warning lights, current fuel level, etc.)
- Front door sill trims
- Lashing eyes in the trunk
- Central locking with remote control (two vehicle keys)
- Bumpers painted in body color
- Sunset (rear window and rear side windows tinted dark)
- Telephone: Comfort hands-free telephone system including phone box (with inductive charging function (connection via external antenna))
- Variable fastening concept in the trunk
- Immobiliser

### Extra equipment

- Swiveling trailer hitch (with electric release, including trailer stabilization)
- Paint finish: Metallic / Pearl effect
- Package: Business Columbus (Sportline) (Dynamic radio navigation system Columbus - 9.2" capacitive color display - Digital Cockpit Plus (10") - Driver fatigue detection - 230V socket and a USB charging port (Type-C) on the back of the front center armrest - KESSY keyless entry - Electric tailgate operation including comfort opening - Luggage net partition - Infotainment Online (3-year subscription))
- Variable loading floor in the trunk
- Traveller assistance system (DSG) (Predictive Adaptive Cruise Control pACC (control range up to 210 km/h) - Lane Assist - Adaptive Lane Guidance - Traffic Jam and Emergency Assist - Traffic Sign Recognition)
- Package: Family (Removable waste bin for the door panel - Sunshades for the rear side windows - Door edge protectors)
- Front and rear parking sensors
- Proactive occupant protection including rear side airbags
- Rear view camera

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | A short maneuvering and shunting exercise was carried out on the company premises. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Equipment | Tirefit filler - Expired - Replace |
| 2 | Door - rear left side | Door - dent(s) - Smart repair |
| 3 | Door - front left side | Brightware - lower - Scratch(es) - Smart repair |
| 4 | Boot lid / rear door | Boot lid - Scratch(es) - Smart repair |
| 5 | Bonnet | Bonnet (+ Dellen) - Scratch(es) - Repair and paint |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Front bumper | Front bumper - Stone chips - No deduction |
| 2 | Roof | Roof - dent(s) - No deduction |
| 3 | Vehicle glazing | Windscreen - Stone chips - No deduction |
| 4 | Body | Body - Scratch(es) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Repainting

| No. | Repainting |
|---|---|
| 1 | Bonnet, Professionally carried out, Invoice of repair done Non-existent |

## Paint coat thickness measurement

| | |
|---|---|
| Bonnet | 222 µm |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel



**Figure 9:** Interior 360° view



**Figure 10:** Cargo area





**Figure 11:** VIN



**Figure 12:** Mounted tyres





**Figure 13:** Documents




**Figure 14:** Documents




**Figure 15:** Documents



**Figure 16:** Additional tyres




**Figure 17:** Additional tyres




**Figure 18:** Navigation





**Figure 19:** Misc.



**Figure 20:** Misc.





**Figure 21:** Misc.



**Figure 22:** Misc.



**Figure 23:** Misc.



**Figure 24:** Misc.




**Figure 25:** Misc.



**Figure 26:** Misc.




**Figure 27:** Misc.



**Figure 28:** Misc.





**Figure 29:** Misc.




**Figure 30:** Misc.



**Figure 31:** Misc.



**Figure 32:** Misc.




**Figure 33:** Misc.



**Figure 34:** Misc.




**Figure 35:** Misc.




**Damage 1:** Equipment: Tirefit filler - Expired - Replace



**Damage 2:** Door - rear left side: Door - dent(s) - Smart repair



**Damage 2:** Door - rear left side: Door - dent(s) - Smart repair



**Damage 3:** Door - front left side: Brightware - lower - Scratch(es) - Smart repair




**Damage 3:** Door - front left side: Brightware - lower - Scratch(es) - Smart repair



**Damage 3:** Door - front left side: Brightware - lower - Scratch(es) - Smart repair





**Damage 4:** Boot lid / rear door: Boot lid - Scratch(es) - Smart repair




**Damage 4:** Boot lid / rear door: Boot lid - Scratch(es) - Smart repair




**Damage 5:** Bonnet: Bonnet (+ Dellen) - Scratch(es) - Repair and paint



**Damage 5:** Bonnet: Bonnet (+ Dellen) - Scratch(es) - Repair and paint



**Damage 5:** Bonnet: Bonnet (+ Dellen) - Scratch(es) - Repair and paint




**Damage 5:** Bonnet: Bonnet (+ Dellen) - Scratch(es) - Repair and paint



**Damage 5:** Bonnet: Bonnet (+ Dellen) - Scratch(es) - Repair and paint

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig


Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach



**Damage 5:** Bonnet: Bonnet (+ Dellen) - Scratch(es) - Repair and paint



**Damage 5:** Bonnet: Bonnet (+ Dellen) - Scratch(es) - Repair and paint



**Damage 5:** Bonnet: Bonnet (+ Dellen) - Scratch(es) - Repair and paint



**Damage 5:** Bonnet: Bonnet (+ Dellen) - Scratch(es) - Repair and paint



**Repainting 1:** Bonnet