BMW 3 SERIES TOURING


Vehicle information


Make:	**BMW**	License:	**2CSY893**
Gearbox:		Body color:	
Model:	**3 SERIES TOURING**	VIN:	**WBA41FY070FN90830**
Fuel type:		Power:	**120 kW**
Version:	**2.0 320E TOURING**	First registration	**16/11/2022**
Mileage:	**165461 km**	N° of doors:	


Damage summary


Interior	1
Right	2
Roof & others	1


Commercial pictures


































Options according to the inspector

GPS	**Yes**

Damages

Alloy rim RR
Scratch(es)
Repair and paint (complete)
Right





Bodywork
Damaged
Acceptable
Roof & others




















Interior
Damaged
Acceptable
Interior





Tyre RR
Tear
Replace
Right





Tyres

Front Left
Summer
Aluminium
225/50/17/98/Y
Hankook
6.0 mm
Front Right
Summer
Aluminium
225/50/17/98/Y
Hankook
6.0 mm
Rear Left
Summer
Aluminium
225/50/17/98/Y
Hankook
4.0 mm
Rear Right
Summer
Aluminium
225/50/17/98/Y
Hankook
4.0 mm

Checks

Category	**Passenger Car**	Certificate of Conformity	**Yes**
Compressor	**N/A**	Maintenance	**OK**
Maintenance	**dans 1700 km**	Number of charging cables (normal)	**1**
Number of charging cables (rapid charge)	**1**	Number of keys total	**2**
Registration Certificate Car (BE)	**Yes**	Registration Certificate Home (BE)	**No**
Repair kit	**N/A**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Statutory inspection	**OK**	Statutory inspection	**16/11/2026**
Type of Maintenance book	**Digital maintenance**		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.