TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48601585
Order No. / Reference: 27258771
Inspection date: 9 Nov 2026

Manufacturer: Volkswagen	Model: Crafter 35 TDI Autm. 4MOTION
VIN: WV1ZZZSYZN9032279	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Crafter 35 TDI Autm. 4MOTION	
Vehicle Identification number	WV1ZZZSYZN9032279
Mileage (Read)	192,963 km
First registration	1 Apr 2022
Number of holders	1
Next periodical technical inspection	04/2026
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	130 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Van
Colour / colour code	Candyweiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	2,100 km
Last service on / at	12/2025 at 167,876 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GH980756
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CCB 21533		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 113R	Summer tyres on Steel	Continental	5mm / 5mm
2)	235/65 R16 113R	Summer tyres on Steel	Continental	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 121R	Winter tyres on Steel	Michelin	5mm / 5mm
2)	235/65 R16 121R	Winter tyres on Steel	Michelin	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	235/65 R16 113R	Summer tyres on Steel	Continental	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Driver's side
- Convex exterior mirrors (left and right), with integrated LED turn signal and wide-angle range
- Floor coverings: Rubber floor covering in the driver's cab
- Three-point automatic seat belts
- Electric windows, front
- Transmission: 8-speed automatic
- Rear wing door without window cutout
- High roof, painted exterior in car color
- Headrests (2)
- Steering wheel adjustable in height and reach
- Multifunction display "Plus"
- Upholstery: Seat covers in fabric, design "Austin"
- Wheels/Tires: 235/65 R 16 C 115/113 R, optimized for low rolling resistance
- Sliding door, on the right in the passenger/cargo area
- Crosswind assist
- Seatbelt check
- Start-stop system
- Power outlets: 2 12V sockets in the driver's cab (in the dashboard)
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control and interior operation
- Registration as a truck
- 4MOTION all-wheel drive (permanent)
- Exterior mirrors, adjustable from the outside
- Hill Start Assist
- third brake light
- Electronic Stability Program and ABS
- Total weight: Vehicle registration with a permissible total weight of 3.5 t
- Rear doors/tailgate: Hinges for rear doors
- Instrument usage (km/h)
- Paint finish: Solid
- Headlight range control
- Particulate filter: Soot particle filter for diesel engines
- Wheel cover center
- Wheels: Steel wheels 6.5 J x 16, in silver (load capacity 1,200 kg)
- Keys for locking system: 2 remote control flip keys
- electromechanical power steering
- Seats 1st row: Seat on the right
- Power outlet: 12V socket and 4 cup holders in the dashboard
- Daytime running light
- Lashing eyes for securing cargo
- thermal insulation glazing
- Accessories: On-board tools

Extra equipment

- Storage compartments: Glove compartment with lockable, illuminated flap
- Batteries: 2nd battery with isolating relay and battery monitoring (AGM battery)
- Roof vent, mechanical without closure, for gas cylinder transport
- Cruise control system including speed limiter
- Speed warning system
- Interior paneling: Side paneling in the cargo area made of plywood, extending to the roof frame
- Fuel fill quantity, higher initial fill (15 l)
- Cargo area ventilation for gas cylinder transport (shaft in the vehicle floor)
- LED headlights with LED daytime running lights (headlight range control, automatically regulated)
- Fatigue detection
- Package: Light and Sight (High beam control "Light Assist" - Daytime running lights with automatic headlight control, "Leaving home" function and manual "Coming home" function - Windscreen wiper interval control with light and rain sensor)
- "Discover Media" radio navigation system including "Streaming & Internet" with 4 speakers (voice control - 2 USB ports (Type C) in the dashboard - illuminated glove compartment with lockable flap - "Discover Media" radio navigation system with 20.3 cm (8 inch) touchscreen including "Streaming and Internet" - 4 speakers: 2 tweeters, 2 woofers - Wired & Wireless App-Connect - mobile phone interface)
- Lane Assist including Blind Spot Sensor with Rear Traffic Alert
- Power outlets in the cab (4 12V sockets in the cab (three in the dashboard, one in the left seat frame))
- Rear step, across the entire width
- Storage package 2: Roof gallery with two 1-DIN slots and reading light
- Batteries: 230V external socket and 230V internal socket in the cargo area, rear left, charger
- Electrical interface for external use (electrical terminal block and function control unit 1 with body manufacturer (ABH) programming)
- Weight class front axle (reinforced front axle)
- Air conditioning "Air Care Climatronic" (daytime running lights with automatic headlight control, "Leaving home" function and manual "Coming home" function - intermittent windscreen wiper control with light and rain sensor - Climatronic with air recirculation control, CFC-free)
- Steering wheel: Multifunction steering wheel (3 spokes)
- Marker lights, side
- Fog lights including cornering lights
- ParkPilot front and rear with active side protection, Blind Spot Sensor including Rear Traffic Alert. (Electrically adjustable, heated and folding exterior mirrors, Blind Spot Sensor including Rear Traffic Alert, Multifunction Display "Plus", ParkPilot front and rear with active side protection)
- Radio accessories: Digital radio reception DAB+
- Wheels, tires: spare wheel (steel rim) with driving tires, as well as on-board tools and jack
- Rear View reversing camera
- Heated windshield washer nozzles for the windshield
- Seats 1st row: "ergoActive" suspension seat on the left, in the 1st row
- Seat heating, left and right, separately adjustable, in the 1st row of seats
- Power outlet: 230V socket in the left seat frame
- Sockets: Preparation for 230V outdoor socket
- Partition walls: Partition wall with fixed window

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Electrical system	Battery cover (Batteriepol Abdeckung) - Missing - Replace
2	Door - front left side	Door - Scratch(es) - Smart repair
3	Rear of vehicle	Foot plate - Scratch(es) - Loss in value
4	Misc.	Main inspection - Due - Perform
5	Wheel / tyres	Tyre - front left side (Flankenbeschädigung, nicht fahrbereit) - Damaged - Replace
6	Side panel - rear right side	Side panel (Lackläufer & Dellen, unterhalb) - Unprofessionally repaired - Repair and paint

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
2	Wheel / tyres	Tyre - rear right side - Abrasion - No deduction
3	Door - front right side	Door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side right, Professionally repaired, Invoice of repair done Non-existent	
2	Side right, not professionally repaired, Invoice of repair done Non-existent	

Repainting

No.	Repainting
1	Boot lid / rear door, Mudguard - right side, Door - rear right side, Door - front right side, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear right side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	171 µm	Mudguard - right side	179 µm
Side panel - rear right side	237 µm	Door - rear right side	222 µm
Door - front right side	176 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

An unprofessionally repaired previous damage was found at the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

- Das Fahrzeugdach konnte unter den gegebenen Bedingungen nicht begutachtet werden. Etwaige wertmindernde Faktoren fließen nicht in diese Beurteilung hinein. Mehrkosten sind möglich.

- Der angegebene Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents



Figure 19: Additional tyres




Figure 20: Navigation



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.




Figure 37: Misc.




Figure 38: Misc.



Figure 39: Misc.




Figure 40: Misc.



Figure 41: Misc.



Figure 42: Misc.



Figure 43: Misc.



Figure 44: Misc.



Damage 1: Electrical system: Battery cover (Batteriepol Abdeckung) - Missing - Replace



Damage 1: Electrical system: Battery cover (Batteriepol Abdeckung) - Missing - Replace



Damage 2: Door - front left side: Door - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door - Scratch(es) - Smart repair




Damage 3: Rear of vehicle: Foot plate - Scratch(es) - Loss in value



Damage 3: Rear of vehicle: Foot plate - Scratch(es) - Loss in value



Damage 3: Rear of vehicle: Foot plate - Scratch(es) - Loss in value



Damage 4: Misc.: Main inspection - Due - Perform



Damage 5: Wheel / tyres: Tyre - front left side (Flankenbeschädigung, nicht fahrbereit) - Damaged - Replace



Damage 5: Wheel / tyres: Tyre - front left side (Flankenbeschädigung, nicht fahrbereit) - Damaged - Replace



Damage 6: Side panel - rear right side: Side panel (Lackläufer & Dellen, unterhalb) - Unprofessionally repaired - Repair and paint



Damage 6: Side panel - rear right side: Side panel (Lackläufer & Dellen, unterhalb) - Unprofessionally repaired - Repair and paint



Damage 6: Side panel - rear right side: Side panel (Lackläufer & Dellen, unterhalb) - Unprofessionally repaired - Repair and paint



Damage 6: Side panel - rear right side: Side panel (Lackläufer & Dellen, unterhalb) - Unprofessionally repaired - Repair and paint



Damage 6: Side panel - rear right side: Side panel (Lackläufer & Dellen, unterhalb) - Unprofessionally repaired - Repair and paint



Damage 6: Side panel - rear right side: Side panel (Lackläufer & Dellen, unterhalb) - Unprofessionally repaired - Repair and paint



Damage 6: Side panel - rear right side: Side panel (Lackläufer & Dellen, unterhalb) - Unprofessionally repaired - Repair and paint



Wear and tear 1: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wear and tear 1: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wear and tear 2: Wheel / tyres: Tyre - rear right side - Abrasion - No deduction




Wear and tear 2: Wheel / tyres: Tyre - rear right side - Abrasion - No deduction



Wear and tear 2: Wheel / tyres: Tyre - rear right side - Abrasion - No deduction



Wear and tear 3: Door - front right side: Door - dent(s) - No deduction



Wear and tear 3: Door - front right side: Door - dent(s) - No deduction



Wear and tear 3: Door - front right side: Door - dent(s) - No deduction



Repainting 1: Boot lid / rear door, Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Door - rear right side, Door - front right side




Repainting 1: Boot lid / rear door, Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Door - rear right side, Door - front right side

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt



Repainting 1: Boot lid / rear door, Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Mudguard - right side, Door - rear right side, Door - front right side