MACADAM











Mercedes Sprinter (Segm. B3): 2EBP602

Vinnumber:	**W1VGFBFZ4PP576201**	Versionname:	**Sprinter 311 Functional L2 2.0CDi 114pk/cv FWD**
First Registrationdate:	**18/08/2023**	Fiscalpower:	
Expertise Mileage:	**47185**	Power Kw:	**84**
Bodytype:		Type of rims (mounted)	**Steel**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**ass A plus 639 d**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Light Commercial Vehicle**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**No Tow bar**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/65/16/110 R**			
	Fr.L.	**Firestone: 8 mm**	Fr.R.	**Firestone: 8 mm**
	Re.L.	**Firestone: 8 mm**	Re.R.	**Firestone: 8 mm**

Tyre profile depth FL	**8.0**
Tyre profile depth FR	**8.0**
Tyre profile depth RL	**8.0**
Tyre profile depth RR	**8.0**
Tyre size FL	**225/65 R 16 110 R**
Tyre size FR	**225/65 R 16 110 R**
Tyre size RL	**225/65 R 16 110 R**
Tyre size RR	**225/65 R 16 110 R**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**258**
Tyre make FR	**258**
Tyre make RL	**258**
Tyre make RR	**258**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Seat cover FL, Stain, Acceptable





Door panel FR, Scratch(es), Smart repair




Bumper F, Dent(s) and scratch(es), Replace










Windscreen, Stone chip(s), Replace





Central pillar L, Dent(s), Acceptable




Wing trim RL, Deformed / Strained, Replace




Boot door lining R, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable




Wing RR, Dent(s), Acceptable




Wing trim RR, Deformed / Strained, Replace




Wing trim RR, Scratch(es), Replace




Sliding door R, Dent(s), Acceptable





Outside rear-view mirror housing R, Scratch(es), Acceptable




Bodywork, Not original part, Check





Onderhoudshistorie van: W1VGFBFZ4PP576201

ALPHABET

Kenteken	2EBP602
Merk Model	Mercedes Sprinter 311 Functional L2 2.0CDi 114pk/cv FWD
Brandstofsoort	Diesel
Datum deel1	8/18/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/31/26	47,115	airco vulling	Uitvoeren
7/31/26	47,115	brandstoffilter	Vervangen
7/31/26	47,115	luchtfilter	Vervangen
7/31/26	47,115	luchtfilter interieur	Vervangen
7/31/26	47,115	oliezeef	Vervangen
7/31/26	47,115	onderhoud 12 maand	Uitvoeren
4/24/25	40,705	mercedes assyst a	Uitvoeren
4/24/25	40,705	remvloeistof	Vervangen
4/24/25	40,705	ruitenwisserrubber vooraan	Vervangen