TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 47913056
Order No. / Reference: 26903134
Inspection date: 29 Sept 2026

Manufacturer: Mercedes-Benz	Model: C 300 de T 9G-TRONIC Avantgarde
VIN: W1K2052131G067965	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz C 300 de T 9G-TRONIC Avantgarde	
Vehicle Identification number	W1K2052131G067965
Mileage (Read)	115,544 km
First registration	3 Dec 2020
Number of holders	1
Fuel type	Hybr.D/E ext.aufl
Engine displacement / Cylinder	1,950 ccm / 4
Power	143 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Rear drive
Type of vehicle	Station wagon
Colour / colour code	CAVANSITBLAU
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Beige
Vehicle with smoke odor	no
readiness to drive	Not roadworthy / moveable

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	130 Tag(e)
Last service on / at	02/2026 at 100,699 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FX737905
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	Conditional: Light/moisture/dirt	**Lifting equipment / pit**	No
Test drive	Not possible	**Engine function test**	Not possible
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	2222 / ALF 00041		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,480 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 95Y	Summer tyres on Light alloy	Pirelli	2mm / 0mm
2)	245/40 R18 97Y	Summer tires (with run-flat tires) on Light alloy	Goodyear	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 95V	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	245/40 R18 97V	Winter tyres on Light alloy	Pirelli	2mm / 3mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment under the load floor
- Airbag
- Airbag: Automatic passenger airbag deactivation
- Foldable armrest for driver and front passenger with storage compartment
- Heated and electrically adjustable exterior mirrors (left and right) painted in body color
- Brake system with larger brake discs on the front axle
- Tachometer
- DYNAMIC SELECT
- Electronic Stability Program (ESP) with Crosswind Assist
- Electric windows (4-way)
- Luggage net on the left side of the trunk
- Halogen headlights with integrated LED daytime running lights
- Interior headliner fabric crystal grey
- Mechanical child safety lock for the rear doors
- Remote trunk lid release
- Combination instrument with 2 tubular round instruments
- Paint finish: Solid
- Charging cable for household socket, 5m, smooth
- Cargo area cover including EASY-PACK safety net
- Steering column mechanically adjustable in height and length
- Mercedes-Benz emergency call system
- Package: Interior lighting package
- Package: Light
- Radio accessories: Digital radio
- Radio accessories: Communication module (LTE) for using Mercedes me connect services
- Windscreen wipers with rain sensor
- Seat belts C-Class
- Seats: ISOFIX child seat attachment with top tether in the rear
- Pre-installation for vehicle monitoring
- High-visibility vest for drivers
- Green heat-insulating glass all around, including rear window made of single-pane safety glass.
- ADAPTIVE BRAKE with hill start assist, pre-filling and drying braking in wet conditions
- Anti-lock braking system (ABS)
- Rear armrest with storage compartment and cupholder
- ATTENTION ASSIST
- Outdoor temperature display
- Brake Assist, Active
- Diesel particulate filter
- Third brake light in LED technology
- ECO start/stop function
- Driving light assistant
- Pedestrian protection (active hood)
- Transmission: 9-speed automatic, 9G-TRONIC
- Heated rear window with timer
- Rear window wiper with intermittent function
- KEYLESS-GO start function
- Climate: THERMATIC automatic climate control with 2 climate zones
- Headrests 5-way adjustable for driver and front passenger, 4-way adjustable, and 2-way adjustable in the rear.
- Steering wheel: Multifunction sports steering wheel in black leather, 3-spoke design
- Steering: Comfort direct steering
- Package: AVANTGARDE Exterior
- Package: Comfort Package
- Upholstery: ARTICO leatherette/Norwich fabric
- Radio: Audio 20 GPS
- Tire pressure monitoring system (TPMS)
- Travel calculator in the multifunction display
- Service interval indicator ASSYST
- Seats: Rear seat backrests foldable 40/20/40 split
- Seats: Front seats electrically adjustable
- Cruise control with HOLD function
- Pre-installation for vehicle setup
- Electronic immobilizer
- Central locking
- Decorative elements in piano black finish / aluminum with light longitudinal grain

Extra equipment

- Head-up Display (Keeping the most important driver information in view without taking your eyes off the road - this is made possible by the head-up display. It projects a virtual image, approximately 21 x 7 cm in size, into the driver's field of vision, which appears to float about 2 meters in front of them above the hood.)
- Paint finish: Metallic
- Charging cable for wallbox and public charging stations, 5m, smooth (This charging cable, also called Mode 3 cable, allows you to charge the vehicle battery at the wallbox or at public charging stations with up to 11 kW (Type 2, 3-phase, 20 A).)
- Package: Advanced Infotainment Package (Smartphone Integration Package consisting of Apple CarPlay and Android Auto, Media Display with high-resolution 16:9 format media display with 10.25" screen diagonal, SD card navigation, Live Traffic Information)
- Package: High-End Assistance Package (Driving Assistance Package: Active Distance Assist DISTRONIC, Active Lane Keeping Assist and Blind Spot Assist, Active Brake Assist with Cross-Traffic Function including Emergency Braking at the End of Traffic Jam and Evasive Steering Assist, PRE-SAFE Plus, Mirror Package: Interior and exterior mirrors on the driver's side automatically dimming, exterior mirrors electrically folding, parking position on the right, ambient lighting in the exterior mirrors, on-board setting - automatic lowering of the passenger-side mirror when reverse gear is engaged)
- Upholstery: ARTICO man-made leather
- Radio accessories: Touchpad with controller (for convenient operation of the multimedia system)
- Radio accessories: Fully digital instrument display (The fully digital instrument display with Classic, Progressive and Sporty display styles lets you decide which information is important to you and how it is displayed. The 31.2 cm (12.3") display delivers a crystal-clear image that is easy to read in all lighting conditions.)
- Sunroof: Panoramic sunroof (with electric sunshade and anti-pinch protection)
- Extendable sun visors (and side-swiveling. The side-swiveling and extendable sun visors for driver and front passenger offer protection against disturbing light from the front or side)
- Heat-insulating dark tinted glass all around from the B-pillar back
- Decorative elements: open-pore black ash wood/light longitudinally sanded aluminum
- KEYLESS-GO Comfort Package (including remote tailgate closing, EASY-PACK tailgate, HANDS-FREE ACCESS, illuminated door handle recesses, and comfort opening and closing. The system allows you to conveniently open, start, and lock the vehicle simply by carrying the electronic key. The HANDS-FREE ACCESS function enables contactless and fully automatic opening and closing of the tailgate.)
- Package: Storage (Luggage net on the side of the trunk, right-hand side panel; net on the trunk floor; folding box under the load floor; double cupholder in the center console for 2 x 500 ml (with 6-speed manual transmission); double cupholder in the center console for 2 x 750 ml (with automatic transmission); luggage net in the front passenger footwell; map pockets on the back of the front seats; 2 USB ports with charging function)
- Package: Business PLUS (Parking Package - Active Parking Assistant - Advanced Infotainment Package - Smartphone Integration Package - Apple CarPlay, Android Auto, Media Display with high-resolution 10.25" diagonal, SD card navigation, Live Traffic preparation - Comfort Package - Heated seats for driver/front passenger, Seat Comfort Package for driver/front passenger: - 4-way electric pneumatic lumbar support - Electric seat cushion tilt and mechanical seat cushion depth adjustment by 6 cm - Large fuel tank (not for 300e/de) - Lighting Package - LED headlights, LED daytime running lights)
- Package: Sound comfort in conjunction with head-up display (Burmester surround sound system: 13 speakers, 9-channel DSP amplifier, 590 watts system power - heat and noise-insulating acoustic glass: with acoustic film for the windshield and laminated safety glass with acoustic film in the front side windows. The acoustic film replaces the conventional plastic interlayer of the laminated safety glass. This reduces the noise level in the interior by up to 10 decibels. The acoustic film is specially tuned.)
- Wheels: 45.7 cm (18") alloy wheels, 4-piece set in 5-twin-spoke design (high-gloss black paint and diamond-turned finish, front axle: 7.5 J x 18 ET 49, tire size 225/45 R 18, rear axle: 8.5 J x 18 ET 56, tire size 245/40 R 18)
- 230V power outlet in the rear
- Telephone accessories: Multifunctional telephony (wireless connection of a compatible mobile phone to the external antenna - wireless charging for compatible mobile phones - Bluetooth and WLAN pairing wirelessly via NFC (Near Field Communication) technology)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/dampness or dirt. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	The conduction of a test drive with the described vehicle was impossible to do under the given conditions.
Engine function test	An engine test run could not be performed. This is due to the following reason.: Motorschaden
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Electrical system	Battery - Empty - Perform diagnosis
2	Door - front left side	Door - dent(s) - Smart repair
3	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Loss in value
4	Wheel / tyres	Tyre - rear right side - Leaking - Replace
5	Multimedia system	Navigation data storage - Non-operational - Perform diagnosis
6	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
7	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
8	Wheel / tyres	Tyre - front - Worn - Replace
9	Seat - front	Seat cover - left side - Broken / torn - Replace
10	Vehicle glazing	Windscreen - Stone chips - Replace
11	Engine	Engine - Non-operational - repair according to calculation

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	2nd wheel set	1 alloy rim - Scratch(es) - No deduction
3	2nd wheel set	2 tyres - Does not meet the leasing specifications - No deduction
4	Side panel - rear left side	Side panel - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side - left, Provided by user / customer, from 10 Jun 2024	3.309,04 €

Repainting

No.	Repainting
1	Side panel - rear left side, Door - front left side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear left side	171 µm	Door - front left side	179 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Der beiliegende Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.
-Bordelektronik fehlerhaft - Schadenausweitung möglich, Zusatzkosten können
entstehen.
-Ein Motorprobelauf, Getriebefunktionstest sowie Funktionstest der Bordelektronik
konnte aufgrund des Motorschadens/Leeren Batterie des Fahrzeuges nicht durchgeführt werden. Zusatzkosten können entstehen.
-Keine Besichtigung des Unterbodens, Begutachtung Fahrwerk/Achsen/Aggregate nur
bedingt möglich, Zusatzkosten können entstehen.
-Zündung kann ohne Externe Stromversorgung nicht eingeschaltet werden.

Minderwerte höher als HEK



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel



Figure 10: Interior 360° view



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.






Figure 26: Misc.




Damage 1: Electrical system: Battery - Empty - Perform diagnosis



Damage 2: Door - front left side: Door - dent(s) - Smart repair




Damage 2: Door - front left side: Door - dent(s) - Smart repair




Damage 3: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value




Damage 3: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Tyre - rear right side - Leaking - Replace



Damage 4: Wheel / tyres: Tyre - rear right side - Leaking - Replace



Damage 5: Multimedia system: Navigation data storage - Non-operational - Perform diagnosis



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 7: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 7: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 8: Wheel / tyres: Tyre - front - Worn - Replace




Damage 8: Wheel / tyres: Tyre - front - Worn - Replace



Damage 8: Wheel / tyres: Tyre - front - Worn - Replace




Damage 8: Wheel / tyres: Tyre - front - Worn - Replace



Damage 9: Seat - front: Seat cover - left side - Broken / torn - Replace



Damage 9: Seat - front: Seat cover - left side - Broken / torn - Replace




Damage 10: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 10: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 11: Engine: Engine - Non-operational - repair according to calculation



Damage 11: Engine: Engine - Non-operational - repair according to calculation



Damage 11: Engine: Engine - Non-operational - repair according to calculation




Damage 11: Engine: Engine - Non-operational - repair according to calculation



Damage 11: Engine: Engine - Non-operational - repair according to calculation



Damage 11: Engine: Engine - Non-operational - repair according to calculation



Wear and tear 4: Side panel - rear left side: Side panel - dent(s) - No deduction



Wear and tear 4: Side panel - rear left side: Side panel - dent(s) - No deduction



Repainting 1: Side panel - rear left side, Door - front left side



Repainting 1: Side panel - rear left side, Door - front left side



Repainting 1: Side panel - rear left side, Door - front left side



Repainting 1: Side panel - rear left side, Door - front left side