TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48230690
Order No. / Reference: 27162407
Inspection date: 21 Oct 2026

Manufacturer: Volkswagen	Model: Tiguan 2.0 TDI SCR DSG
VIN: WVGZZZCT5RW047179	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Tiguan 2.0 TDI SCR DSG	
Vehicle Identification number	WVGZZZCT5RW047179
Mileage (Read)	34,546 km
First registration	30 Jul 2024
Number of holders	2
Next periodical technical inspection	07/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Oyster Silver-Metallic (M7P)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	66 Tag(e)
Last service on / at	12/2025 at 27,510 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HD525058
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CSG 00037		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,160 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99V	Summer tyres on Light alloy	Hankook	5mm / 5mm
2)	215/65 R17 99V	Summer tyres on Light alloy	Hankook	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 103H	Winter tyres on Light alloy	Pirelli	7mm / 7mm
2)	215/65 R17 103H	Winter tyres on Light alloy	Pirelli	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Turning brake function and evasive steering support
- Airbag for driver and front passenger, with front passenger airbag deactivation
- Anti-lock braking system (ABS)
- Exterior mirror housings and door handles in body color
- Vehicle tool kit
- Ceramique headliner
- Tiguan Decor Set
- Digital Cockpit Pro (multicoloured, various info profiles selectable)
- Electronic stability program and electromechanical brake booster
- Driving profile selection
- Windscreen made of laminated safety glass, heat-insulating
- Speed limiter with predictive control
- Back window, heater
- Infotainment system with 32 cm (12.9 inch) display
- ISOFIX mounting points for child car seats
- Rear headrests (3)
- Intersection assistant
- LED headlights
- Headlight range control
- Illuminated makeup mirrors in the sun visors
- Non-smoking version
- Emergency call service
- Upholstery: Fabric "Tiguan"
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system
- Wheels: Tire Mobility Set
- Rear View reversing camera
- electromechanical power steering
- Seat belts: Three-point automatic seat belts with belt tensioners for the outer rear seats
- Seats: Front seats with height adjustment
- Lane change assistant "Side Assist", parking assistant and exit warning
- Power outlet: 2 USB-C ports on the front
- Telephone interface
- First aid kit, warning triangle and high-visibility vest
- Prepared for later activation: Navigation system
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear
- Distraction and fatigue detection
- Airbag: Front and rear head and side airbags, center airbag
- Electrically adjustable and heated exterior mirrors
- Hill start assist
- third brake light
- black roof rails
- Diesel particulate filter
- Parking assistance
- Electronic parking brake including auto-hold function
- Automatic headlight control, with LED daytime running lights
- Electric windows front and rear
- Pedestrian protection measures expanded
- luggage compartment cover
- Transmission: 7-speed DSG
- rear window wiper
- Interior mirror automatically dimming
- "Climatronic" air conditioning system
- Front headrests
- LED taillights
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters
- front center armrest
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Radio accessories: 8 speakers
- Rain sensor
- Wheels: Light alloy (4) "Bari" 7 J x 17 (tires 215/65 R 17, optimized for rolling resistance)
- Keyless Start system
- Seat belts: Three-point automatic seat belt for the middle rear seat
- Seats: Rear bench seat
- Lane keeping assistant “Lane Assist”
- Start-stop system with brake energy recuperation
- Power outlet: 12V socket in the luggage compartment
- Bumpers in body color
- Textile floor mats front and rear
- Traffic sign recognition
- Warning tone and light for unfastened seat belts front and rear
- Central locking including remote control

Extra equipment

- Package: Infotainment package including "Discover" navigation system (2 USB-C ports in the front, 2 USB-C charging ports in the rear of the center console; charging power up to 45 W - navigation system - IDA voice assistant - "Comfort" telephone interface with inductive charging function for 2 smartphones, charging power up to 15 W)
- Mesh partition
- Package: Winter package (automatically heated front windshield washer nozzles - heated front seats)
- Paint finish: Metallic

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Indicator - front	Mirror - right side - Scratched - Replace
2	Trim / covers	Door trim - rear right side - Deformed - Replace
3	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint
4	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Wing mirror - right side	Cap - Abrasion - No deduction
2	Door - front left side	Door - dent(s) - No deduction
3	2nd wheel set	1 alloy rim - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Interior 360° view (Online Link)

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Damage 1: Indicator - front: Mirror - right side - Scratched - Replace



Damage 1: Indicator - front: Mirror - right side - Scratched - Replace



Damage 2: Trim / covers: Door trim - rear right side - Deformed - Replace



Damage 2: Trim / covers: Door trim - rear right side - Deformed - Replace




Damage 3: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 3: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 4: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint