DEKRA

DEKRA Automotive Solutions

Condition Report

Vehicle details

VIN	JMZKBAC37 0A364017	Mileage	67 182 km	Engine (Fuel) Type	Hybrid petrol
Licence Plate	2FUZ994	Registration date	02/09/2024	Engine size	1490
Brand	MAZDA	Fuel level	-	Transmission	Automatic
Model	2-Hybrid-Berlina-KBAC3-2021	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Noir		

Inspection Details

Inspection date	12/10/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique




Other technical information

Emergency compressor kit	✓	Service manual holder	✓
Refill emergency kit	✓	User manual	✓
Rear parcel shelf	✓	Warranty booklet	✓
		Spare key	✓

Tyres

Bridgestone 195/55/16 V Summer 3.0 mm

Bridgestone 195/55/16 V Summer 3.0 mm






Bridgestone 195/55/16 V Summer 4.0 mm

Bridgestone 195/55/16 V Summer 4.0 mm

Damages

1



Part	Warranty booklet
Position	-
Damages	Not conform
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	100.00€

ne possede pas de tampon

2




Part	Bumper
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	145.00€

3



Part	Alloy wheel 16"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	123.00€

4



Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	60.00€

DEKRA

DEKRA Automotive Solutions

Condition Report

5



Part	Door
Position	Inside
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	60.00€

6



Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

7



Part	Wing
Position	Back right
Damages	Dented
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

8



Part	Roof
Position	-
Damages	Dented
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

9



Part	Roof post A/B/C
Position	Right
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	60.00€

Summary Inspection

Net Price (Exclusing VAT)	548.00€