MACADAM











## BMW 5 Reeks (MKL): 2CLQ678

| | | | |
|---|---|---|---|
| Vinnumber: | **WBA31CG000CL33697** | Versionname: | **530e Touring (G31) 2.0i 292pk/cv 5p xDrive Aut.** |
| First Registrationdate: | **7/09/2022** | Fiscalpower: | |
| Expertise Mileage: | **128218** | Power Kw: | **135** |
| Bodytype: | | Type of rims (mounted) | **Aluminium** |
| Gearbox: | **Automatic** | | |
| Transmission: | | | |
| Fueltype: | **Plug-in Hybrid Petrol** | | |
| Maintenance | **OK** | | |
| Maintenance | **8000 km - 02/2028** | | |
| Battery functioning | **Yes** | | |
| Type of rims (mounted) | **Aluminium** | | |
| Certificate of Conformity | **Yes** | | |
| Category | **Passenger Car** | | |
| Registration Certificate Car (BE) | **Yes** | | |

## Options

| | | | |
|---|---|---|---|
| Number of keys total | **3** | Luggage cover | |
| GPS | | Type of Tow bar | **Tow bar collapsible** |
| Type of Maintenance book | **Digital maintenance** | | |
| Type of GPS storage | **HD** | | |

## Tyres

| | | | | |
|---|---|---|---|---|
| Summer tyres: | **245/45/18/100 Y** | | | |
| | Fr.L. | **Goodyear: 5 mm** | Fr.R. | **Goodyear: 5 mm** |
| | Re.L. | **Pirelli: 4 mm** | Re.R. | **Pirelli: 4 mm** |

| | |
|---|---|
| Tyre profile depth FL | **5.0** |
| Tyre profile depth FR | **5.0** |
| Tyre profile depth RL | **4.0** |
| Tyre profile depth RR | **4.0** |
| Tyre size FL | **245/45 R 18 100 Y** |
| Tyre size FR | **245/45 R 18 100 Y** |
| Tyre size RL | **245/45 R 18 100 Y** |
| Tyre size RR | **245/45 R 18 100 Y** |
| Tyre type FL | **Summer** |
| Tyre type FR | **Summer** |
| Tyre type RL | **Summer** |
| Tyre type RR | **Summer** |
| Tyre make FL | **259** |
| Tyre make FR | **259** |
| Tyre make RL | **264** |
| Tyre make RR | **264** |

## Assistance equipment

| | |
|---|---|
| Number of charging cables (normal) | **0** |
| Number of charging cables (rapid charge) | **1** |

**Charging cable (normal), Missing, Check**



**Bumper R, Scratch(es), Acceptable**




**Wing RR, Dent(s), Acceptable**




**Alloy rim RR, Scratch(es), Repair and paint (complete)**





**Bodywork, Paint measurement, Acceptable**



# Onderhoudshistorie van: WBA31CG000CL33697

ALPHABET

| | |
|---|---|
| **Kenteken** | 2CLQ678 |
| **Merk Model** | BMW 530e Touring (G31) 2.0i 292pk/cv 5p xDrive Aut. |
| **Brandstofsoort** | Benzine |
| **Datum deel1** | 9/7/22 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving | Bewerking |
|---|---|---|---|
| 2/3/26 | 103,074 | batterij | Vervangen |
| 2/3/26 | 103,074 | BMW/MINI service standaard omvang | Uitvoeren |
| 2/3/26 | 103,074 | BMW/MINI service voertuig-check | Uitvoeren |
| 2/3/26 | 103,074 | bougie | Vervangen |
| 2/3/26 | 103,074 | klein materiaal | |
| 2/3/26 | 103,074 | koelwatervloeistof | Bijvullen/-laden |
| 2/3/26 | 103,074 | ruitenwisserrubber achter | Vervangen |
| 2/3/26 | 103,074 | ruitenwisserrubber vooraan | Vervangen |
| 2/3/26 | 103,074 | ruitenwisservloeistof | Bijvullen/-laden |
| 2/3/26 | 103,074 | service luchtfilter | Uitvoeren |
| 2/3/26 | 103,074 | service microfilter | Uitvoeren |
| 2/3/26 | 103,074 | service motorolie | Uitvoeren |
| 7/7/25 | 84,728 | BMW/MINI service standaard omvang | Uitvoeren |
| 7/7/25 | 84,728 | klein materiaal | N.v.t. |
| 7/7/25 | 84,728 | remvloeistof | Bijvullen/-laden |
| 7/7/25 | 84,728 | ruitenwisservloeistof | Bijvullen/-laden |
| 1/13/25 | 71,623 | BMW/MINI service standaard omvang | Uitvoeren |
| 1/13/25 | 71,623 | klein materiaal | |
| 1/13/25 | 71,623 | service microfilter | Uitvoeren |
| 1/13/25 | 71,623 | service motorolie | Uitvoeren |
| 8/21/24 | 60,017 | batterij | Vervangen |
| 11/3/23 | 35,502 | BMW/MINI service standaard omvang | Uitvoeren |
| 11/3/23 | 35,502 | klein materiaal | Uitvoeren |
| 11/3/23 | 35,502 | service microfilter | Uitvoeren |
| 11/3/23 | 35,502 | service motorolie | Uitvoeren |