TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48513486
Order No. / Reference: 27212509
Inspection date: 29 Oct 2026

Manufacturer: Opel	Model: Mokka 1.2 DI Turbo Automatik Elegance
VIN: VXKUSHNSSNW046244	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Mokka 1.2 DI Turbo Automatik Elegance	
Vehicle Identification number	VXKUSHNSSNW046244
Mileage (Read)	76,238 km
First registration	5 Jul 2022
Number of holders	1
Next periodical technical inspection (Report on hand)	09/2027
Fuel type	Petrol
Engine displacement / Cylinder	1,199 ccm / 3
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Multipurpose vehicle
Colour / colour code	Jade Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Grey-Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	16,700 km
Last service on / at	08/2026 at 73,009 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ690463
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / ADB 00027		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,740 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 96V	All-season tyres on Light alloy	Uniroyal	6mm / 6mm
2)	215/60 R17 96V	All-season tyres on Light alloy	Hankook	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 ignition keys, both foldable
- Adaptive brake light
- Airbag: Front and side airbags
- Actively controlled air intakes (Active Aero Shutter)
- Electrically adjustable and heated exterior mirrors
- Exterior mirrors in black
- Roof design line in chrome
- Roof spoiler, black
- Double boot floor
- Third brake light
- Electronic Stability Program Plus (ESP Plus)
- Front collision warning with automatic city emergency braking and pedestrian detection
- Transmission: 8-speed automatic
- Child safety lock in the rear doors, manual
- Headrests (2)
- Rear headrests (3), height adjustable
- Paint finish: Metallic
- LED headlights (LED ambient lighting in door storage compartments, front - LED turn signals, front and rear - LED taillights - LED daytime running lights - LED headlights - High beam assist)
- Reading lights, front
- Center armrest, front
- Fatigue detection
- Parkpilot, rear parking aid, with acoustic warning signal when reversing.
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- Seat belts
- Seats: Passenger seat 6-way manually adjustable
- Seats: Comfort seats, front
- Seats: Pre-installation for ISOFIX child seat mounting system, rear outer
- 12-volt power outlet
- Ambient lighting
- Traffic sign recognition
- Central locking with remote control
- Storage compartments
- Driver and passenger side airbags
- Airbag: Head airbags, front and rear outer
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Hill Start Assist
- Headliner, Grey
- Decorative strips, silver
- Tachometer
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Pedestrian protection
- Cruise control with intelligent speed limiter
- Rear shelf
- Automatic climate control (with activated carbon filter, manual recirculation, automatic air distribution - footwell heating, rear - sun position sensor)
- LED fog lights
- Steering wheel: Heated leather steering wheel
- Steering wheel: Leather steering wheel, flattened at the bottom with paddle shifters
- Steering column, height and tilt adjustable
- Makeup mirror in sun visor, driver and front passenger
- Multi-collision brake
- Otto particulate filter
- Upholstery: Fabric/Premium leather look
- Radio accessories: Digital radio reception DAB+
- Side impact protection
- Speed-sensitive power steering
- Visibility equipment
- Seats: Driver's seat 6-way manually adjustable
- Seats: Rear seat backrest foldable in a 60:40 ratio
- Lane Keeping Assist
- Start/Stop System
- Traction control with engine and brake intervention TC Plus
- Underride protection look, front and rear, in silver
- Tinted heat-insulating glazing

Extra equipment

- Paint finish: Roof and A-pillar in Diamond Black
- Park & Go (Park Pilot, front and rear parking aid with audiovisual warning - 180-degree panoramic reversing camera - blind spot warning and side protection - electrically folding exterior mirrors - ambient lighting)
- Wheels: Light alloy (4) 5 double spokes 6.5 J x 17 in BiColor Black with all-weather tires (with all-weather tires 215/60/R17)
- Keyless locking and starting system "Keyless Open & Start" (keyless unlocking for driver and passenger doors as well as the luggage compartment - engine start button)
- Solar Protect heat-insulating glazing (heavily tinted, in the rear)
- Paint finish: Uni Jade White
- Radio: Multimedia Navi (with 7" color touchscreen display and fully digital 7" driver information display - Navigation with integrated memory - European road map - 3D map display - Dynamic route guidance via map and/or arrow display - Display of points of interest - Trip plan. - OpelConnect GPS module, including LIVE navigation services: - Map updates. - Voice control for audio, telephone and navigation. - Radio, Bluetooth, DAB+, USB, hands-free.)
- Seats: Heated seats, multi-stage, driver and front passenger

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Door - front left side	Door handle - inside - Malposition - Perform diagnosis
3	Roof	Stub aerial (Bissspuren) - Damage caused by marten / rodent - Replace
4	Equipment	Vehicle key with remote control (Batterie) - Empty - Replace
5	Equipment	Tirefit filler - Empty - Replace
6	Interior	Cargo area floor (Farbe o.ä) - Soiled - Clean
7	Door - front right side	Door edge - Scratch(es) - Smart repair
8	Instrument panel	Instrument panel (Handyhalterung o.ä) - Glued / labelled - De-glue / neutralise
9	Mudguard - right side	Wheel well extension - Scratched - Replace
10	Door - rear right side	Door - dent(s) - Smooth repair work
11	Roof	Roof rail - right side - dent(s) - Smooth repair work
12	Side panel - rear left side	Sill - Dent / paintcoat damage - Smart repair
13	Wheel / tyres	Alloy rim - front left side (Flanke) - Deformed - Replace
14	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
15	Trim / covers	Boot sill cover (Schlossabdeckung) - Broken / torn - Replace
16	Trim / covers	Roof lining - Burn hole (cigarettes) - Smart repair
17	Door - front right side	Brightware - upper - Dent / paintcoat damage - Replace
18	Instrument panel	Centre console - front (Materialabtrag) - Scratched - Replace
19	Roof	Roof rail - left side (Einätzungen, Mehrkosten sind möglich) - Paint defect - Conditioning
20	Trim / covers	Door trim - rear left side - Scratched - Replace
21	Door - front left side	Door - Dent / paintcoat damage - Repair and paint
22	Side panel - rear right side	Sill - Dent / paintcoat damage - Smart repair
23	Rear bumper	Rear bumper (Verkratzt) - Deformed - Repair and paint
24	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
25	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
26	Roof	Roof (Einätzungen,Dellen, Farbe o.ä) - Paint defect - Paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Scratch(es) - No deduction
2	Trim / covers	Floor mats - Broken / torn - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Documents - Service book

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 29 Nov 2023	657,17 €
2	Side - left, Provided by user / customer, from 23 Aug 2024	5.443,67 €

Accident damages

No.	Accident
1	Rear, Side right
2	Side - left

Repainting

No.	Repainting
1	Mudguard - left side, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent
3	Door - rear left side, Professionally carried out, Invoice of repair done Non-existent
4	Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - left side	175 µm	Side panel - rear left side	205 µm
Door - rear left side	176 µm	Door - front left side	167 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster




Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Navigation



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Damage 2: Door - front left side: Door handle - inside - Malposition - Perform diagnosis



Damage 2: Door - front left side: Door handle - inside - Malposition - Perform diagnosis




Damage 2: Door - front left side: Door handle - inside - Malposition - Perform diagnosis



Damage 2: Door - front left side: Door handle - inside - Malposition - Perform diagnosis



Damage 3: Roof: Stub aerial (Bissspuren) - Damage caused by marten / rodent - Replace



Damage 3: Roof: Stub aerial (Bissspuren) - Damage caused by marten / rodent - Replace



Damage 5: Equipment: Tirefit filler - Empty - Replace



Damage 6: Interior: Cargo area floor (Farbe o.ä) - Soiled - Clean




Damage 6: Interior: Cargo area floor (Farbe o.ä) - Soiled - Clean



Damage 7: Door - front right side: Door edge - Scratch(es) - Smart repair




Damage 7: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 8: Instrument panel: Instrument panel (Handyhalterung o.ä) - Glued / labelled - De-glue / neutralise




Damage 8: Instrument panel: Instrument panel (Handyhalterung o.ä) - Glued / labelled - De-glue / neutralise



Damage 9: Mudguard - right side: Wheel well extension - Scratched - Replace



Damage 9: Mudguard - right side: Wheel well extension - Scratched - Replace



Damage 10: Door - rear right side: Door - dent(s) - Smooth repair work




Damage 10: Door - rear right side: Door - dent(s) - Smooth repair work




Damage 11: Roof: Roof rail - right side - dent(s) - Smooth repair work




Damage 11: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage 11: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage 11: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage 12: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 12: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair




Damage 13: Wheel / tyres: Alloy rim - front left side (Flanke) - Deformed - Replace



Damage 13: Wheel / tyres: Alloy rim - front left side (Flanke) - Deformed - Replace



Damage 14: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 14: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 14: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 15: Trim / covers: Boot sill cover (Schlossabdeckung) - Broken / torn - Replace




Damage 15: Trim / covers: Boot sill cover (Schlossabdeckung) - Broken / torn - Replace



Damage 16: Trim / covers: Roof lining - Burn hole (cigarettes) - Smart repair




Damage 16: Trim / covers: Roof lining - Burn hole (cigarettes) - Smart repair



Damage 16: Trim / covers: Roof lining - Burn hole (cigarettes) - Smart repair



Damage 16: Trim / covers: Roof lining - Burn hole (cigarettes) - Smart repair




Damage 17: Door - front right side: Brightware - upper - Dent / paintcoat damage - Replace



Damage 17: Door - front right side: Brightware - upper - Dent / paintcoat damage - Replace




Damage 17: Door - front right side: Brightware - upper - Dent / paintcoat damage - Replace



Damage 18: Instrument panel: Centre console - front (Materialabtrag) - Scratched - Replace



Damage 18: Instrument panel: Centre console - front (Materialabtrag) - Scratched - Replace




Damage 19: Roof: Roof rail - left side (Einätzungen, Mehrkosten sind möglich) - Paint defect - Conditioning



Damage 19: Roof: Roof rail - left side (Einätzungen, Mehrkosten sind möglich) - Paint defect - Conditioning



Damage 19: Roof: Roof rail - left side (Einätzungen, Mehrkosten sind möglich) - Paint defect - Conditioning



Damage 19: Roof: Roof rail - left side (Einätzungen, Mehrkosten sind möglich) - Paint defect - Conditioning



Damage 20: Trim / covers: Door trim - rear left side - Scratched - Replace




Damage 20: Trim / covers: Door trim - rear left side - Scratched - Replace



Damage 20: Trim / covers: Door trim - rear left side - Scratched - Replace



Damage 20: Trim / covers: Door trim - rear left side - Scratched - Replace



Damage 20: Trim / covers: Door trim - rear left side - Scratched - Replace



Damage 21: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 21: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 21: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 21: Door - front left side: Door - Dent / paintcoat damage - Repair and paint




Damage 21: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 21: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 21: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 22: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 22: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 22: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 22: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair




Damage 22: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 23: Rear bumper: Rear bumper (Verkratzt) - Deformed - Repair and paint



Damage 23: Rear bumper: Rear bumper (Verkratzt) - Deformed - Repair and paint



Damage 23: Rear bumper: Rear bumper (Verkratzt) - Deformed - Repair and paint



Damage 23: Rear bumper: Rear bumper (Verkratzt) - Deformed - Repair and paint



Damage 23: Rear bumper: Rear bumper (Verkratzt) - Deformed - Repair and paint



Damage 24: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 24: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 24: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 25: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 25: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 25: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 25: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 25: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 26: Roof: Roof (Einätzungen,Dellen, Farbe o.ä) - Paint defect - Paint




Damage 26: Roof: Roof (Einätzungen,Dellen, Farbe o.ä) - Paint defect - Paint



Damage 26: Roof: Roof (Einätzungen,Dellen, Farbe o.ä) - Paint defect - Paint




Damage 26: Roof: Roof (Einätzungen,Dellen, Farbe o.ä) - Paint defect - Paint




Damage 26: Roof: Roof (Einätzungen,Dellen, Farbe o.ä) - Paint defect - Paint



Damage 26: Roof: Roof (Einätzungen,Dellen, Farbe o.ä) - Paint defect - Paint



Damage 26: Roof: Roof (Einätzungen,Dellen, Farbe o.ä) - Paint defect - Paint



Damage 26: Roof: Roof (Einätzungen,Dellen, Farbe o.ä) - Paint defect - Paint



Wear and tear 2: Trim / covers: Floor mats - Broken / torn - No deduction



Wear and tear 2: Trim / covers: Floor mats - Broken / torn - No deduction



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right




Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 2: Side - left



Accident 2: Side - left



Accident 2: Side - left



Accident 2: Side - left



Accident 2: Side - left



Accident 2: Side - left



Accident 2: Side - left



Accident 2: Side - left



Accident 2: Side - left



Accident 2: Side - left



Accident 2: Side - left



Accident 2: Side - left



Accident 2: Side - left



Repainting 1: Mudguard - left side



Repainting 2: Side panel - rear left side



Repainting 3: Door - rear left side



Repainting 4: Door - front left side