BMW

VIN: WBA6L51080FJ67391

Estimated repair cost

258.75 EUR
TOTAL



Description

Registration number	Registration date	Odometer
2CHP508	-	52270 km
Color	**Year**	**Upholstery**
-	-	-
Number of doors	**Number of seats**	**Generation**
-	-	-

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction	net cost
001	Rim / Front Left Rim/Tyre diameter : 17 " / Surface : Painted	Scratched	Smart repair	165.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	**165.00 EUR**
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

002	Front face / -	Chip	Acceptable	-

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

003	Bonnet / - [1]	Dent	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

004	Bumper moulding / Front Left Painted : Yes	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

005	Door / Back Left	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

006	Door sill / Back Left	Scratched	Polishing	37.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	-	-	

007	Bumper / Back Painted : Yes	Scratched	Polishing	37.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	-	-	

008	Interior tailgate lining / - Trim material : Plastic	Scratched	Acceptable	-

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

009	Wing / Back Right Windowed : Yes	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

010	Door / Back Right	Scratched	Polishing	18.75 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.25 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
18.75 EUR	-	-	

011	Door sill / Back Right	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

012	Grille chrome moulding / Front Chromed : Yes	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

[1] +kras

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Loose Items

- [x] Rear parcel shelf
- [x] Document holder
- [x] Registration certificate owner
- [ ] Load cover
- [ ] Charging cable bag
- [ ] Spare wheel tyre
- [ ] In-car tools
- [x] Tyre repair kit complete
- [ ] Triangle
- [x] User manual
- [ ] Slow charging cable (Type 2, Mode 2)
- [x] Registration certificate
- [ ] Service book
- [ ] Compressor tyre repair kit
- [ ] First aid kit
- [ ] Jack
- [ ] Refill tyre repair kit
- [x] Spare Key
- [ ] Quick charging cable (Type 2, Mode 3)

Main set of tyres

Front Left	UNIROYAL	225 / 50 / 17 / All	5 mm
Front Right	UNIROYAL	225 / 50 / 17 / All	5 mm
Back Left	UNIROYAL	225 / 50 / 17 / All	5 mm
Back Right	UNIROYAL	225 / 50 / 17 / All	5 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left



Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment



Front right


Odometer



Spare Tyre



Vin


Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Front face / - / Chip



Bonnet / - / Dent



Bonnet / - / Dent



Bonnet / - / Dent



Bumper moulding / Front Left / Scratched



Bumper moulding / Front Left / Scratched



Door / Back Left / Scratched



Door / Back Left / Scratched



Door / Back Left / Scratched



Door sill / Back Left / Scratched



Door sill / Back Left / Scratched



Bumper / Back / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Interior tailgate lining / - / Scratched



Wing / Back Right / Scratched



Wing / Back Right / Scratched



Door / Back Right / Scratched



Door / Back Right / Scratched



Door / Back Right / Scratched



Door sill / Back Right / Scratched



Door sill / Back Right / Scratched



Grille chrome moulding / Front / Scratched



Grille chrome moulding / Front / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.