MACADAM

Polestar Polestar 2 '19 BEV


Vehicle information

Make:	**Polestar**	License:	
Gearbox:	**Automatic**	Body color:	
Model:	**Polestar 2 '19 BEV**	VIN:	**LPSVSEGEKNL051618**
Fuel type:	**Electric**	Power:	**170 kW**
Version:	**78kWh Sing.M.Lo.Ra.**	First registration	**05/10/2021**
Mileage:	**214607 km**	N° of doors:	

Damage summary

Front	1
Interior	1
Left	2
Right	2

Commercial pictures


Trip
Trip handmatig (TM)
1 842.2 km
22.2 kWh/100km
38:44 h
10 km/h
Trip automatisch (TA)
111.3 km
17.0 kWh/100km
01:24 h
82 km/h
ODO 214 907 km





LPSVSEGEKNL051618














14:32


14:31


Batterijcertificaat
Datum van diagnose: 30/10/2026
88,79%
Status van de gezondheid (SOH)*
Polestar 2 LR Single motor
VIN : LPSVSEGEKNL051618
Kilometerstand : 214.607 km
* SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA



Options according to the inspector

Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Radio multimedia	**Yes**	Rear view camera	**Yes**	Telephone equipment	**Yes**

Damages

Alloy rim FL
Scratch(es)
Repair and paint (complete)
Left




Alloy rim FR
Scratch(es)
Repair and paint (complete)
Right





Bonnet
Deformed / Strained
Repair and paint (complete)
Front




Door FR
Scratch(es)
Repair and paint (complete)
Right




Door RL
Deformed / Strained
Repair and paint (complete)
Left




Ignition key
Worn
Replace
Interior





Tyres

Front Left	
Summer	
245/45/19/102/Y	
Hankook	
3.8 mm	
Front Right	
Summer	
245/45/19/102/Y	
Hankook	
3.0 mm	
Rear Left	
Summer	
245/45/19/102/Y	
Hankook	
6.2 mm	
Rear Right	
Summer	
245/45/19/102/Y	
Hankook	
4.0 mm	

Checks

CO2 Emission	**0**	Digital maintenance	**Yes**
GPS storage	**Yes**	Luggage cover	**Yes**
Number head rests	**5**	Number of charging cables (rapid charge)	**1**
Number of keys total	**2**	Reset to factory settings	**No, not possible**
Service book	**N/A**	User's manual	**Yes**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.