TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48565372
Order No. / Reference: 27290548
Inspection date: 6 Nov 2026

Manufacturer: Volkswagen	Model: Crafter 35 TDI VA
VIN: WV1ZZZSYZL9057211	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Crafter 35 TDI VA	
Vehicle Identification number	WV1ZZZSYZL9057211
Mileage (Read)	49,668 km
First registration	21 Aug 2020
Number of holders	1
Next periodical technical inspection	08/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	103 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Reflexsilber Metallic
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	18,900 km
Last service on / at	08/2026 at 48,505 km		
Key is / should be	3 / 4	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FU572777
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CBY 42737		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	All-season tyres on Steel	Continental	6mm / 6mm
2)	235/65 R16 115R	All-season tyres on Steel	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	235/65 R16 115R C	All-season tyres on Steel	Continental	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Driver's side
- Hill Start Assist
- Floor coverings: Rubber floor covering in the driver's cab
- Three-point automatic seat belts
- Chassis: Suspension and damping, standard
- Total weight: Vehicle registration with a permissible total weight of 3.5 t
- Rear wing door without window cutout
- Instrument usage (km/h)
- Steering wheel adjustable in height and reach
- Multifunction display "Plus"
- Upholstery: Seat covers in fabric, design "Austin"
- Wheels/Tires: 235/65 R 16 C 115/113 R, optimized for low rolling resistance
- Keys for locking system: 2 remote control flip keys
- electromechanical power steering
- Seats 1st row: Seat on the right
- Power outlet: 12V socket and 4 cup holders in the dashboard
- Daytime running light
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control and interior operation
- Registration as a truck
- Convex exterior mirrors (left and right), with integrated LED turn signal and wide-angle range
- third brake light
- Electronic Stability Program and ABS
- Electric windows, front
- Transmission: 6-speed transmission
- Weight class front axle
- Rear doors/tailgate: Hinges for rear doors
- Headrests (2)
- Headlight range control
- Particulate filter: Soot particle filter for diesel engines
- Wheel cover center
- Wheels: Steel wheels 6.5 J x 16, in silver
- Sliding door, on the right in the passenger/cargo area
- Crosswind assist
- Seatbelt check
- Start-stop system
- Power outlets: 2 12V sockets in the driver's cab (in the dashboard)
- Partition walls: Partition wall
- Lashing eyes for securing cargo
- thermal insulation glazing
- Accessories: On-board tools

Extra equipment

- Storage package 2: Roof gallery with two 1-DIN slots and reading light
- Air conditioning in the driver's cab with electric control
- Marker lights, side
- "Discover Media" radio navigation system including "Streaming & Internet" with 4 speakers (voice control - 2 USB ports (Type C) in the dashboard - illuminated glove compartment with lockable flap - "Discover Media" radio navigation system with 20.3 cm (8 inch) touchscreen including "Streaming and Internet" - 4 speakers: 2 tweeters, 2 woofers - Wired & Wireless App-Connect - mobile phone interface)
- Auxiliary heaters/parking heaters: Water-based auxiliary heater with programmable parking heater function (with radio remote control)
- Electrically adjustable and heated exterior mirrors
- Suspension/damping, reinforced
- Paint finish: Metallic
- ParkPilot in the front and rear areas
- Wheels, tires: All-season tires
- Wheels, tires: spare wheel (steel rim) with driving tires, as well as on-board tools and jack
- Keys for locking system (4 wireless folding keys)
- Seats 1st row: Comfort seat "Plus" on the left, in the 1st row
- Seat heating, left and right, separately adjustable, in the 1st row of seats
- Rear step, across the entire width

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Brightware - Scratch(es) - Loss in value
2	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
3	Front bumper	Front bumper (unpainted) - Scratch(es) - Loss in value
4	Door - front right side	Door - Dent / paintcoat damage - Paint

Wear and tear

No.	Component group	Description
1	Rear of vehicle	Foot plate - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Vehicle key

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Side right, Professionally repaired, Invoice of repair done Non-existent	

Repainting

No.	Repainting
1	Mudguard - left side, Door - rear right side, Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - left side	215 µm	Door - rear right side	599 µm
Door - front left side	182 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Damage 1: Side panel - rear right side: Brightware - Scratch(es) - Loss in value




Damage 1: Side panel - rear right side: Brightware - Scratch(es) - Loss in value



Damage 1: Side panel - rear right side: Brightware - Scratch(es) - Loss in value



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work




Damage 3: Front bumper: Front bumper (unpainted) - Scratch(es) - Loss in value



Damage 3: Front bumper: Front bumper (unpainted) - Scratch(es) - Loss in value



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Paint



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Paint



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Paint



Repainting 1: Mudguard - left side, Door - rear right side, Door - front left side



Repainting 1: Mudguard - left side, Door - rear right side, Door - front left side



Repainting 1: Mudguard - left side, Door - rear right side, Door - front left side