TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48411423
Order No. / Reference: 27192764
Inspection date: 27 Oct 2026

Manufacturer: Ford	Model: Transit Connect 230 L2 S&S Trend
VIN: WF07XXWPG7NY73424	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit Connect 230 L2 S&S Trend	
Vehicle Identification number	WF07XXWPG7NY73424
Mileage (Read)	137,700 km
First registration	1 Apr 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	73 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frost-Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	42 %
Last service on / at	04/2026 at 120,352 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GH430228
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BUT 00234		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,300 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Steel rim with wheel cover	Dunlop	4mm / 4mm
2)	205/60 R16 96H	Winter tyres on Steel rim with wheel cover	Dunlop	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/60 R16 96H	Summer tyres on Steel	Continental	5 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS with EBD
- Airbag package
- Exterior mirrors, narrow mirror format
- Battery (12 V / 71h)
- Floor covering: Carpet (1st and 2nd row)
- Diesel particulate filter (DPF)
- Third brake light
- Fixed rear windows, right and left (at the height of the 3rd row of seats)
- Front electric windows
- Ford ECO-Coach
- Heated windshield
- Rubberized luggage compartment floor mat
- Cruise control system with intelligent speed limiter (camera-based)
- Heated rear windows
- Front interior lighting with delay function
- Front air conditioning including semi-electronic recirculation system
- Alternator/Generator
- Fog light
- Camera-based pre-collision assist
- Wheels: Steel wheels 6.5 J x 16 with 205/60 R 16 tires and wheel trims
- Electro-mechanical power steering
- Automatic door locking mechanism (45 sec.)
- Seats: Seat package 22 (fabric "Capitol/City" in Ebony (black) - driver's seat, 3-way manually adjustable (forward/backward, height, backrest) - single passenger seat, 2-way manually adjustable (forward/backward, backrest), foldable - headrests, height-adjustable - lumbar support, manual (driver's seat) - map pockets for driver and passenger seats - airbag package for driver and passenger seats)
- Front bumper and rear bumper end caps painted in body color
- Child safety lock on sliding doors
- Lashing eyes
- Electronic immobilizer (EPATS)
- Central locking with remote control
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- Exterior mirror housing black
- Hill start assist
- On-board computer including outside temperature display
- Tachometer
- Electronic Safety and Stability Program (ESP)
- Rear electric windows, right and left (at the height of the 2nd row of seats)
- Ford Easy Fuel
- FordPass Connect
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Transmission: 6-speed transmission
- Glove compartment with lid
- Rear window wiper/washer system
- Isofix mount
- Paint finish: Solid
- Steering column, adjustable in height and reach
- Center console, front
- Emergency brake light
- Tire pressure monitoring system
- Sliding door, right and left
- Side protection strips, plastic
- Safety brake assist
- Passenger compartment seats: 2nd row (bench seat, 60:40 split, foldable, can be lowered into the footwell - ISOFIX mounting on the outer seats)
- Front spoiler lip
- Start-stop system
- Dust and pollen filter
- Concealed storage compartment
- Power outlet: 12-volt connection on the center console, front and rear
- Daytime running light
- Carpet floor mats, front (2-piece set)
- Door handles, black
- Warning system for unfastened seat belts
- Heat-insulating glazing, lightly tinted
- Auxiliary electric heater (PTC), front

Extra equipment

- Detachable towbar (including ESP trailer stabilization and continuous power supply)
- Faux leather seat cover for driver and passenger seats
- Package: Passenger car version package with double rear doors (folding front passenger seat, lane keeping assist, lane departure warning, driver drowsiness detection, cruise control, integrated speed limiter (camera-based), traffic sign recognition system, IPS: front and side airbags, front/rear head/shoulder airbags, seat belt tensioners and force limiters, safety pedals and steering column, 3-point seat belts at all seats, height-adjustable front seats, pre-collision assist, pedestrian/cyclist detection, tire pressure monitoring system (TPMS). (Without partition and safety net)
- Spare wheel: Steel wheel
- Rotating beacon
- Safety partition net for separating passenger and luggage compartments (including attachment points (retrofitting not possible later))
- lettering
- Adaptive cruise control (with intelligent speed limiter - including radar- and camera-based pre-collision assist with pedestrian and cyclist detection, lane keeping assist including lane keeping assist and driver drowsiness detection - including traffic sign recognition system - leather multifunction steering wheel with 4 spokes in aluminum trim)
- Front and rear parking pilot system
- Radio: Ford Audio System 9 (Ford navigation system incl. Ford SYNC 3 with AppLink, 6" touchscreen radio (FM/AM), 2 USB ports, audio remote control on the steering wheel, Bluetooth hands-free system and audio streaming, emergency call assistant, SMS text-to-speech function, SMS sending function, voice control, reversing camera, phase diversity antenna, DAB/DAB+, acoustic and visual route guidance, road map for Europe, TMCpro live traffic, detailed 3D visualization, Michelin travel guide for Europe)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - Incomplete - No deduction
2	Wheel / tyres	Spare wheel (Locker, wackelt) - Loose - Un- / install
3	Mudguard - left side	Mud flap - Broken / torn - Replace
4	Engine	Engine cover (Dämmung) - Damage caused by marten / rodent - Replace
5	Boot lid / rear door	Reflectors (Heck rechts) - Broken / torn - Replace
6	Engine cooling	Coolant (Weit unter minimum) - Missing - Perform diagnosis
7	Exhaust system	Heat shield - Broken / torn - Replace
8	Wheel / tyres	Tyre - front right side (Flanke) - Damaged - Replace
9	Instrument panel	Centre console - front (Abdeckung unter Lenkrad) - Scratched - Replace
10	Rear bumper	Rear bumper (unpainted) - Scratched - Loss in value
11	Engine	Engine (Extrem Ölfeucht) - Leaking - Perform diagnosis
12	Sliding door, right	Sliding door with glass panel - Dent / paintcoat damage - Smart repair
13	Seat - rear	Headrest - 2nd row (Mitte) - Scratched - Replace
14	Interior	Interior (Extrem) - Soiled - Clean
15	Body	Underbody (Extrem, Beton o.ä) - Soiled - Conditioning
16	Front bumper	Front bumper (Unterteil) - Scratch(es) - Paint
17	Boot lid / rear door	Rear door - right side - Deformed - Repair and paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Door - front left side	Door edge - Scratch(es) - No deduction
4	Side panel - rear left side	Side panel - dent(s) - No deduction
5	Interior	Interior - Scratch(es) - No deduction
6	Sliding door - left side	Sliding door with glass panel - dent(s) - No deduction
7	Door - front left side	Door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Trim / covers - Floor mats (Vorne rechts)
Trim / covers - Floor mats (Hinten rechts)
Rear of vehicle - Key trailer hitch
Documents - Service book

Repainting

No.	Repainting
1	Bonnet, Professionally carried out, Invoice of repair done Non-existent
2	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
3	Door - front left side, Professionally carried out, Invoice of repair done Non-existent
4	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Bonnet	164 µm	Door - rear right side	147 µm
Door - front left side	145 µm	Door - front right side	148 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN




Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.







Figure 31: Misc.



Damage 1: Misc.: Inspection / maintenance - Incomplete - No deduction



Damage 1: Misc.: Inspection / maintenance - Incomplete - No deduction



Damage 1: Misc.: Inspection / maintenance - Incomplete - No deduction



Damage 2: Wheel / tyres: Spare wheel (Locker, wackelt) - Loose - Un- / install



Damage 2: Wheel / tyres: Spare wheel (Locker, wackelt) - Loose - Un- / install




Damage 3: Mudguard - left side: Mud flap - Broken / torn - Replace



Damage 3: Mudguard - left side: Mud flap - Broken / torn - Replace



Damage 3: Mudguard - left side: Mud flap - Broken / torn - Replace



Damage 4: Engine: Engine cover (Dämmung) - Damage caused by marten / rodent - Replace




Damage 4: Engine: Engine cover (Dämmung) - Damage caused by marten / rodent - Replace




Damage 5: Boot lid / rear door: Reflectors (Heck rechts) - Broken / torn - Replace




Damage 5: Boot lid / rear door: Reflectors (Heck rechts) - Broken / torn - Replace



Damage 6: Engine cooling: Coolant (Weit unter minimum) - Missing - Perform diagnosis



Damage 6: Engine cooling: Coolant (Weit unter minimum) - Missing - Perform diagnosis



Damage 7: Exhaust system: Heat shield - Broken / torn - Replace



Damage 7: Exhaust system: Heat shield - Broken / torn - Replace



Damage 7: Exhaust system: Heat shield - Broken / torn - Replace



Damage 8: Wheel / tyres: Tyre - front right side (Flanke) - Damaged - Replace



Damage 8: Wheel / tyres: Tyre - front right side (Flanke) - Damaged - Replace



Damage 9: Instrument panel: Centre console - front (Abdeckung unter Lenkrad) - Scratched - Replace



Damage 9: Instrument panel: Centre console - front (Abdeckung unter Lenkrad) - Scratched - Replace



Damage 9: Instrument panel: Centre console - front (Abdeckung unter Lenkrad) - Scratched - Replace



Damage 10: Rear bumper: Rear bumper (unpainted) - Scratched - Loss in value




Damage 10: Rear bumper: Rear bumper (unpainted) - Scratched - Loss in value




Damage 10: Rear bumper: Rear bumper (unpainted) - Scratched - Loss in value



Damage 10: Rear bumper: Rear bumper (unpainted) - Scratched - Loss in value



Damage 11: Engine: Engine (Extrem Ölfeucht) - Leaking - Perform diagnosis



Damage 11: Engine: Engine (Extrem Ölfeucht) - Leaking - Perform diagnosis



Damage 12: Sliding door, right: Sliding door with glass panel - Dent / paintcoat damage - Smart repair



Damage 12: Sliding door, right: Sliding door with glass panel - Dent / paintcoat damage - Smart repair



Damage 12: Sliding door, right: Sliding door with glass panel - Dent / paintcoat damage - Smart repair



Damage 13: Seat - rear: Headrest - 2nd row (Mitte) - Scratched - Replace



Damage 13: Seat - rear: Headrest - 2nd row (Mitte) - Scratched - Replace



Damage 14: Interior: Interior (Extrem) - Soiled - Clean



Damage 15: Body: Underbody (Extrem, Beton o.ä) - Soiled - Conditioning



Damage 15: Body: Underbody (Extrem, Beton o.ä) - Soiled - Conditioning




Damage 15: Body: Underbody (Extrem, Beton o.ä) - Soiled - Conditioning




Damage 15: Body: Underbody (Extrem, Beton o.ä) - Soiled - Conditioning



Damage 15: Body: Underbody (Extrem, Beton o.ä) - Soiled - Conditioning



Damage 15: Body: Underbody (Extrem, Beton o.ä) - Soiled - Conditioning



Damage 15: Body: Underbody (Extrem, Beton o.ä) - Soiled - Conditioning




Damage 16: Front bumper: Front bumper (Unterteil) - Scratch(es) - Paint



Damage 16: Front bumper: Front bumper (Unterteil) - Scratch(es) - Paint



Damage 16: Front bumper: Front bumper (Unterteil) - Scratch(es) - Paint



Damage 16: Front bumper: Front bumper (Unterteil) - Scratch(es) - Paint



Damage 16: Front bumper: Front bumper (Unterteil) - Scratch(es) - Paint




Damage 17: Boot lid / rear door: Rear door - right side - Deformed - Repair and paint



Damage 17: Boot lid / rear door: Rear door - right side - Deformed - Repair and paint



Damage 17: Boot lid / rear door: Rear door - right side - Deformed - Repair and paint



Damage 17: Boot lid / rear door: Rear door - right side - Deformed - Repair and paint



Wear and tear 6: Sliding door - left side: Sliding door with glass panel - dent(s) - No deduction



Wear and tear 6: Sliding door - left side: Sliding door with glass panel - dent(s) - No deduction



Wear and tear 7: Door - front left side: Door - dent(s) - No deduction



Wear and tear 7: Door - front left side: Door - dent(s) - No deduction




Missing part 1: Trim / covers: Floor mats (Vorne rechts) - Missing - Replace



Missing part 2: Trim / covers: Floor mats (Hinten rechts) - Missing - Replace



Missing part 3: Rear of vehicle: Key trailer hitch - Missing - Replace



Missing part 4: Documents: Service book - Missing - Replace



Repainting 1: Bonnet



Repainting 2: Door - rear right side



Repainting 3: Door - front left side



Repainting 4: Door - front right side