TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48513710
Order No. / Reference: 27238567
Inspection date: 5 Nov 2026

Manufacturer: Volkswagen	Model: Passat Variant 2.0 TDI SCR DSG Conceptline
VIN: WVWZZZ3CZPE009528	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Passat Variant 2.0 TDI SCR DSG Conceptline	
Vehicle Identification number	WVWZZZ3CZPE009528
Mileage (Read)	142,847 km
First registration	11 Oct 2022
Number of holders	1
Next periodical technical inspection (Report on hand)	12/2027
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Scale Silver Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	7,800 km
Last service on / at	12/2025 at 120,593 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM698578
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / BQS 03667		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,200 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 99V	All-season tyres on Steel rim with wheel cover	Continental	3mm / 3mm
2)	215/60 R16 99V	All-season tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors
- Hill start assist
- Headliner in Mistral Grey
- Diesel particulate filter
- Electronic parking brake including auto-hold function
- Remote release for luggage compartment lid
- Windscreen made of laminated safety glass, heat and sound insulating
- Transmission: 7-speed DSG
- ISOFIX mounting points
- Rear headrests (3)
- Paint finish: Solid
- LED headlights with daytime running lights
- Headlight range control
- Front center armrest, height and length adjustable, with storage box
- Mesh partition
- Emergency call service
- Radio accessories: Digital radio reception DAB+
- Wheels: 4 steel wheels 6.5 J x 16
- Rear bench seat, undivided, backrest asymmetrically split and foldable, with center armrest
- Power steering
- Seats: Front seats are height-adjustable
- Start-stop system
- Bumpers in body color
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Black trim strips on the side windows
- Airbag, head airbag system for front and rear passengers
- App-Connect
- Cup holders (2) front
- third brake light
- black roof rails
- Tachometer
- Electronic stability program and electromechanical brake booster
- Adjustable luggage compartment floor
- Cruise control system including speed limiter
- Interior lights front and rear with switch-off delay and dimming function
- Front headrests
- LED taillights
- Steering wheel: Multifunction steering wheel
- Makeup mirrors in the sun visors
- Multifunction display "Plus"
- Fatigue detection
- Non-smoking version
- Upholstery: "Lizard" fabric
- Tire pressure monitoring system (passive)
- Wheels: Tires 215/60 R16
- Gearshift knob in leather
- Keyless start system without safe locking
- Seat belts: Three-point automatic seat belt
- Lane keeping assistant “Lane Assist”
- 12V power outlet on the rear of the center console
- Telephone interface
- Warning tone and light for unfastened seat belts front and rear

Extra equipment

- Parking aid - warning signals for obstacles in the front and rear area
- LED fog lights and cornering lights
- Package: "Business Premium" package including navigation (230V socket on the rear center console - App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto - "Air Care Climatronic" air conditioning with 3-zone temperature control and active combination filter - "Rear View" reversing camera - automatically heated front windshield washer nozzles - "Comfort" telephone interface with inductive charging function - heated front seats)
- Wheels: Tire Mobility Set omitted
- Voice control
- Interior mirror automatically dimming
- Paint finish: Metallic
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters
- Package: Luggage management package (fixing strap and lashing eyes that can be fixed on 4 rails - sliding luggage compartment floor - stainless steel loading sill protector)
- Package: Seat comfort package (front passenger seat backrest fully foldable - lumbar support in front)
- Wheels: 4 all-season tires 215/60 R 16 (AirStop all-season tires - Tire Mobility Set not included)
- Rear side windows and rear window tinted
- Textile floor mats (front and rear)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Vehicle glazing	Windscreen (Zierleiste links) - Scratch(es) - Replace
2	Wing mirror - right side	Cap - Scratch(es) - Smart repair
3	Side panel - rear right side	Side panel - dent(s) - Smart repair
4	Front bumper	Front bumper - Scratch(es) - Smart repair
5	Wheel / tyres	Tyre - front - Does not meet the leasing specifications - Replace
6	Rear bumper	Rear bumper - Scratch(es) - Paint
7	Vehicle glazing	Windscreen (kein Staubschutz) - Stone chips - repair according to calculation

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.





Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Damage 1: Vehicle glazing: Windscreen (Zierleiste links) - Scratch(es) - Replace



Damage 1: Vehicle glazing: Windscreen (Zierleiste links) - Scratch(es) - Replace




Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 3: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 3: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 5: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Paint

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck



Damage 6: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 7: Vehicle glazing: Windscreen (kein Staubschutz) - Stone chips - repair according to calculation



Damage 7: Vehicle glazing: Windscreen (kein Staubschutz) - Stone chips - repair according to calculation