TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 47210797
Order No. / Reference: 26837648-1
Inspection date: 14 Aug 2026

Manufacturer: Opel	Model: Zafira Life 2.0 D M Edition
VIN: VXEVEEHTMMZ071507	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Zafira Life 2.0 D M Edition	
Vehicle Identification number	VXEVEEHTMMZ071507
Mileage (Read)	188,623 km
First registration	4 Aug 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,997 ccm / 4
Power	106 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Jade Weiß
Doors / Seats	5 / 8
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	49,980 km
Last service on / at	07/2026 at 188,618 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA238383
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	3003 / BBV 00225		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,760 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101W	Summer tyres on Light alloy	Goodyear	6mm / 6mm
2)	225/55 R17 101W	Summer tyres on Light alloy	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101V	Winter tyres on Light alloy	Dunlop	3mm / 6mm
2)	225/55 R17 101V	Winter tyres on Light alloy	Dunlop	6mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Low beam automatically
- Airbag for driver and passenger side
- Airbag: Curtain airbags, in the 2nd and 3rd rows of seats
- Automatic activation of the hazard warning lights
- Exterior mirror housings in body color
- On-board computer
- Diesel particulate filter
- Electronic Stability Program (ESP Plus)
- Electric front windows
- luggage compartment cover
- Glazed tailgate, with rear window wiper and heater
- Child safety lock, mechanical
- Automatic climate control: Dual-zone automatic climate control
- Headlight range adjustment, manual
- Package: Driver Assistance Package 1
- Rear parking pilot
- Radio: Multimedia radio with 7" touchscreen color display
- Tire repair kit
- Wheels: Alloy wheels in bicolor, 7J x 17
- Power steering
- Safety steering column, height and length adjustable
- Heated seats for driver and front passenger
- Sun visors driver and passenger side
- 12V socket
- Door: Sliding door, driver and passenger side
- Immobiliser
- Ignition key (2)
- Storage compartments
- Airbag: Head airbags, driver and front passenger
- Anti-lock braking system (ABS)
- Exterior mirrors, electrically adjustable, heated and folding
- Hill Start Assist
- third brake light
- Tachometer
- Window: Window, driver's side in the 2nd row of seats, fixed
- Transmission: 6-speed manual transmission
- Interior rearview mirror, automatically dimming
- Air conditioning: Auxiliary air conditioning, rear
- Paint finish: Solid
- LED daytime running lights
- Fog lights with static cornering lights
- Package: Driver Assistance Package 2
- Radio: Digital radio reception DAB+
- Rain sensor
- Tire pressure warning
- Side protection strips in vehicle color
- Seat belts: Three-point seat belts in all seats
- Seats: 8 seats in fabric, Harlequin Black
- Solar Protect thermal insulation glazing
- Sunshades in the 2nd row of seats
- Traction Control (TC) Plus
- Exterior door handles, in car color
- Central locking with remote control

Extra equipment

- Detachable trailer hitch
- Package: Innovation Package (Head-Up Display - Park Pilot, front and rear - 180° panoramic reversing camera - Blind Spot Warning - Multimedia Navi Pro with 7" touchscreen, voice control, Bluetooth, hands-free system, USB, Apple CarPlay, Android Auto, OpelConnect)
- Steering wheel: Multifunction leather steering wheel, flattened at the bottom
- Dividing grid
- winter tires
- Xenon headlights with LED daytime running lights

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Seat - rear	Back seat (3 Sitzreihe Verstellungsgriff) - Damaged - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
4	Steering system	Steering column (Lenkradschloss) - Non-operational - Perform diagnosis
5	Engine	Engine (Motor / Getriebe) - Leaking - Perform diagnosis
6	2nd wheel set	1 tyre - Does not meet the leasing specifications - Replace
7	Engine	Engine cover - Damage caused by marten / rodent - Replace
8	Seat - front	Seat cover - right side - Damaged - Loss in value
9	Seat - front	Seat cover - left side - Holes - Loss in value
10	Side panel - rear right side	Sill - Dent / paintcoat damage - Smart repair
11	Cab	Insulation lining - Damage caused by marten / rodent - Replace
12	Rear bumper	Rear bumper - Scratch(es) - Paint
13	2nd wheel set	3 alloy rims - Scratch(es) - Replace

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratched - No deduction
2	Trim / covers	Boot lining - Scratched - No deduction
3	Boot lid / rear door	Boot lid - Scratch(es) - No deduction
4	Sliding door - left side	Sliding door with glass panel - Scratch(es) - No deduction
5	Door - front left side	Door - Scratch(es) - No deduction
6	Mudguard - left side	Mudguard - left side - Stone chips - No deduction
7	Bonnet	Bonnet - Stone chips - No deduction
8	Roof	Roof - dent(s) - No deduction
9	Front bumper	Front bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 3 May 2023	1.895,12 €

Repainting

No.	Repainting
1	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear right side	149 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view




Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Documents




Figure 18: Documents




Figure 19: Documents




Figure 20: Documents



Figure 21: Documents



Figure 22: Additional tyres



Figure 23: Navigation



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.



Figure 42: Misc.



Figure 43: Misc.



Figure 44: Misc.



Figure 45: Misc.



Figure 46: Misc.



Figure 47: Misc.



Figure 48: Misc.



Damage 1: Seat - rear: Back seat (3 Sitzreihe Verstellungsgriff) - Damaged - Replace



Damage 1: Seat - rear: Back seat (3 Sitzreihe Verstellungsgriff) - Damaged - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace




Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 5: Engine: Engine (Motor / Getriebe) - Leaking - Perform diagnosis



Damage 5: Engine: Engine (Motor / Getriebe) - Leaking - Perform diagnosis



Damage 5: Engine: Engine (Motor / Getriebe) - Leaking - Perform diagnosis



Damage 5: Engine: Engine (Motor / Getriebe) - Leaking - Perform diagnosis




Damage 6: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 6: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 7: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 8: Seat - front: Seat cover - right side - Damaged - Loss in value



Damage 8: Seat - front: Seat cover - right side - Damaged - Loss in value



Damage 9: Seat - front: Seat cover - left side - Holes - Loss in value




Damage 9: Seat - front: Seat cover - left side - Holes - Loss in value



Damage 10: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 10: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 10: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 11: Cab: Insulation lining - Damage caused by marten / rodent - Replace



Damage 11: Cab: Insulation lining - Damage caused by marten / rodent - Replace



Damage 11: Cab: Insulation lining - Damage caused by marten / rodent - Replace




Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: 2nd wheel set: 3 alloy rims - Scratch(es) - Replace



Damage 13: 2nd wheel set: 3 alloy rims - Scratch(es) - Replace



Damage 13: 2nd wheel set: 3 alloy rims - Scratch(es) - Replace



Damage 13: 2nd wheel set: 3 alloy rims - Scratch(es) - Replace




Damage 13: 2nd wheel set: 3 alloy rims - Scratch(es) - Replace



Damage 13: 2nd wheel set: 3 alloy rims - Scratch(es) - Replace




Wear and tear 3: Boot lid / rear door: Boot lid - Scratch(es) - No deduction



Wear and tear 3: Boot lid / rear door: Boot lid - Scratch(es) - No deduction



Wear and tear 4: Sliding door - left side: Sliding door with glass panel - Scratch(es) - No deduction



Wear and tear 4: Sliding door - left side: Sliding door with glass panel - Scratch(es) - No deduction



Wear and tear 4: Sliding door - left side: Sliding door with glass panel - Scratch(es) - No deduction



Wear and tear 4: Sliding door - left side: Sliding door with glass panel - Scratch(es) - No deduction



Wear and tear 4: Sliding door - left side: Sliding door with glass panel - Scratch(es) - No deduction



Wear and tear 5: Door - front left side: Door - Scratch(es) - No deduction



Wear and tear 5: Door - front left side: Door - Scratch(es) - No deduction



Wear and tear 9: Front bumper: Front bumper - Scratch(es) - No deduction



Wear and tear 9: Front bumper: Front bumper - Scratch(es) - No deduction



Wear and tear 9: Front bumper: Front bumper - Scratch(es) - No deduction



Wear and tear 9: Front bumper: Front bumper - Scratch(es) - No deduction



Wear and tear 9: Front bumper: Front bumper - Scratch(es) - No deduction



Repainting 1: Side panel - rear right side