TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48456432
Order No. / Reference: 27211120
Inspection date: 2 Nov 2026

Manufacturer: Opel	Model: Combo Cargo 1.5 D EHZ Selection
VIN: W0VEFYHT2NJ588330	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Combo Cargo 1.5 D EHZ Selection	
Vehicle Identification number	W0VEFYHT2NJ588330
Mileage (Read)	63,326 km
First registration	5 Apr 2022
Number of holders	1
Next periodical technical inspection	04/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	75 kW
Gearbox / Number of gears	Manual / 5
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Jade Weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Grey
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	27,120 km
Last service on / at	11/2025 at 50,463 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ646772
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1844 / AIQ 01112		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,345 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/65 R15 95H	Summer tyres on Steel	Michelin	5mm / 5mm
2)	195/65 R15 95H	Summer tyres on Steel	Michelin	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Driver's side airbag
- Automatic dipped headlights
- Exterior mirrors, electrically adjustable, heated and manually folding
- Hill Start Assist
- On-board computer
- Tachometer
- Third brake light
- Electric front windows
- Rear wing doors, asymmetrically split, sheet metal, 180° opening angle
- Headrests (2), front, height adjustable
- Steering wheel: Comfort steering wheel (PU), flattened at the bottom
- Radio BT with Graphic Info Display
- Wheels: Steel wheels 6.5 J x 16
- Side protection strips
- Seats: Single passenger seat, fixed
- 12-volt power outlet in the center console
- Traction control with engine and brake intervention (TC Plus)
- Immobiliser
- Central locking with remote control
- ABS including brake assist and adaptive brake light
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Exterior mirror housings in black
- Battery discharge protection
- Floor covering: Cargo area floor, painted
- Diesel particulate filter, maintenance-free
- Three-point seat belts in all seats
- Electronic Stability Program (ESP Plus)
- Transmission: 5-speed transmission
- Heating and ventilation system with particle and odor filter, front
- Paint finish: Solid color paint
- Steering column, adjustable for reach and height
- Upholstery: Cloth
- Wheels: Tire repair kit
- Side impact protection
- Speed-sensitive power steering
- Seats: Driver's seat manually adjustable in 4 positions
- Daytime running light
- Partition wall, closed
- Lashing eyes (6) in the cargo area
- Heat-insulating glazing, tinted
- Central locking: Ignition keys (2), one of which is foldable

Extra equipment

- Driver and passenger side airbags
- Tailgate, glazed (with rear window wiper and rear window heater - 2 folding ignition keys)
- Package: Cool & Sound 1 (Multimedia Radio (Bluetooth, Hands-free system, USB, Smartphone integration, 8" touchscreen color display, Cruise control, Steering wheel remote control) - Air conditioning, front)
- Seats: Driver's seat adjustable in 6 ways: length, height and backrest angle (with lumbar support and armrest)
- FlexCargo partition wall with window (with pass-through function below the passenger double seat including protective bag for the load - interior rearview mirror, manually dimmable)
- Electric windows, front, with one-touch function and anti-pinch protection (as well as comfort closing function via remote control of the central locking system - electrically adjustable, heated and folding exterior mirrors)
- Rear parking pilot
- Seats: Double passenger seat (seatbelt warning, single passenger seat - electric parking brake - storage compartment on the backrest of the middle seat of the double passenger seat)
- Doors: Sliding door, passenger side with fixed window
- Würth expansion

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door (Griffmulde) - Scratched - Smart repair
2	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
3	Trim / covers	Door trim - front right side - Scratched - Loss in value
4	Wing mirror - right side	Wing mirror (Glas ganz) - Damaged - Replace
5	Door - rear right side	Door - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Interior	Cargo space partition (Regaleinbauten) - Differs from the original configuration - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No.	Accident
1	Rear, Side - left

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.




Figure 37: Misc.



Damage 1: Door - front left side: Door (Griffmulde) - Scratched - Smart repair



Damage 1: Door - front left side: Door (Griffmulde) - Scratched - Smart repair



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 3: Trim / covers: Door trim - front right side - Scratched - Loss in value



Damage 3: Trim / covers: Door trim - front right side - Scratched - Loss in value



Damage 3: Trim / covers: Door trim - front right side - Scratched - Loss in value




Damage 4: Wing mirror - right side: Wing mirror (Glas ganz) - Damaged - Replace



Damage 4: Wing mirror - right side: Wing mirror (Glas ganz) - Damaged - Replace



Damage 4: Wing mirror - right side: Wing mirror (Glas ganz) - Damaged - Replace



Damage 4: Wing mirror - right side: Wing mirror (Glas ganz) - Damaged - Replace



Damage 5: Door - rear right side: Door - Scratched - Paint



Damage 5: Door - rear right side: Door - Scratched - Paint



Damage 5: Door - rear right side: Door - Scratched - Paint



Damage 5: Door - rear right side: Door - Scratched - Paint



Damage 5: Door - rear right side: Door - Scratched - Paint



Damage 5: Door - rear right side: Door - Scratched - Paint



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula



Accident 1: Rear, Side - left