TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48016354
Order No. / Reference: 26986007
Inspection date: 8 Oct 2026

Manufacturer: Volkswagen	Model: Golf Variant 2.0 TDI SCR DSG R-Line
VIN: WVWZZZCD0RW808407	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Golf Variant 2.0 TDI SCR DSG R-Line	
Vehicle Identification number	WVWZZZCD0RW808407
Mileage (Read)	113,635 km
First registration	13 Oct 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	MONDSTEINGRAU
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Anthracite-Black
Vehicle with smoke odor	no
readiness to drive	Not roadworthy / moveable

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	3,600 km
Last service on / at	01/2026 at 89,832 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV404838
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	With complaint
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	0603 / CNN 02101		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,060 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 91W	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	225/45 R17 91W	Summer tyres on Light alloy	Nexen	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Michelin	7mm / 7mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Fulda	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger (with passenger airbag deactivation)
- Ambient lighting 30-color (LED light in the front footwell, light color selectable)
- Electrically adjustable and heated exterior mirrors with memory function and passenger-side mirror lowering function.
- Car2X (Using the WLANp ITS G5 standard, all Car2X-enabled vehicles and traffic systems such as traffic lights can transmit data at high speed without using the mobile network. This works over a distance of around 800 meters - enough to warn of an invisible traffic jam.)
- Parking aid (acoustic warning signals for obstacles in the front and rear area)
- Electronic parking brake including auto-hold function
- Automatic headlight control, with LED daytime running lights (as well as welcome and farewell lights)
- Driving profile selection (possibility to set different vehicle settings: Comfort, Normal, Sport, Eco, Individual - adaptable vehicle systems include: engine, adaptive chassis control DCC, DSG, steering, start-stop system, cornering lights and "Dynamic Light Assist", automatic distance control ACC, air conditioning)
- Pedestrian protection measures expanded
- Speed limiter (in conjunction with online services)
- Rear window heated
- Rear window wiper with intermittent function
- ISOFIX mounting points (for child seats on the outer rear seats and on the front passenger seat, i-Size compatible)
- Rear headrests (3)
- Paint finish: Solid
- LED taillights
- Steering wheel: Multifunction sports steering wheel in leather, with touch controls and paddle shifters
- Non-smoking version (storage compartment and 12V socket at the front)
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection (detects critical distance situations to other vehicles and helps to shorten the stopping distance - warns the driver visually and audibly in dangerous situations as well as with a preventive braking jolt with pedestrian and cyclist detection - also reacts to pedestrians and cyclists)
- Brushed stainless steel pedals
- Radio "Composition" (touchscreen with 21 cm screen diagonal - 4+1 speakers - output power 4 x 20 watts - FM radio reception - dual tuner with phase diversity for the best possible radio reception - Radio Data System (RDS) - MP3 playback - USB-C interface with Apple compatibility - DAB+ digital radio reception - telephone interface (hands-free system, Bluetooth audio))
- Wheels: Tire Mobility Set (12-volt compressor and tire sealant)
- Rear bench seat undivided, backrest asymmetrically split and foldable with center armrest
- Airbag: Head airbag system for front and rear passengers including front side airbags
- App-Connect (selected apps for Android smartphones and Apple iPhones can be displayed and operated on the touchscreen of the radio or navigation system)
- Exterior mirror housings and door handles in body color
- third brake light
- black roof rails
- Decorative inlays "Carbon Grey" (for instrument panel and front door panels)
- Diesel particulate filter and SCR catalyst
- Digital Cockpit Pro, multicolor (various info profiles selectable)
- Electronic differential lock XDS
- Electronic stability program and electromechanical brake booster (Anti-lock braking system with brake assist - Electronic brake force distribution - Traction control - Electronic differential lock - Engine drag torque control - Trailer stabilization)
- Chassis: Sport chassis
- Electric windows, front and rear
- Windscreen made of laminated safety glass, heat and sound insulating
- luggage compartment cover
- Transmission: 7-speed DSG (7-speed dual-clutch transmission DSG)
- Rear spoiler in car color
- "Climatronic" air conditioning system (with active combination filter)
- Front headrests (safety-optimized)
- LED reading lights at the front (2) and 2 at the rear
- LED headlights
- Dynamic headlight range control
- Fatigue detection (detects signs of possible driver fatigue based on characteristic steering behavior, time of day and driving duration and issues a visual and audible warning)
- Emergency call service (no registration required, service is activated upon delivery)
- Package: Seating comfort package (2 USB-C ports in the front, 2 USB-C charging ports on the rear center console; charging power up to 45 W - front center armrest adjustable in height and length - front seats with height adjustment)
- Progressive steering (the steering ratio is progressively increased with increasing steering angle - the steering behavior becomes noticeably more direct depending on the driving situation, the steering wheel movements are significantly reduced and thus steering comfort is increased)
- Tire pressure monitoring system (passive)
- Wheels: Alloy wheels (4) "Valencia" 7.5 J x 17 in grey metallic (with tires 225/45 R17 - wheel locks with enhanced theft protection)
- Keyless start system without safe locking
- Seat belts: Three-point automatic seat belt for the middle rear seat
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner

- Seat belts: Three-point automatic seat belts for the outer rear seats
- Seat covers in "R-Line" fabric (center panels of the front seats and outer rear seats in "R-Line" fabric, inner side panels in "ArtVelours")
- Lane keeping assistant “Lane Assist”
- 12-volt power outlet in the luggage compartment
- Telephone interface with inductive charging function
- Ambient lighting with logo projection
- Green thermal insulation glazing, sides and rear
- Seats: Lumbar support in the front
- Seats: Top sports seats in the front (height adjustable)
- Start-stop system (with brake energy recuperation)
- Bumpers in body color
- Textile floor mats front and rear
- Electronic immobilizer
- Central locking without safe locking, with remote control and 2 remote folding keys

Extra equipment

- Package: Comfort Package (electrically adjustable, folding, and heated exterior mirrors with memory function and passenger-side mirror lowering - anti-theft alarm system with interior monitoring, backup horn, and tow-away protection - "Park Assist" parking assistant including parking aid - proactive occupant protection system in conjunction with Front Assist and Side Assist - Keyless Access keyless locking and starting system with safe locking - side airbags for the outer rear seats, including front side airbags and head airbag system)
- Package: Winter "Premium" (DSG) (R-Line) in conjunction with Top Package (Air Care Climatronic air conditioning with active combination filter, rear controls and 3-zone temperature control - multifunction leather sports steering wheel, heated, with shift paddles - automatically heated front windshield washer nozzles - auxiliary heating and ventilation with remote control and timer - heated front seats and outer rear seats)
- Lane change assistant "Side Assist"
- Mesh partition
- Package: Top Package (2 LED reading lights front, 2 rear, Dynamic High Beam Control, Dynamic Light Assist, Automatically dimming interior mirror, IQ.LIGHT - LED matrix headlights with LED daytime running lights, cornering lights and dynamic turn signals, Air Care Climatronic air conditioning with 3-zone temperature control, allergen filter and rear controls, LED taillights with dynamic turn signals, Dynamic headlight range control with dynamic cornering lights, Multifunction camera, Panoramic tilt/slide sunroof, Rain sensor, Bad weather lights and cornering lights)
- Paint finish: Special color Moonstone Grey
- Park Assist system including parking aid

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed, problem has been detected This is due to the following reason.: Fehler Antriebstrang
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Mirror housing - Broken / torn - Replace
2	Door - front left side	Door - dent(s) - Smart repair
3	Side panel - rear right side	Side panel - dent(s) - Smart repair
4	Front bumper	Front bumper - Scratch(es) - Smart repair
5	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
6	Rear bumper	Spoiler - Scratch(es) - Loss in value
7	Instrument panel	Indicator light (Start- Stopp Fehler) - Electrical fault - Perform diagnosis
8	Body	Underbody panelling - Broken / torn - Replace
9	Front bumper	Spoiler - Scratched - Replace
10	Instrument panel	Indicator light (Fehler Antriebsystem) - Electrical fault - Perform diagnosis
11	Mudguard - left side	Mudguard - left side - dent(s) - Paint
12	Rear bumper	Rear bumper - Scratch(es) - Paint
13	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Paint

Wear and tear

No.	Component group	Description
1	Body	Body - Scratch(es) - No deduction
2	Door - front right side	Door handle - outside - Scratch(es) - No deduction
3	Side panel - rear left side	Sill - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 16 Jan 2026	771,31 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Der beiliegende Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster




Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Additional tyres



Figure 14: Additional tyres



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.





Figure 29: Misc.




Damage 1: Wing mirror - right side: Mirror housing - Broken / torn - Replace




Damage 1: Wing mirror - right side: Mirror housing - Broken / torn - Replace



Damage 2: Door - front left side: Door - dent(s) - Smart repair




Damage 2: Door - front left side: Door - dent(s) - Smart repair



Damage 3: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 3: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 5: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 5: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 6: Rear bumper: Spoiler - Scratch(es) - Loss in value




Damage 6: Rear bumper: Spoiler - Scratch(es) - Loss in value



Damage 6: Rear bumper: Spoiler - Scratch(es) - Loss in value




Damage 7: Instrument panel: Indicator light (Start- Stopp Fehler) - Electrical fault - Perform diagnosis



Damage 8: Body: Underbody panelling - Broken / torn - Replace



Damage 8: Body: Underbody panelling - Broken / torn - Replace




Damage 9: Front bumper: Spoiler - Scratched - Replace



Damage 9: Front bumper: Spoiler - Scratched - Replace



Damage 10: Instrument panel: Indicator light (Fehler Antriebsystem) - Electrical fault - Perform diagnosis



Damage 11: Mudguard - left side: Mudguard - left side - dent(s) - Paint




Damage 11: Mudguard - left side: Mudguard - left side - dent(s) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Paint



Damage 13: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Paint



Damage 13: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Paint



Damage 13: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Paint