TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48616330
Order No. / Reference: 27266107
Inspection date: 5 Nov 2026

Manufacturer: Mercedes-Benz	Model: 311 CDI Sprinter Kompakt HA
VIN: W1V9076311P214756	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz 311 CDI Sprinter Kompakt HA	
Vehicle Identification number	W1V9076311P214756
Mileage (Read)	103,981 km
First registration	3 Feb 2020
Number of holders	1
Next periodical technical inspection	04/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	2,143 ccm / 4
Power	84 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Iridiumsilber metallic
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	597 Tag(e)
Key is / should be	4 / 4	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FS118326
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	2222 / ARJ 02665		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	
Dimensions	5267 x 2020 x 2332		

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 121R	Winter tyres on Steel	Continental	6mm / 6mm
2)	235/65 R16 121R	Winter tyres on Steel	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	235/65 R16 121R C	All-season tyres on Steel	Continental	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ADAPTIVE ESP (latest generation) with load- and speed-dependent driving dynamics control
- Outdoor temperature display
- third brake light
- Diesel particulate filter and SCR
- Driving light assistant
- Transmission: 6-speed manual
- Instrument panel and combination instrument with various storage options
- Communication module (LTE) for digital services
- Headlight range control
- Center section with 2-DIN storage compartments and air vents
- Sliding door on the right side
- Power steering
- Seats: Driver's seat adjustable
- continuous partition wall
- Lashing eyes
- ASSYST maintenance interval indicator
- Central locking with radio remote control
- Driver's side airbag
- Exterior mirrors, manually adjustable (2)
- Battery: fleece battery 1x 12 V / 70 Ah
- Brake lights, adaptive
- Tachometer
- Electric window regulator for driver and passenger door
- Seatbelt warning device for driver's seat
- KEYLESS start
- Child safety locks on doors in the passenger compartment
- Headrests (2), front
- Mercedes-Benz emergency call system
- Upholstery: Cloth
- Wheels: Steel rims 6.5 J x 16
- Crosswind Assist
- Seats: Passenger seat
- Daytime running light
- Doors: Rear doors, double-wing doors opening 180 degrees, available in two height versions
- Immobiliser

Extra equipment

- Acoustic package
- Tempmatic controlled air conditioning
- MBUX multimedia system with 7-inch touchscreen (High-resolution 7-inch touchscreen (960 x 540 pixels), AM/FM radio with dual tuner, Bluetooth connectivity with audio streaming and hands-free function, smartphone integration via Android Auto or Apple CarPlay, multimedia connection unit for connecting portable devices via a USB-C interface, 4 x 25 W output power, sound adjustment, separate volume control for audio and telephone, 2-way front speakers)
- Spare wheel
- Key: Multi-button radio remote control
- Seats: Comfort driver's seat
- Seat heating on driver's side
- Entrance rear door
- Paint finish: Metallic
- Navigation (linguatronic voice control, Wi-Fi hotspot, multimedia connection unit for connecting portable devices via an additional USB-C interface, center fill speaker for improved sound and voice output, improved hands-free function, dual-phone operation, digital operating instructions)
- Package: Parking package with reversing camera
- Package: SMOKER
- Tires: All-season tires
- Spare wheel carrier with jack (under frame end)
- Keys: 2 additional master keys
- Seats: Lumbar support for driver's seat
- Hot water auxiliary heater (5 kW)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Fuel system	Tank flap - Glued / labelled - De-glue / neutralise
2	Rear of vehicle	Foot plate - Deformed - Loss in value
3	Body	B-pillar - right side - Dent / paintcoat damage - Repair and paint
4	Bonnet	Bonnet - Stone chips - Paint
5	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
6	Sliding door, right	Sliding door - Unprofessionally repaired - Repair and paint
7	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
8	Front bumper	Front bumper (unpainted) - Broken / torn - Replace
9	Body	Body - Damage by hail - repair according to calculation

Wear and tear

No.	Component group	Description
1	Body	Partition wall - Scratch(es) - No deduction
2	Boot lid / rear door	Rear door - right side (Innen) - Dent / paintcoat damage - No deduction
3	Boot lid / rear door	Rear door - left side (Innen) - Dent / paintcoat damage - No deduction
4	Interior	Cargo area floor - Scratch(es) - No deduction
5	Door - front left side	Door - Dent / paintcoat damage - No deduction
6	2nd wheel set	Steel rim set - complete - Corrosion - No deduction
7	Interior	Cargo space partition (Bott Regalsystem) - Differs from the original configuration - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Side panel - rear left side, Door - rear right side

Paint coat thickness measurement

Side panel - rear left side	417 µm	Door - rear right side	400 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Comments

- Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Documents



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.





Figure 32: Misc.



Damage 1: Fuel system: Tank flap - Glued / labelled - De-glue / neutralise



Damage 1: Fuel system: Tank flap - Glued / labelled - De-glue / neutralise




Damage 2: Rear of vehicle: Foot plate - Deformed - Loss in value



Damage 2: Rear of vehicle: Foot plate - Deformed - Loss in value



Damage 2: Rear of vehicle: Foot plate - Deformed - Loss in value



Damage 3: Body: B-pillar - right side - Dent / paintcoat damage - Repair and paint



Damage 3: Body: B-pillar - right side - Dent / paintcoat damage - Repair and paint




Damage 3: Body: B-pillar - right side - Dent / paintcoat damage - Repair and paint



Damage 3: Body: B-pillar - right side - Dent / paintcoat damage - Repair and paint



Damage 3: Body: B-pillar - right side - Dent / paintcoat damage - Repair and paint



Damage 4: Bonnet: Bonnet - Stone chips - Paint




Damage 4: Bonnet: Bonnet - Stone chips - Paint



Damage 4: Bonnet: Bonnet - Stone chips - Paint



Damage 4: Bonnet: Bonnet - Stone chips - Paint




Damage 4: Bonnet: Bonnet - Stone chips - Paint



Damage 4: Bonnet: Bonnet - Stone chips - Paint



Damage 4: Bonnet: Bonnet - Stone chips - Paint



Damage 4: Bonnet: Bonnet - Stone chips - Paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 6: Sliding door, right: Sliding door - Unprofessionally repaired - Repair and paint



Damage 6: Sliding door, right: Sliding door - Unprofessionally repaired - Repair and paint



Damage 6: Sliding door, right: Sliding door - Unprofessionally repaired - Repair and paint



Damage 6: Sliding door, right: Sliding door - Unprofessionally repaired - Repair and paint



Damage 7: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 7: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 7: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 8: Front bumper: Front bumper (unpainted) - Broken / torn - Replace



Damage 8: Front bumper: Front bumper (unpainted) - Broken / torn - Replace



Damage 9: Body: Body - Damage by hail - repair according to calculation



Damage 9: Body: Body - Damage by hail - repair according to calculation



Damage 9: Body: Body - Damage by hail - repair according to calculation



Damage 9: Body: Body - Damage by hail - repair according to calculation




Damage 9: Body: Body - Damage by hail - repair according to calculation



Damage 9: Body: Body - Damage by hail - repair according to calculation



Damage 9: Body: Body - Damage by hail - repair according to calculation



Damage 9: Body: Body - Damage by hail - repair according to calculation



Damage 9: Body: Body - Damage by hail - repair according to calculation



Damage 9: Body: Body - Damage by hail - repair according to calculation



Damage 9: Body: Body - Damage by hail - repair according to calculation



Damage 9: Body: Body - Damage by hail - repair according to calculation



Damage 9: Body: Body - Damage by hail - repair according to calculation



Damage 9: Body: Body - Damage by hail - repair according to calculation



Wear and tear 1: Body: Partition wall - Scratch(es) - No deduction



Wear and tear 2: Boot lid / rear door: Rear door - right side (Innen) - Dent / paintcoat damage - No deduction



Wear and tear 3: Boot lid / rear door: Rear door - left side (Innen) - Dent / paintcoat damage - No deduction



Wear and tear 4: Interior: Cargo area floor - Scratch(es) - No deduction



Wear and tear 5: Door - front left side: Door - Dent / paintcoat damage - No deduction



Wear and tear 5: Door - front left side: Door - Dent / paintcoat damage - No deduction



Wear and tear 5: Door - front left side: Door - Dent / paintcoat damage - No deduction



Wear and tear 5: Door - front left side: Door - Dent / paintcoat damage - No deduction



Wear and tear 5: Door - front left side: Door - Dent / paintcoat damage - No deduction



Wear and tear 5: Door - front left side: Door - Dent / paintcoat damage - No deduction



Wear and tear 6: 2nd wheel set: Steel rim set - complete - Corrosion - No deduction



Wear and tear 6: 2nd wheel set: Steel rim set - complete - Corrosion - No deduction



Wear and tear 6: 2nd wheel set: Steel rim set - complete - Corrosion - No deduction



Wear and tear 6: 2nd wheel set: Steel rim set - complete - Corrosion - No deduction




Wear and tear 6: 2nd wheel set: Steel rim set - complete - Corrosion - No deduction



Repainting 1: Side panel - rear left side, Door - rear right side



Repainting 1: Side panel - rear left side, Door - rear right side



Repainting 1: Side panel - rear left side, Door - rear right side



Repainting 1: Side panel - rear left side, Door - rear right side