TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48423165
Order No. / Reference: 27215072
Inspection date: 28 Oct 2026

Manufacturer: Ford	Model: Puma 1.5 EcoBlue ST-LINE VIGNALE
VIN: WF02XXERK2NY59971	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Puma 1.5 EcoBlue ST-LINE VIGNALE	
Vehicle Identification number	WF02XXERK2NY59971
Mileage (Read)	152,345 km
First registration	17 Mar 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	88 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Frozen White
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Black
readiness to drive	Not roadworthy / moveable

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	95 %
Last service on / at	09/2025 at 121,500 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GH425737
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	With complaint
readiness to drive	Not roadworthy / moveable		
Roadworthiness	not roadworthy/operational		
Manufacturer key number/ type code number	8566 / BUA 00041		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,840 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R18 96W	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	215/50 R18 96W	Summer tyres on Light alloy	Continental	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Ambient lighting (front including front door storage, footwell and cup holder lighting with LED technology)
- Dashboard in leather look
- Passenger airbag deactivation
- Tires: 7 J x 18 light alloy wheels (4) in 5-spoke design, black, diamond-turned (with 215/50 R 18 tires)
- Hill start assist
- Brake Assist (EBA)
- third brake light
- Fabric headliner
- Diesel particulate filter
- Tachometer
- Electronic Stability Program (ESP) (with Traction Control System (TCS))
- Chassis: Sport-tuned chassis
- Electric front and rear windows (with quick-down function including all-around closing function)
- High Beam Assist
- Ford EcoCoach (shows the efficiency of current driving behavior)
- Ford Key Free System (keyless locking/unlocking)
- Ford MegaBox
- FordPower start function (keyless start)
- Luggage compartment lighting
- Cruise control system (Intelligent speed limiter with speed limit display)
- Illuminated glove compartment
- Rear window wiper/washer system
- Intelligent Protection System (IPS) (front airbag for driver and front passenger - front and rear head and shoulder airbags - side airbag for driver and front passenger - seat belt tensioners and force limiters for front and outer rear seats - seat belt warning system for front and second-row seats)
- LED taillights
- LED headlights for low and high beam (with LED turn signals at the front)
- Steering column, adjustable in height and reach
- MyKey key system (individually programmable second key)
- Fatigue warning
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Package: Comfort (Air conditioning with automatic temperature control, activated carbon filter - Windscreen wipers with rain sensor (sensitivity adjustable) - Interior mirror, automatically dimming - Inductive charging station for mobile devices (according to Qi standard, compatibility depends on the device))
- Front and rear parking pilot system
- Pollen and dust filter
- Post-Collision Assist
- Pre-Collision Assist (including Forward Alert system with pedestrian and bicycle detection)
- Anti-lock braking system (ABS) (with electronic brake force distribution (EBD))
- Electrically adjustable, heated and folding exterior mirrors (painted in body color - with integrated turn signals and ambient lighting)
- Tires: Tire repair kit (maximum speed 80 km/h when used)
- Body styling kit (side skirts painted in body color, with black high-gloss insert - front and rear bumpers, ST-Line design)
- Large roof spoiler (painted in car color)
- 12.3-inch digital instrument panel
- Door sill trims, ST-Line design
- Driver information system with on-board computer
- Lane keeping assist including lane keeping assist
- Wrong-way driver warning function (traffic signs, e.g. no-overtaking zones or speed limits, are detected via the front camera and displayed on the on-board computer.)
- Ford Easy Fuel (Ford Easy Fuel comfort refueling system (Eliminates the need for a separate internal fuel cap and prevents misfueling by detecting the size difference between petrol and diesel nozzles. The filler neck only opens when the correct fuel is used.)
- FordPass Connect (including eCall, live traffic information and Wi-Fi hotspot)
- Transmission: 6-speed manual transmission
- Grab handles for driver and passenger side
- Heated rear window
- Interior lighting front and rear with LED technology (map reading lights at the front)
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Rear headrests (3) height adjustable
- Front headrests are height-adjustable
- Paint finish: Solid color, special color
- LED fog lights (including static cornering lights)
- Steering wheel: ST-Line steering wheel, 3-spoke design, in Sensico synthetic leather
- Front center console with integrated armrest (2 cup holders - 12-volt socket)
- Ford navigation system including Ford SYNC 3 with AppLink and 8" touchscreen (Android Auto and Apple CarPlay support - DAB/DAB+ digital radio reception (Digital Audio Broadcasting) - 6 speakers - steering wheel controls - Bluetooth hands-free system and audio streaming - 2 USB ports - voice control for audio and telephone - SMS text-to-speech function - road map for Europe - Ford navigation system includes advanced voice control and voice output, detailed visualization (3D display), One Box Search)
- Upholstery: Premium Sensico upholstery in leather look in black
- Radio accessories: B&O Sound System (575 Watt premium sound system with 10 speakers, including subwoofer - based on the renowned sound and design expertise of Bang & Olufsen)
- Headlight assistant with day/night sensor

- Tire Pressure Monitoring System (TPMS)
- Headlights with LED daytime running lights and LED low beam headlights
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Power steering (electro-mechanical, speed-dependent (EPAS - Electric Power Assisted Steering))
- Seats: Driver and front passenger seats with massage function
- Seats: Rear seat backrest, foldable, 60:40 split
- Seats: Front sports seats with integrated headrests
- Sun visors including illuminated makeup mirrors, on driver and passenger side
- Carpet floor mats front and rear
- Door handles painted in car color
- Traffic sign recognition system
- Immobiliser
- Selective driving mode switch (settings "Normal", "Eco", "Sport", "Slippery" and "Unpaved Roads" - Depending on the selected mode, various factors such as the steering, the resistance of the accelerator pedal and the iACC basic settings are affected.)
- Seats: Driver's seat height adjustable (with lumbar support)
- Seats: Front seats, individually and variably heated
- Start-stop system
- Front and rear bumpers (painted in body color, ST-Line Vignale design)
- Variable radiator air intake
- Lashing eyes in the luggage compartment
- Central locking with remote control

Extra equipment

- Package: Driver Assistance Package II (Active Parking Assist with parking and exiting function - Evasive Steering Assist - Distance Display and Distance Warning - Intelligent Adaptive Cruise Control with Traffic Sign Recognition System - Front Parking Pilot System - Pre-Collision Assist including Collision Warning System with Pedestrian and Cyclist Detection - Rear View Camera with "Split View" Technology - Blind Spot Assist with Emergency Braking Function when Reversing Out of Parking Spaces)
- Package: Winter (Heated windscreen - Heated leather steering wheel - Individually and variably heated front seats)
- Cigarette lighter and ashtray

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed, problem has been detected This is due to the following reason.: Motorschaden
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.
Roadworthy/operationally safe	Due to the damage characteristic listed under accident or value-reducing factors, the vehicle was not roadworthy or safe to operate at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Interior	Boot cover / roller cover - Damaged - Replace
2	Side panel - rear left side	Wheel well extension - Scratch(es) - Paint
3	Boot lid / rear door	Boot lid - Scratch(es) - Paint
4	Rear bumper	Rear bumper - Scratch(es) - Paint
5	Vehicle glazing	Windscreen - Broken / torn - Replace
6	Engine	Engine (Schleifen, quietschen, überhitzt) - Defective - repair according to calculation

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No.	Accident
1	Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.



Damage 1: Interior: Boot cover / roller cover - Damaged - Replace



Damage 1: Interior: Boot cover / roller cover - Damaged - Replace



Damage 1: Interior: Boot cover / roller cover - Damaged - Replace



Damage 2: Side panel - rear left side: Wheel well extension - Scratch(es) - Paint



Damage 2: Side panel - rear left side: Wheel well extension - Scratch(es) - Paint



Damage 3: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 3: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 5: Vehicle glazing: Windscreen - Broken / torn - Replace




Damage 5: Vehicle glazing: Windscreen - Broken / torn - Replace




Damage 6: Engine: Engine (Schleifen, quietschen, überhitzt) - Defective - repair according to calculation




Damage 6: Engine: Engine (Schleifen, quietschen, überhitzt) - Defective - repair according to calculation



Damage 6: Engine: Engine (Schleifen, quietschen, überhitzt) - Defective - repair according to calculation



Damage 6: Engine: Engine (Schleifen, quietschen, überhitzt) - Defective - repair according to calculation



Damage 6: Engine: Engine (Schleifen, quietschen, überhitzt) - Defective - repair according to calculation



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right