MACADAM








Skoda Octavia (UKL): 2BMR581

Vinnumber:	**TMBJW7NX5NY050273**	Versionname:	**Octavia Combi Clever 1.4TSi iV 204pk/cv 5p DSG6**
First Registrationdate:	**17/01/2022**	Fiscalpower:	
Expertise Mileage:	**80861**	Power Kw:	**110**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**over 2300 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/45/18/95 Y**			
	Fr.L.	**Continental: 4 mm**	Fr.R.	**Continental: 4 mm**
	Re.L.	**Pirelli: 3 mm**	Re.R.	**Pirelli: 3 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**225/45 R 18 95 Y**
Tyre size FR	**225/45 R 18 95 Y**
Tyre size RL	**225/45 R 18 91 Y**
Tyre size RR	**225/45 R 18 91 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**264**
Tyre make RR	**264**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**2**		
Number of charging cables (rapid charge)	**1**		

MOT certificate, Missing, Replace



Roof liner, Scratch(es), Acceptable





Backrest cover FL, Damaged, Acceptable




Seat cover FL, Damaged, Acceptable




Bumper F, Scratch(es), Spot repair





Bumper F, Scratch(es), Acceptable




Wing FL, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable






Wing RL, Scratch(es), Acceptable




Alloy rim FL, Scratch(es), Repair and paint (complete)











Tyre FL, Tear, Acceptable





Alloy rim RL, Scratch(es), Repair and paint (complete)












Internal boot lining R, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Acceptable





Bumper R, Scratch(es), Repair and paint (complete)

















Wing RR, Dent(s), Acceptable




Door RR, Scratch(es), Acceptable










Door FR, Scratch(es), Acceptable




Alloy rim RR, Scratch(es), Acceptable







Alloy rim RR, Scratch(es), Repair and paint (complete)











Roof, Chemical polution, Acceptable




Onderhoudshistorie van: TMBJW7NX5NY050273

ALPHABET

Kenteken	2BMR581
Merk Model	Skoda Octavia Combi Clever 1.4TSi iV 204pk/cv 5p DSG6
Brandstofsoort	Benzine
Datum deel1	1/17/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/16/26	64,574	bougie	Vervangen
4/16/26	64,574	Inspectie met olieververvanging (vast in	Uitvoeren
4/16/26	64,574	klein materiaal	
4/16/26	64,574	remblokken vooraan	Vervangen
4/16/26	64,574	ruitenwisserrubber achter	Vervangen
4/16/26	64,574	ruitenwisserrubber vooraan	Vervangen
4/16/26	64,574	ruitenwisservloeistof	Bijvullen/-laden
4/16/26	64,574	versnellingsbakolie	Vervangen
10/6/25	47,905	klein materiaal	
10/6/25	47,905	koelwatervloeistof	Bijvullen/-laden
10/6/25	47,905	ruitenwisservloeistof	Bijvullen/-laden
10/6/25	47,905	Tussentijds onderhoud (vast interval)	Uitvoeren
1/13/25	32,987	Inspectie met olieververvanging (vast in	Uitvoeren
1/13/25	32,987	klein materiaal	
1/13/25	32,987	luchtfilter interieur	Vervangen
1/13/25	32,987	remvloeistof	Bijvullen/-laden
1/13/25	32,987	ruitenwisserrubber achter	Vervangen
1/13/25	32,987	ruitenwisserrubber vooraan	Vervangen
1/13/25	32,987	ruitenwisservloeistof	Bijvullen/-laden
3/16/23	10,216	klein materiaal	
3/16/23	10,216	ruitenwisservloeistof	Bijvullen/-laden
3/16/23	10,216	Tussentijds onderhoud (vast interval)	Uitvoeren
3/16/23	10,216	universele lampen	Vervangen