TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48430516
Order No. / Reference: 27198638
Inspection date: 29 Oct 2026

Manufacturer: Seat	Model: Arona 1.0 TSI OPF Xperience
VIN: VSSZZZKJZNR047266	





Vehicle details

Manufacturer / Type / Model / Equipment	
Seat Arona 1.0 TSI OPF Xperience	
Vehicle Identification number	VSSZZZKJZNR047266
Mileage (Read)	152,825 km
First registration	7 Jul 2022
Number of holders	1
Fuel type	Petrol
Engine displacement / Cylinder	999 ccm / 3
Power	70 kW
Gearbox / Number of gears	Manual / 5
Type of drive	Front drive
Type of vehicle	Car hatchback
Colour / colour code	Dark Camouflage/Midnight schwarz
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	3,400 km
Last service on / at	07/2026 at 146,069 km		
Key is / should be	1 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG161900
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	7593 / ANP 00681		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,710 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 95V	All-season tyres on Light alloy	Goodyear	5mm / 5mm
2)	205/55 R17 95V	All-season tyres on Light alloy	Goodyear	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 12V socket at the front
- Storage pocket on the back of the front seats
- Ambient lighting (two-tone) in the front doors
- Exterior mirror housings in body color
- Lighting in the storage compartment of the center console and front footwell
- On-board computer
- Black headliner
- Tachometer
- Three-point automatic seat belts, front and rear
- Electronic Stability Control (ESC)
- luggage compartment cover
- Speed limiter
- Transmission: 5-speed transmission
- LED taillights
- Rear window wiper/washer system with intermittent function
- illuminated trunk
- Radiator grille in chrome diamond design
- Steering wheel: Steering column with height and reach adjustment
- light sensor
- Air vents in the dashboard
- Fatigue detection
- Otto particulate filter
- Package: Climate Comfort Package (Heated and electrically folding exterior mirrors - Automatic coming home and leaving home function - Climatronic with electronic temperature control, separate temperature control for driver and front passenger - Automatically dimming interior mirror - Rain sensor)
- Tire pressure monitoring system
- Wheels: Tyre fit
- Front windshield wipers with intermittent function
- Electromechanical power steering
- Seats: Driver's seat with height adjustment
- Lane departure warning system
- Bumpers in body color
- Ultrasonic rear parking aid
- Electronic immobilizer
- thermal insulation glazing
- Storage compartment in the front doors
- Airbags
- Electrically adjustable exterior mirrors
- Outdoor temperature display
- Hill Start Assist (HHC)
- Turn signals in the wing mirrors
- Chrome trim on the side windows
- Roof rails and design element in the C-pillar in chrome colors
- Third brake light integrated into the rear spoiler
- Electric window regulator with anti-pinch protection and one-touch function
- Cruise control
- Cup holders, 2 front
- Heated rear window with timer function
- ISOFIX child seat restraint system
- Child safety locks on the rear doors
- Height-adjustable headrests, front and rear
- Paint finish: Vehicle roof painted in Midnight Black Metallic, Magnetic Grey Metallic or White
- Steering wheel: Multifunction steering wheel in nappa leather
- Multi-collision brake
- Emergency call service
- Package: Storage package (front center armrest - storage compartment under the passenger seat - owner's manual holder under the driver's seat - lashing eyes in the luggage compartment)
- Pollen filter
- Upholstery: Cloth
- Radio: Digital radio reception DAB+
- Wheels: 4 alloy wheels "Dynamic 20/1" (6.5J x 17", tires 205/55 R 17)
- Keyless locking and starting system "Kessy"
- Seats: Passenger seat with height adjustment
- Seats: Rear seat backrest split 1/3 to 2/3, foldable
- Start-stop technology
- Door handles in car color
- Front Assist area monitoring system with City Emergency Braking function and pedestrian detection
- Central locking with remote control and comfort closing

Extra equipment

- Deletion of the colored air vents in the dashboard (air vents in neutral, unlit grey)
- Package: Winter (passenger seat with height adjustment - heated front seats)
- Paint finish: Metallic with vehicle roof in a different color
- Navigation: Navigation data for Europe including MAPCARE (on SD card) for navigation systems
- Package: Xperience Pro (9.2" media system with navigation system and Full Link (Android Auto and Apple CarPlay including Full Link Wireless) - full LED headlights - wireless charger)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Wheel arch - Scratch(es) - Replace
2	Sill - right side	Trim - Scratched - Replace
3	Boot lid / rear door	Boot lid (Teillackierung) - Corrosion - Paint
4	Rear bumper	Rear bumper - Scratch(es) - Paint
5	Door - front left side	Door - Scratch(es) - Paint
6	Side panel - rear right side	Side panel - Dent / paintcoat damage - Paint
7	Door - rear left side	Door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Side panel - rear left side	Side panel - dent(s) - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Rear bumper	Spoiler - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Vehicle key

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 27 Mar 2023	1.246,31 €
2	Front, Provided by user / customer, from 23 Jan 2024	1.365,42 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Damage 1: Side panel - rear right side: Wheel arch - Scratch(es) - Replace



Damage 1: Side panel - rear right side: Wheel arch - Scratch(es) - Replace



Damage 1: Side panel - rear right side: Wheel arch - Scratch(es) - Replace




Damage 2: Sill - right side: Trim - Scratched - Replace



Damage 2: Sill - right side: Trim - Scratched - Replace



Damage 2: Sill - right side: Trim - Scratched - Replace



Damage 2: Sill - right side: Trim - Scratched - Replace




Damage 3: Boot lid / rear door: Boot lid (Teillackierung) - Corrosion - Paint



Damage 3: Boot lid / rear door: Boot lid (Teillackierung) - Corrosion - Paint



Damage 3: Boot lid / rear door: Boot lid (Teillackierung) - Corrosion - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 5: Door - front left side: Door - Scratch(es) - Paint



Damage 5: Door - front left side: Door - Scratch(es) - Paint




Damage 6: Side panel - rear right side: Side panel - Dent / paintcoat damage - Paint




Damage 6: Side panel - rear right side: Side panel - Dent / paintcoat damage - Paint



Damage 6: Side panel - rear right side: Side panel - Dent / paintcoat damage - Paint



Damage 7: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




Damage 7: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 7: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 7: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 7: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Missing part 1: Equipment: Vehicle key - Missing - Replace