MACADAM









HYUNDAI TUCSON: GJ-615-LB

Vinnumber:	**TMAJE811BNJ109318**	Versionname:	**HYUNDAI TUCSON 1.6 HYBRID 230 EXECUTIVE VP [5P] bva 6-230CH-10cv (SUV)**
First Registrationdate:	**15/09/2022**	Fiscalpower:	
Expertise Mileage:	**171788**	Power Kw:	**169**
Bodytype:	**SUV**	Body colour	**Black**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Beige**
Fueltype:	**Hybrid**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Seats electric F L	
GPS big screen color		Seats electric F R	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Steering wheel leather		Headlights Xenon/LED/Laser	
Type of climate control	**Autom climate control**	Front parking sensors	
		Rear parking sensors	
		Rear view camera	
		Seat cover lining	**Lining Leather**

Tyres

Summer tyres:	**235/50/19/103 V**			
	Fr.L.	**Michelin: 40%**	Fr.R.	**Michelin: 45%**
	Re.L.	**Michelin: 50%**	Re.R.	**Michelin: 60%**

Tyre profile depth FL	**5.5**
Tyre profile depth FR	**5.3**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.2**
Tyre size FL	**235/50 R 19 103 V**
Tyre size FR	**235/50 R 19 103 V**
Tyre size RL	**235/50 R 19 103 V**
Tyre size RR	**235/50 R 19 103 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Jack	**Yes**

Bonnet, Dent(s), Repair and paint (complete)




Door FR, Scratch(es), Paint




Door RR, Scratch(es), Acceptable




Tailgate / Boot, Dent(s), Repair and paint (complete)




ALPHABET

Historique Maintenance

Immatriculation: **GJ-615-LB** Date de 1ère immatriculation: **15/09/2022**

Modèle: **Hyundai TUCSON 1.6 HYBRID 230 EXECUTIVE VP [5P] bva 6-230CH-10cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
31/08/2026	160.433	BORDEAUX SUD AUTOMOBILES	LIQUIDE DE FREIN
			Huile
			Main D'œuvre
			Pieces
			Main D'œuvre
			Pieces
			Main D'œuvre
			Pieces
			Main D'œuvre
			Pieces
			BALAIS ESSUIE GLACE AV AR
			REVISION ET CLIM
			DISQUES PLAQUETTES AV RPLT
04/06/2026	151.993	BORDEAUX SUD AUTOMOBILES	BOUGIES ALLUMAGE RPLT
			FERMETURE DOSSIER TECH ADO
11/03/2026	140.472	BORDEAUX SUD AUTOMOBILES	REVISION
			REFUS
06/11/2025	122.302	BORDEAUX SUD AUTOMOBILES	REVISION ET CLIM
			FILTRE A AIR RPLT
			LIQUIDE DE FREIN
10/06/2025	106.099	BORDEAUX SUD AUTOMOBILES	BALAIS ESSUIE GLACE AV AR
			PLAQUETTES AR RPLT
			PLAQUETTES AV RPLT
			REVISION
18/12/2024	89.093	AUTO PORT	REVISION ET CLIM
			LIQUIDE DE FREIN
14/08/2024	74.989	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
23/07/2024	72.514	BORDEAUX SUD AUTOMOBILES	REVISION
25/03/2024	58.449	BORDEAUX SUD AUTOMOBILES	BALAIS ESSUIE GLACE AV AR
			LIQUIDE DE FREIN
			REVISION ET CLIM
03/11/2023	44.890	BORDEAUX SUD AUTOMOBILES	FILTRE A AIR RPLT

Historique Maintenance

Immatriculation: **GJ-615-LB** Date de 1ère immatriculation: **15/09/2022**

Modèle: **Hyundai TUCSON 1.6 HYBRID 230 EXECUTIVE VP [5P] bva 6-230CH-10cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
			REVISION
29/06/2023	30.524	GCA LAVAL	REVISION ET CLIM
			LIQUIDE DE FREIN
06/06/2023	28.944	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
24/02/2023	16.093	GCA LAVAL	REVISION
02/12/2022	4.694	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS HIVER